Complainant submitted an SSO Report Form for **1306 Barton Lane, Paragould** (**AR0033766, 28-00470**) on **7/7/2023**. They stated they've had some overflow issues in the bathroom of their residence, and a backup in their backyard. They stated they contacted their landlord and a plumber was dispatched twice. Plumber stated they believed the issue was with the main sewer line.

On **7/11/2023**, DEQ contacted the main office of Paragould Light and Water. Facility stated that no issues had been reported to them for that address. A work order was created by the facility and they were to go out to check on the status of the overflow and address it as necessary. DEQ requested a follow-up after the SSO inspection was complete.

William with Paragould Light and Water (870-476-5466) called back with a follow-up on **7/11/2023**. He stated that there was a misunderstanding between the resident and plumber, and that the issue was with the customer's line, not the City's. This issue would then be the responsibility of the resident to repair.

ID:	00a658ce-2b4a-43b8-a98b-e3cc5226d2ce	
-----	--------------------------------------	--

Facility									
C NPID: AR0033766 Paragould Light an	d Water Comm		AFIN:	28-0047	0	ľ			
Facility Addr: 401 GRANT LANE, , PARAGOULD, A	L	40							
SSO									
Date Received: 7/7/2023 V Started: 6/29/	1023 ~ Time: 7:30 pm	Volume: 0			Receiving	Waters:	EIGHT MIL	E CREEK	
ocation Stopped:	V Time:	Stream:							
Overflow Type									
a provide the second	Main Line Overflow	ift Station Ov	erflow						
		and bedrefort of							
Cause] I & I - Rainfall _ Construction _ Debris _		ipment Failur		wer Failu	ure 🔲	Line Failu	re Break [] Vandalis	m
] I & I - Rainfall Construction Debris C Measures Taken	Grease CRoots CEqu	ipment Failur	e 🗌 Po						
] I & I - Rainfall Construction Debris Measures Taken	Grease CRoots CEqu	ipment Failur	e 🗌 Po						
] I & I - Rainfall 🔲 Construction 📄 Debris 📄	Grease CRoots CEqu	ipment Failur	e 🗌 Po						
] I & I - Rainfall Construction Debris Measures Taken Machine Rodded Hand Rodded Hydro Cle Environmental Damage	Grease Roots Equ	ipment Failur I Lime o 🗌 U	e 🗌 Po Jsed Gene	erator [⊇ Disinfe	cted and			
] I & I - Rainfall Construction Debris Measures Taken Machine Rodded Hand Rodded Hydro Cle Environmental Damage OEHC - Observed or Evidence of Human Contact	Grease Roots Equ aned Jet-Vac Spreac	ipment Failur I Lime o 🗌 U of Adverse Hi	e 🗌 Po Jsed Gene	erator [⊇ Disinfe	cted and			
I & I - Rainfall Construction Debris Measures Taken Machine Rodded Hand Rodded Hydro Cle Environmental Damage OEHC - Observed or Evidence of Human Contact OEEI - Observed or Evidence of Environmental In	Grease Roots Equ aned Jet-Vac Spreac	ipment Failur I Lime o 🗌 U of Adverse Hi	e 🗌 Po Jsed Gene	erator [☑ Disinfe	cted and	Deoderized		
I & I - Rainfall Construction Debris Measures Taken Machine Rodded Hand Rodded Hydro Cle Environmental Damage OEHC - Observed or Evidence of Human Contact OEEI - Observed or Evidence of Environmental In Caller Info	Grease Roots Equ aned Jet-Vac Spread NEAH - No Evidence pact EFK - Evidence of Fi s: I have contacted my land	ipment Failur d Lime o 🗌 U of Adverse H sh Kill dlord plumper	e Po Jsed Geno ealth Env came tw	erator [ironmen'	☑ Disinfe	cted and	Deoderized		
I & I - Rainfall Construction Debris Measures Taken Machine Rodded Hand Rodded Hydro Cle Environmental Damage OEHC - Observed or Evidence of Human Contact OEEI - Observed or Evidence of Environmental In Caller Info	Grease Roots Equ aned Jet-Vac Spread NEAH - No Evidence pact EFK - Evidence of Fi s: I have contacted my land stated it was the main se bathroom overflowing, ho	ipment Failur d Lime o 🗌 U of Adverse H sh Kill dlord plumper wer line. It h ole in the bac	e Po Jsed Geno ealth Env came two as my ma	erator E ironmen' ice and in	Disinfe	cted and ct eceiver Ir Ltr/Tabul	Deoderized nfo ar Report Re	Public	Notific
I & I - Rainfall Construction Debris Measures Taken Machine Rodded Hand Rodded Hydro Cle Environmental Damage OEHC - Observed or Evidence of Human Contact OEEI - Observed or Evidence of Environmental In Caller Info	Grease Roots Equ aned Jet-Vac Spread NEAH - No Evidence pact EFK - Evidence of Fi s: I have contacted my land stated it was the main se	ipment Failur d Lime o 🗌 U of Adverse H sh Kill dlord plumper wer line. It h ole in the bac	e Po Jsed Geno ealth Env came two as my ma	erator E ironmen' ice and in	Disinfe	cted and ct eceiver Ir Ltr/Tabul	Deoderized	Public	Notific