

Non- Compliance Report.

The Stuttgart Waterworks failed it's permit limit for Chlorine res. due to a failure in the Sulphur Dioxide filtering system. Corrective action has been taken and Vacuum regulator has been repaired.