

The Fecal coliform Permit limit was exceeded due to the injector supply line failure. This problem has been repaired and is back on line.