

From: [Gilliam, Allen](#)
To: tpurifoy@hmmusa.com; erowlett@hmmusa.com
Cc: [Walker, Brent](#); [Burrow, Kealey](#); [Peltier, Hannah](#); [Shafii, Mo](#); jshempert.waterdept@yahoo.com; [Healey, Richard](#)
Subject: AR0021971_Hino Motors ARP001025 bypass or spill from Pretreatment containment area_20150826
Date: Wednesday, August 26, 2015 3:00:26 PM

Tommie or Ed,

There was a report of a large spill outside the containment area of Hino's Pretreatment facility on or around 6/13/15. The report indicated frac tanks were moved onto the scene to supply containment of the spill preventing it from entering your stormwater pond.

If this report is correct, please provide this office the details on what exactly caused this spill, how it was contained and what corrective actions Hino will take to ensure this will not happen again within 10 working days of the date on this email.

Bypass of pretreatment is prohibited under 40 CFR 403.17(d).

Thank you in advance for a quick response.

Sincerely,

Allen Gilliam
ADEQ State Pretreatment Coordinator
501.682.0625

ec: Richard Healey, NPDES Enforcement Branch Manager
Jim Shempert, City of Marion Utilities Manager

E/NPDES/NPDES/Pretreatment/Reports