



Each of these locations were monitored for Benzene, VOC, and H₂S at the beginning of the day time work shift 4/6/2013. All readings were Non Detect.