| ≎EPA   |   |                 |   |           | Form Approved<br>OMB No. 2040-0003        |  |  |  |  |
|--|---|-----------------|---|-----------|---|--|--|--|--|
| UNITED STATES ENVIRONM   |   | AGENCY          |   |           |   |  |  |  |  |
| NPDES Compliance   | n, D.C. 20460<br>Pe Insnec  | tion            | Renort  |           |   |  |  |  |  |
| Section A: National Data System Coding   |   |                 |   |           |   |  |  |  |  |
| Transaction Code         NPDES         Yr/Mo/Day         Inspector         Fac. Type   |   |                 |   |           |   |  |  |  |  |
| $1 \boxed{\mathbf{N}} 2 \boxed{5} 3 \boxed{\mathbf{A}} \boxed{\mathbf{R}} 0 \boxed{0} 2 \boxed{2} 1$   | <b>87</b> 11  | 12 0<br>Remarks | <b>7 1 2 1 3</b> 17                                   | 118<br>18 | $\mathbf{I} \qquad 19  \mathbf{S}  20  2$ |  |  |  |  |
| 0 4 C  |   | kemarks         |   |           |   |  |  |  |  |
| Inspection Work Days Facility Evaluation F<br>67 69 70 N   | Rating 1<br>71  | BI<br>N 72      | QA<br>N 73 74 75                                      | R         | eserved 80                                |  |  |  |  |
| Section B: Facility Data   |   |                 |   |           |   |  |  |  |  |
| Name and Location of Facility Inspected (For industrial users disa<br>include POTW name and NPDES permit number)<br>Bright Harvest Sweet Potato Co.                                      | Entry Time/Date<br>0855 / December 13, 2007   |                 | Permit Effective Date<br>na                           |           |   |  |  |  |  |
| 509 Taylor Road, Clarksville, AR 72830<br>POTW – Clarksville Light & Water – AR0022187   |   |                 | Exit Time/Date<br>0925 / December 13, 2007            |           | Permit Expiration Date<br>na              |  |  |  |  |
| Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s)Other Facility DataMr. Jeff Hannon, Manager of QA & Compliance / 479-754-6313 phone / 479 754-7794 faxAFIN 36-00153 |   |                 |   |           |   |  |  |  |  |
| Name, Address of Responsible Official/Title/Phone and Fax Num<br>Mr. Jeff Hannon, Manager of QA & Compliance / 479-754-63<br>Po Box 528<br>Clarksville, AR 72830                         |   |                 |   |           |   |  |  |  |  |
|  | Yes ♥ No ↓<br>Section C: Areas Evaluated During Inspection<br>(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated) |                 |   |           |   |  |  |  |  |
| N Permit N Flow Measureme  | ent   | N OI            | perations & Maintenance                               | Ν         | Sampling                                  |  |  |  |  |
| N Records/Reports N Self-Monitoring  | Program   | N Sh            | udge Handling/Disposal                                | Ν         | Pollution Prevention                      |  |  |  |  |
| N Facility Site Review N Compliance Sche   | edules  | Y Pr            | retreatment   | Ν         | Multimedia                                |  |  |  |  |
| N Effluent/Receiving Waters N Laboratory   |   |                 | orm Water   |           | Other:                                    |  |  |  |  |
| Section D: Summary   | of Findings/Com   | ments (At       | ttach additional sheets if necessary                  | y)        |   |  |  |  |  |
| This inspection revealed that Clarksville Light & Water is repermits and program documents of the pretreatment program   |   |                 |   |           |   |  |  |  |  |
|  |   | nvironmen       | /Fax<br>ntal Quality-Jasper<br>) /FAX# (870) 446-2181 |           | Date January 16, 2008                     |  |  |  |  |
|  |   |                 |   |           |   |  |  |  |  |
| Signature of Reviewer  | Agency/Office/  | Phone and       | d Fax Numbers   |           | Date                                      |  |  |  |  |

## **POTW Pretreatment Program**

## Industrial Site Visit

Name of Industry: Bright Harvest Sweet Potato Co.

Industry Contacts: Mr. Jeff Hannon, Manager of QA & Compliance

Type of Industry: Sweet potato processing

| Date of Visit: December 13, 2007                             |                  |                  |              |
|--|------------------|------------------|--------------|
| 1. Significant industrial user <u>X</u><br>Determined        | Yes              | No               | Not          |
| 2. Pretreatment equipment or procedur                        | res? <u>X</u> Ye | es <u>No</u>     | N/A          |
| <b>3. Pretreatment equipment maintained and operational?</b> | <u>X</u> Y       | es <u>No</u>     | N/A          |
| 4. Hazardous waste generated or stored                       | ?Yes             | No               | <u>X</u> N/A |
| 5. Proper solid waste disposal?                              | <u>X</u> Y       | es <u>No</u>     | N/A          |
| 6. Solvent management/TTO control?                           | Yes              | No               | <u>X N/A</u> |
| 7. Suitable sampling location?                               | <u>X</u> Y       | es <u>No</u>     | N/A          |
| 8. Appropriate self-monitoring procedures / equipment?       | <u>X</u> Ye      | es <u>No</u>     | N/A          |
| 9. Adequate spill prevention?                                | <u>X</u> Y       | es <u>No</u>     | N/A          |
| 10. Industry familiar with limits and requirements           | <u>X</u> Y       | es <u>No</u>     | N/A          |
| Additional Comments: None                                    |                  |                  |              |
| Visit Conducted By: <u>Bruce Kirkpatrick</u>                 | Da               | te: <u>Janua</u> | nry 16, 2008 |