\$EPA

Form Approved OMB No. 2040-0003

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Washington, D.C. 20460										
NPDES Compliance Inspection Report										
Section A: National Data System Coding										
•										
1	Transaction Code									
1	A F I N 0	8	- 0 0 0	3 4	Remark	cs				
L	Inspection Work Days		Facility Evaluation R	atino	BI	(QA		Reserved	
67 69 70 N 71 N 73 74 75									80	
Section B: Facility Data										
Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number) City of Berryville 1000 W. Cedarvale						Entry Time/Date 1420 / January 30, 2009		Permit Effective Date December 01, 2007		
Berryville, Arkansas							Exit Time/Date 1510 / January 30, 2009		Permit Expiration Date November 30, 2012	
									ler Facility Data cility: 36 21' 25.95", -93 34' 43.51"	
Name, Address of Responsible Official/Title/Phone and Fax Number Kirby Murray, Public Works Director City of Berryville P.O. Box 227 Berryville, Arkansas 72616 870-423-4074, 870-423-4501 (fax)							Contacted Yes No No			
Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)										
N	Permit	N	Flow Measurement			Operations & Maintenance			Sampling	
N	Records/Reports	N Self-Monitoring Program		rogram	N	Slu	Sludge Handling/Disposal		Pollution Prevention	
N	Facility Site Review	N	Compliance Schedules		N	Pretreatment		N	Multimedia	
N	Effluent/Receiving Waters	N	Laboratory	N Stor			rm Water	N	Other:	
	Section D: Summary of Findings/Comments (Attach additional sheets if necessary)									
A reconnaissance level inspection was performed on January 30, 2009, to assess the impacts of a large ice storm which struck the area three days prior. Mr. Darrell Backs, Chief Operator, stated that the facility lost power at about 1200 hrs on the 27th. The facility generator powered up and ran for 14 hours until the windings burned up at about 0200 hrs on the 28th. Mr. Backs used tablet chlorination at the Parshall Flume to disinfect the wastewater since the UV unit was not in operation. He monitored the residual Chlorine at the Outfall 001 monitoring point every hour. Plant records showed a residual Chlorine of 0.05 ppm to 0.20 ppm during the times when the plant was without power. Mr. Backs stated that flow was minimum during the time the plant was without power. Power was restored at 1924 hrs on the 28th. Mr. Kirby Murray, Public Works Director, stated that no overflows occurred in the collection system. He stated that power was lost to the Industrial Park Lift Station. Wastewater was trucked from this lift station to the wastewater plant for about 48 hours on the 27th and 28th. Mr. Backs stated that all the information above was telephoned to Ms. Cindy Garner, ADEQ Water Division Enforcement Branch Manager.										
	ne(s) and Signature(s) of Inspector(s		Agency/Office/Telephone/Fax AR Dept. of Environmental Quality- Jasper					Date		
Bruce Kirkpatrick Clace Refriend				870-446-6170; 870-4476-2181 (fax)					July 20, 2009	
Signature of Reviewer				Agency/Office/Phone and Fax Numbers					Date	

Two photos of Outfall 001



