

November 5, 2009

Honorable Larry Mitchell ATTN Mgr. W&WW Dept. 1019 S.W. 2nd Street Bryant, AR 72022

AFIN: 63-00065



NPDES Permit No.: AR0034002

Dear Mayor Mitchell:

On October 28, 2009, Eric Fleming and I performed a reconnaissance inspection of the your waste water treatment facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. This inspection was performed in response to a complaint alleging that there was a strong Hydrogen Sulfide odor possibly coming from the facility. The inspection was requested by the Deputy Director of ADEQ, Ryan Benefield. At this time, the complaint was not found to be valid. But, the inspection revealed the following violations:

- There was not enough freeboard in the polishing pond. This is a violation of Part II.10 of the permit which requires 2 feet of freeboard. A trench had been cut in the polishing pond to avoid an overflow but there was still less than a foot of freeboard. This is an unpermitted discharge and is a violation of the Arkansas Water and Air Pollution Control Act (§8-4-217(b)(1)(E)).
- 2. There was not enough freeboard in the sludge wasting pond. There was less than 6 inches of freeboard available for the pond. This is a violation of Part II.10 of the permit which requires 2 feet of freeboard.
- 3. The ponds contained no staff gauges for measuring the freeboard levels.

The above items require your immediate attention. Please submit a written response to these findings to Cindy Garner, Water Division Enforcement Branch Manager. This response should be mailed to the address below. This response should contain documentation describing the course of action taken to correct each item noted. This corrective action should be completed as soon as possible, and the written response with all necessary documentations (i.e. photos) is due by November 15, 2009.

If I can be any assistance, please contact me at keller@adeq.state.ar.us or 501-682-0658.

Sincerely,

Jan

Dawn Keller Inspection Branch Manager Water Division

cc: Water Division Enforcement Branch Water Division Permits Branch

≎EPA												Form Approved OMB No. 2040-0003										
		UNIT	ED ST	ATES E					TECTI(ON AGE	NCY											
	NPDES	5 (Cor	np		0	n, D.C. e]		pe	ctio	n]	Rer	or	t								
				1						onal D												
	Transaction Code			N	PDE	ES							Yr/	/Mo/I	Day			In	spec. 7	Type Inspector Fac	c. Type	
1	N 2 5 3 A R	0	0	3	4	0	0	2	11		0	9 1 0 2 8 17 18						18	R 19 S 20 1			
	A F I N 6	3	-	0	0	0	6	5		Rema	rks S	А	L	Ι	N	E		С	0	U N T Y		
	Inspection Work Days]	Facilit	ty Eva	luat	tion F	Rating	;		BI		QA							Reserved			
67 69 70 N 71 N 72 N 73 74 75														8	0							
Section B: Facility Data																						
										y Tim p.m.			2009			Per	mit Effective Date					
City of Bryant										F						02/	01/2009					
1019 Southwest 2 nd StreetExit Time/DatePermit Expiration DateBryant, AR 720222:40 p.m. on 10/28/200901/31/2014																						
	ne(s) of On-Site Representative(s)/Ti gg Asher/ Chief Plant Operator/50								ıx									Ot	her Fa	cility Data		
Hor Bry	ne, Address of Responsible Official/ norable Larry Mitchell/ Mayor/ 10 ant, AR 72022/ -847-8083 office/ 501-847-2583 fax						ber								tacted							
501	-047-0005 0HIC/ 501-047-2505 IAX												Yes		No	√						
			(S = S	atisf					E valua 1, U = 1						uated)		-			
Ν	Permit	S	Flo	w Me	asu	reme	nt			U	OF	perations & Maintenance						Ν	N Sampling			
Ν	Records/Reports	Ν	Self	f-Mor	nitor	ring l	Program N Slu				dge Handling/Disposal						Ν	N Pollution Prevention				
U	Facility Site Review	Ν	Сол	mplia	nce	Sche	dules	6		Ν	Pr	etreatment N						Ν	Multimedia			
S	Effluent/Receiving Waters	Ν		oorate	•					Ν		orm W						Ν	Other.			
	Section D: Summary of Findings/Comments (Attach additional sheets if necessary) 1. There was not enough freeboard in the polishing pond. This is a violation of Part II.10 of the permit which requires 2 feet of freeboard. A trench had been cut in the polishing pond to avoid an overflow but there was still less than a foot of freeboard. This is an unpermitted discharge and is a violation of the Arkansas Water and Air Pollution Control Act (§8- 4-217(b)(1)(E)). 2. There was not enough freeboard in the sludge wasting pond. There was less than 6 inches of freeboard available for the																					
	pond. This is a violation	on of	f Pai	rt II.1	0	of th	në p	ermi	t wh	nich r	equi	res 2	fee	t of				163 (, ne			
	3. The ponds contained no		f ga	uges	s fo	or m							/els.						-			
	ne(s) and Signature(s) of Inspector(s	, 								e/Telep e Rock		Fax -682-0658 / 501-682-0910						Date 10/30/2009				
Dav							1															
Sig	nature of Reviewer						Aş	gency/	Offic	e/Phor	ne and	l Fax N	lumbe	ers					Da	te		

ADEQ Water NPDES Inspection	AFIN: 63-00065	Permit #: AR0034002

	W	ater Div	ision No D	ischarge Industrial Photogra	aphic Evidence	Sheet		
	City of	Bryant, I	Bryant, AR					
Photographer:	Daw	n Keller		Witness:	Eric Fleming			
Photo #	1	Of	4		Date:	10/28/2009	Time:	2:11 p.m.
Description:		Front vie freeboard	ew of the tre d.	ench that was cut in the Polish	ing Pond to prev	vent an overflow of	the pond. The	ere is not enough
Photographer:		Dawn Ko	allar	Brederic Same	Witness:	Eric Fleming		
Photo #	2	Of Of	4		Date:	10/28/2009	Time:	2:12 p.m.
Description:				ch cut in the Polishing Pond s				2.12 p.m.

AD	EQ Wa	ter NPD	ES Inspectior	AFIN: 63-00065		Permit #: AR003	4002	
Location:	Cit	y of Br	yant, Bryant	, AR				
Photographer:			Keller		Witness:	Eric Fleming		
Photo #	3	0	f 4		Date:	10/28/2009	Time:	2:12 p.m.
Description:		Back	side of the t	rench that was cut to prevent of	overflow of the Po	olishing Pond.		
Photographer: Photo #	4	Of	Keller 4		Witness: Date:	Eric Fleming 10/28/2009	Time:	2:15 p.m.
Description:		Sludge	e Wasting Po	ond with less than 6 inches of	freeboard.			



November 16, 2009

Arkansas Department of Environmental Quality 5301 Northshore Dr. North Little Rock, AR 72118-5317 Attn. Cindy Garner, Enforcement Branch Manager

RE: NPDES PERMIT NO: AR0034002

Bryant, City of 200 SW 3rd St. Bryant, AR 72022 Gregg Asher

「はたいたい」とないというないという

This is a letter in response to an inspection of our facility on October 28, 2009 by Dawn Keller and Eric Fleming. It was reported to me that the violations revealed in this inspection were a permit violation and required our immediate attention.

- 1. Due to the record amount of rainfall we have received this year it has been a struggle to maintain the freeboard in our storage lagoons. We were able to maintain the required 24 inches until the month of June. Since we have received over 30 inches of rainfall and have not been able to treat the extra surface water that had accumulated in these lagoons.
- 2. Due to the above mentioned issue on the 22nd of October we cut a trench in the levee to prevent water from overflowing this lagoon. As in the past we reported this release as an SSO, to your office and included it in our monthly report. We now have been informed that this type of release will be reported as a by-pass and a letter has been sent to the enforcement section addressing this incident.
- 3. It has never been brought to my attention in previous inspections that these storage lagoons needed a staff gauge to measure the freeboard levels. We now have installed the gauges and the photos included are showing that the required 24 inches of freeboard have been achieved in all storage lagoons.

I do appreciate the assistance your office has provided us on this matter. If you have any questions regarding these issues please contact me at (501) 847-8083.

Sincerely Gregg Ashe


Wastewater Superintendant

Cc: Larry Mitchell Richard Penn Monty Ledbetter Larry Gaddis Image of Staff Gauge in the Equalization Basin The large marks indicate 6" with the top of the gauge representing the height of the levee.



Image of Staff Gauge in the Polishing Lagoon The large marks indicate 6" with the top of the gauge representing the height of the levee.









Arkansas Dept. of Environmental Quality Attn. Enforcement Section 5301 Northshore Drive North Little Rock, AR 72118-5317

Hustaldan Burlla takin Burlla attan Burn Halaft