≎EPA

Signature of Reviewer

Form Approved OMB No. 2040-0003

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Washington, D.C. 20460									
NPDES Compliance Inspection Report									
Section A: National Data System Coding									
Transaction Code									
L	A F I N 0 :	5	- 0 0 0	5 4	Remar	ks			
	Inspection Work Days 67 69	I	Facility Evaluation R	ating I	BI N	72	QA 73 74 75		Reserved
Section B: Facility Data									
inclu	e and Location of Facility Inspected de POTW name and NPDES permit of Harrison Wastewater 7	per)	harging to POTW, also		•	Entry Time/Date 1202 / January 19, 2011		Permit Effective Date October 1, 2007	
1508	Silver Valley Road	, T18N, R20W in Bo	oone County			Exit Time/Date 1355 / January 19, 2011		Permit Expiration Date September 30, 2012	
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Mr. Rick Maples / Pretreatment Coordinator / Phone 870-741-2528 Other Facility Data									
Mr. I City P.O.	e, Address of Responsible Official/ Mike Crow / Interim Wastewater of Harrison Box 1715 ison, AR 72602					Contacted Yes			
Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)									
S	Permit	Y.			U	Operations & Maintenance N			Sampling
N	Records/Reports	N	Self-Monitoring Program N		N	Sludge Handling/Disposal		N	Pollution Prevention
S	Facility Site Review	N	Compliance Scheo	dules	N Pret		etreatment		Multimedia
S	Effluent/Receiving Waters	N	Laboratory				orm Water		Other:
Section D: Summary of Findings/Comments (Attach additional sheets if necessary)									
A reconnaissance level inspection was performed on 1/19/2011 in response to a 1/18/2011 report by the City informing the Department that one of the facility's two clarifiers was out of service and would be so for approximately one month. It was reported that the facility would be able to meet all effluent limitations unless heavy rainfall resulted in high inflow to the plant. This inspection revealed that at the time of inspection the facility was producing what appeared to be a high quality effluent. No visual adverse impacts were observed at the WHI0066 ADEQ Ambient Monitoring Site which is just down stream of Outfall 001. The violation of by-passing this treatment was previously reported by the permittee. No letter will be sent to the facility.									
	e(s) and Signature(s) of Inspector(s	e Kirkpatrick	Agency/Office/Telephone/Fax AR Dept. of Environmental Quality-Jasper PHONE# (870) 446-6170 / FAX# (870) 446-2181					Date 1-24-2011	

Agency/Office/Phone and Fax Numbers

Date

Photo of Parshall flume showing effluent that appeared to be of good quality on 1-19-2011



Photo of North Clarifier which was not in service at time of inspection due to motor failure

