



<h1 style="margin:0;">ADEQ</h1> <p style="margin:0; font-weight: normal;">A R K A N S A S Department of Environmental Quality</p>	WATER DIVISION INSPECTION REPORT				
	AFIN: 47-00544	PERMIT #: AR0022560	DATE: 8/27/2015		
	COUNTY: 47 Mississippi	PDS #: 087293	MEDIA: WN		
	GPS LAT: 35.928786 LONG: -89.777200 LOCATION: Entrance				
FACILITY INFORMATION		INSPECTION INFORMATION			
NAME: Precoat Metals LOCATION: 5888 County Road East 180 - IU of Blytheville CITY: Blytheville		FACILITY TYPE: 2 - Industrial INSPECTOR ID#: 52138 S - State FACILITY EVALUATION RATING: N INSPECTION TYPE: Industrial User			
RESPONSIBLE OFFICIAL		DATE(S): 8/27/2015 ENTRY TIME: 13:50 EXIT TIME: 14:30 PERMIT EFFECTIVE DATE: PERMIT EXPIRATION DATE:			
NAME / TITLE: Richard Dzurney / Plant Manager COMPANY: Precoat Metals MAILING ADDRESS: 5888 County Road East 180 CITY, STATE, ZIP: Blytheville AR 72315 PHONE & EXT. / FAX: / EMAIL:		INSPECTION PARTICIPANTS			
CONTACTED DURING INSPECTION: No		NAME/TITLE/PHONE/FAX/EMAIL/ETC.: Will Rogers/Environmental Health and Safety			
AREA EVALUATIONS					
(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)					
S	PERMIT	N	FLOW MEASUREMENT	N	STORMWATER
N	RECORDS/REPORTS	N	LABORATORY	N	FACILITY SITE REVIEW
S	OPERATION & MAINTENANCE	N	EFFLUENT/RECEIVING WATER	N	SELF-MONITORING PROGRAM
S	SAMPLING	N	SLUDGE HANDLING/DISPOSAL	S	PRETREATMENT
N	OTHER:				
SUMMARY OF FINDINGS					
<p>No significant pretreatment concerns were noted at the time of the inspection. Facility familiar with pretreatment requirements. Clarifier was not operating efficiently at the time of inspection and may need repair/replacement.</p> <p>Facility is an IU of the City of Blytheville</p>					
GENERAL COMMENTS					
None					
INSPECTOR'S SIGNATURE:  Brent L. Walker				DATE: 10/16/2015	
SUPERVISOR'S SIGNATURE:  Jason Bolenbaugh				DATE: 10/23/2015	

POTW Pretreatment Program

Industrial User Site Visit

Name of Industry: Precoat Metals

Industry Contacts: Will Rogers/EHS

Type of Industry: Metal Finishing

Date of Visit: 8/27/2015

1.	Significant industrial user?	<u> X </u>	Yes	<u> </u>	No	<u> </u>	N/A
2.	Pretreatment equipment or procedures?	<u> X </u>	Yes	<u> </u>	No	<u> </u>	N/A
3.	Pretreatment equipment maintained and operational?	<u> X </u>	Yes	<u> </u>	No	<u> </u>	N/A
4.	Hazardous waste generated or stored?	<u> </u>	Yes	<u> </u>	No	<u> </u>	N/A
5.	Proper solid waste disposal?	<u> X </u>	Yes	<u> </u>	No	<u> </u>	N/A
6.	Solvent management/TTO control?	<u> </u>	Yes	<u> </u>	No	<u> X </u>	N/A
7.	Suitable sampling location?	<u> X </u>	Yes	<u> </u>	No	<u> </u>	N/A
8.	Appropriate self-monitoring procedures/equipment?	<u> </u>	Yes	<u> </u>	No	<u> X </u>	N/A
9.	Adequate spill prevention?	<u> X </u>	Yes	<u> </u>	No	<u> </u>	N/A
10.	Industry familiar with limits and requirements?	<u> X </u>	Yes	<u> </u>	No	<u> </u>	N/A

Additional Comments:

Clarifier was not operating efficiently at the time of inspection and may need repair/replacement.

Visit Conducted by: Brent L Walker Brent L. Walker Date: 10/16/2015