

Blue, Karen

To: Baker, Tobin
Subject: RE: Response to February 19, 2020 Inspection

From: rhendrix@ccswda.com [<mailto:rhendrix@ccswda.com>]

Sent: Thursday, March 05, 2020 10:44 AM

To: Baker, Tobin

Cc: Krou, Christopher; Witherow, David; 'Angela Sparks'; David Passmore; Bob Blankenship; Brett Provost; 'Dan Shaw'; danny@honnoll.com; Dennis Burks; Derek McCormick; 'Garry Tate'; John Householder; Jon Milligan; Kapil Bajaj; 'Kevin Orr'; Mitchell Fitts; Rick Miles; Wayne Bond; Willis Tyler

Subject: Response to February 19, 2020 Inspection

Please find attached our response to your February inspection of the Legacy Landfill.

Also, I did receive a paper copy of your inspection in the mail.

Thank you.

Robert D. Hendrix, PE, Ex. Dir.

Craighead County Solid Waste Disposal Authority

PO Box 16777 – 238 CR 476

Jonesboro, AR 72403

Ph (870) 972-6353 ext. 5

FAX (870) 972-0495

E-mail: rhendrix@ccswda.com

Rec'd Digitally	
AFIN: <u>16-00199</u>	S W M D
PMT#: <u>0254-S1-R4</u>	
RECEIVED By Karen Blue at 12:41 pm, Mar 09, 2020	
DOC ID#: <u>77904</u>	
TO: <u>RH>FILE <KMB</u>	

Craighead County Solid Waste Disposal Authority

P.O. Box 16777 • Jonesboro, AR 72403 • 870-972-6353 • fax: 870-972-0495

March 5, 2020

Mr. Tobin Baker, ADEQ Inspector
Solid Waste Management Division
Arkansas Department of Environmental Quality
5301 North Shore Drive
North Little Rock, AR 72118-5317

Re: First Quarterly Inspection 2020; AFN16-00199; Permit Number 0254-S1-R4

Dear Mr. Baker:

I have reviewed the latest Quarterly Inspection Report dated February 19, 2020 and would like to address your comments in the following paragraphs.

Reg. 22.411 (o) Erosion or other cover defects resulting in exposed refuse.

Comments: Erosion with exposed waste observed on the west slope of Cell 3. (Refer to Photo #1.)



ADEQ Photo #1

Response: Due to extremely wet conditions our repairs were delayed; however, the erosion was repaired on February 28, 2020. (See CCSWDA Photo #1).



CCSWDA Photo #1

Reg. 22.411 (o) Erosion or other cover defects resulting in exposed refuse.

Comments: Erosion with exposed waste observed on the south slope of Cell 4 Unit 2 by 360 elevation bench road. (Refer to Photo #2.)



ADEQ Photo #1

Response: Due to extremely wet conditions our repairs were delayed; however, the erosion was repaired on February 21, 2020. (See CCSWDA Photo #2).



CCSWDA Photo #2

Mr. Baker, I sincerely appreciate you working with us and the cooperation we receive during these inspections. I can assure you and the Department that we will continue with all diligence to maintain the Legacy Landfill to the very best of our ability and in accordance with Regulation 22.

Thanks again for your understanding and consideration.

Respectfully,

Handwritten signature of Robert D. Hendrix in blue ink.

Robert D. Hendrix, PE, CFM
Executive Director

RDH:rdh

CC: CCSWDA Board; CCSWDA Staff