

**From:** Pemberton, Layne  
**To:** ["dsartain@edc-ark.com"](mailto:dsartain@edc-ark.com)  
**Subject:** AR0000752 EDCC 006- & 007 Streamflow Warning  
**Date:** Monday, January 22, 2018 10:42:00 AM  
**Importance:** High

---

David,

It has been brought to my attention that the Streamflow values for outfalls 006 & 007 are overdue for the Oct 2017 monitoring period. In the comments section of NetDMR there is a notation, "Streamflow - Downstream Monitoring is not required."

If there isn't a wavier or some sort in the permit, a violation letter will have to be issued.

Could you bring me up to speed on this?

Thank you,

Layne Pemberton  
Enforcement Analyst  
ADEQ Office of Water Quality  
Enforcement Branch  
Phone: 501-682-0664  
Fax: 501-682-0880  
[pemberton@adeq.state.ar.us](mailto:pemberton@adeq.state.ar.us)

