LOCATION	ТҮРЕ	Start Date & Time	End Date & Time	Est. Vol. in gallons	CAUSE	Environmental Impact	ACTIONS TAKEN	Discharge Location
Red Bridge Rd.	MH	10/18/16 08:00 AM	10/18/16 04:00 PM	2000	D	NEAH	EC,HC,	GR
		SUM	IMARY REPORT CODE DESC	RIPTIONS	1	1	1	
CAUSE(S) of Overflow	Overflow IMPACT		Action(s) Taken	Ultimate	Ultimate Discharge Location		Type of Overflow	
E- Equipment Failure	NEAH- No Evidence of Adverse Health		WO- Work Order	CR- Creek/Stream/River (specify) or Environmental Impact			MH- Manhole	
C- Construction	OEHC - Observed	l or Evidence of	EC- Enviromental Cleanup DI-Ditch				LS- Lift Station	
HC- Hydro cleaning	EFK- Evidence of Fish Kill		HC- Hydro Cleaned	Human Contact DR - Drop Inlet			ML- Main line	
- P - Power Failure	OEEI - Observed or Evidence of		HR- Hand Rodded	nd Rodded GR- Ground Surfac		ce	SL- Servic	
R- Rainfall			REN- Referred to Engineer	ring PA- Paved	d Area		SSO- Sanitary Se	wer
R O - Roots			PN- Public Notificatio		Cotained in Bu	ilding	Overflov BP- Bypass	
-						inding		
D- Debris			LR - Line Repair				U - Upset	
	G - Grease			I	MR- Manhole	Repair		
			LF - Line Failure / Break					
ł			RG- Roots & Grease					
							1	