



February 3, 2023

ADEQ

Attn: Ms. Leslie Allen-Daniel
Enforcement Coordinator, Office of Water Quality
5301 Northshore Drive
North Little Rock, AR 72118

Re: NPDES Permit Number AR0021806, AFIN 60-00409

Dear Ms. Daniels:

On Tuesday, January 31, 2023, the Adams Field Water Reclamation Facility was operating at peak flow conditions when it experienced a power outage from the primary electrical feed (F340 LR East) at 6:56 a.m.

Due to a diagnostic error, the automatic transfer switch did not roll power to the secondary feed (V840 LR Port). Utility staff contacted Entergy regarding the power outage on both feeds and was advised work was underway.

During this outage, connection to the decommissioned emergency power generator was reestablished and power was restored to the plant's main pump station at approximately 9:38 a.m. Influent flow was then able to be diverted from the collection system to the equalization basin for storage.

Entergy arrived on site and confirmed that power was available on the secondary electrical feed (V840 LR Port). The electrical service was manually switched over at 2:14 p.m. by utility staff and full power was restored to the facility.

Respectfully submitted,

A handwritten signature in blue ink, appearing to read "John Thompson", is written over a faint, larger version of the signature.

John Thompson
Adams Field Water Reclamation Facility Supervisor