PERMITTEE Paragou AR0033	ld Light, Water and Cable - Wastewater Treatment Plant 3766
DATE OF VIOLATION	TRC - August 4, 2015
PARAMETER VIOLATED	TRC Instantaneous Maximum
REPORTED DISCHARGE	TRC Instantaneous Maximum: 0.14 mg/L
PERMIT CONDITION	TRC Instantaneous Maximum: <0.011 mg/L*
	*TRC MDL for PLWC is 0.02 mg/L.
A description of the noncomplying discharge including its impact upon the receiving waters: TRC instantaneous value above permit limit; there were no observable impacts to the receiving stream.	
Cause of the non-compliance: The TRC violation was due to the chlorine feed rate, which was adjusted to bring the effluent back into compliance.	
Anticipated time the condition of noncompliance is expected to continue or, if it has been corrected, the duration of the period of noncompliance: At the present time, the plant is in compliance.	
PLWC is in the process of instanced for chlorine and sulfur did	inate the noncomplying discharge: alling a UV Disinfection system which will eliminate the exide. Current plans are to have the new system operational In addition, WWTP personnel will closely monitor compliant.
Steps taken to prevent recurrence of the condition of noncompliance: Operators will closely monitor chlorine levels in the post-aeration basin to ensure chlorine levels are within limits and equipment is functioning properly.	
9-8-2015 Date Signature	