



H2BBD\*



**ROGERS POLLUTION CONTROL FACILITY**


*"Serving Rogers - Protecting Our Environment"*



August 4, 2016

Allen Anderson  
NPDES Enforcement Branch  
5301 Northshore Drive  
North Little Rock, AR. 72118

Permit Number: AR0043397



Dear Mr. Anderson,

On July 28<sup>th</sup> a full ton Cl2 cylinder was added to our dual feed scaling system and our Superior auto switchover gas chlorinator was installed and tested for leaks following the appropriate SOP steps. During this process the operations staff failed to notice a lead washer wedged in the tank valve that the regulator was attached too. At approximately 3:00 pm Friday afternoon, the original tank emptied calling for feed to begin from the full tank that was waiting on standby. The equipment functioned properly, but because of the lead washer in the valve no chlorination occurred from this time until Monday morning at approximately 9:00 am. At 9:00 am the problem was discovered and corrected immediately allowing chlorination to continue.

Our SOP has been updated to include that an inspection is done on the tank valve before our regulators are attached. We will also be performing a longer test run on a new regulator hookup to make sure that our system vacuum is operating in the proper range.

Yours truly,

David Staib

RWU Operations Supervisor