

## Anderson, Alan

---

**From:** Todd Beaver <ToddBeaver@RWU.ORG>  
**Sent:** Thursday, March 01, 2018 3:56 PM  
**To:** Anderson, Alan  
**Cc:** Cary Roth; David Staib; Earl Rausch  
**Subject:** AR0043397

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

Mr. Anderson,

Thursday 3/1/18 at 10:19 AM, our effluent grab sample indicated a chlorine residual of .14 mg/L. Our discharge limit is an instantaneous .1 mg/l. We investigated and found a faulty sulfur dioxide regulator and immediately replaced the faulty equipment. We re-tested at 11:24 A.M. and found we were back to a .01 residual and back to compliance. We will report the exceedence in our DMR as the single failure value for 3/1/18.

Please accept this notice as our immediate reporting requirement. If you have further questions or comments please call or email.

Sincerely,

Todd Beaver, P.E.  
Plant Manager  
479-273-7378

