



## ROGERS POLLUTION CONTROL FACILITY

---

"Serving Rogers - Protecting Our Environment"

Wednesday, December 30, 2015

Allen,

Per our conversation this morning I am writing to let you know that we had a chlorine residual of 0.2 in a grab sample. We immediately increased our sulfur dioxide feed and the next grab sample had a residual of 0.02. Chlorine analyzer did not pick up the 0.2 reading. We inspected the analyzer and found it to be working properly however we replaced all the tubing and recalibrated the analyzer. I will report the 0.2 reading on the DNR's instead of the analyzer reading for that day.

If you need any more information regarding this event please do not hesitate to give me a call at 479-273-7378 and my extension is 307

A handwritten signature in black ink, appearing to read 'Rob Moore', is positioned above the typed name.

Robert Moore

Plant Manager