

RENE' MEINTS

REPORT OF NON-COMPLIANCE WITH EFFLUENT LIMITATIONS

PERMITEE: CLINTON, EAST 001

PERMIT: AR0048836 001

REPORTING PERIOD: FEBRUARY 2014

REPORT DATE: MARCH 2014

PARAMETER(S)	NPDES MIN	NPDES AVG	NPDES MAX	RESULT REPORTED	DATE OF EXCURSION
E. COLI #/100M			2050.00	4153.33	02/16-22/14

COMMENTS:

Upon receiving permit results from ESC. an investigation into the cause was performed. It was found that the Proportional Flow Device had went out and did not adjust the intensity of the Ultra-violet Bulbs as necessary nor did it Alarm. The exact time that this device went out is not known. The ultraviolet bulbs are energized and burning.

A technician has been notified to repair or replace the Flow Device and Alarm. New ultra violet bulbs will also be installed.

PRINCIPAL EXECUTIVE OFFICER

TITLE

DATE

Roy Keeling
CLINTON, EAST 001

MANAGER

3-20-2014

Clinton Water
PO Box 277
Clinton AR 72031



US POSTAGE
\$ 00.90
First-Class

Mailed From 72031
03/20/2014
032A 0061814271

ADEQ
Enforcement Section/Water Division
5301 Northshore Dr.
North Little Rock, AR 72118

7211835917 0015

