

Forrest City Water Utility

303 NORTH ROSSER ST.
FORREST CITY, ARKANSAS 72335
870-633-2921



April 13, 2018

ADEQ Office of Water Quality
Enforcement Branch
Phone: 501-682-0664

RE: 5-Day Written Report Requirements for SSO reported 4/10/18
Confirmation Number: 06b0ac2d-5520-42f8-baa4-070415d10dd4

1. Facility/Permittee name: City of Forrest City
2. Permit number: AR0020087
3. Location of SSO:
Scottsmeadows Subdivision, In woods approximately 300' west of 12 Birnamwood residence
4. Receiving water: A natural tributary ditch of Crow Creek
5. Total duration of overflow: 4/10/18 4:00pm - 4/11/18 12:00pm
6. Total estimated volume: >1000
7. Cause of SSO: A unearthed force main was struck by a fallen tree that caused a section of pipe to push apart at a joint, enough to allow leakage.
8. Steps taken or planned to reduce, eliminate, and prevent future SSOs:
Pipe joint was repaired. The discovery of this leak was during FCWU's routine sewer line inspection. FCWU will continue to follow the procedure of visionally inspecting the paths of its sewer lines with a goal to eliminating SSO's.
9. Contact name and phone number:
Edward Gregory Jr., PO
870-270-1756

Sincerely,
Edward Gregory Jr., PO
Forrest City Water Utility