

CONFIRMATION NUMBER

8F95DFD8-0A01-43F9-984A-9021EF2F011E

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 8F95DFD8-0A01-43F9-984A-9021EF2F011E

Date Sent: 7/2/2014

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P street

Date Overflow Began: **07/01/2014**

Time:

03:50 pm

Date Overflow Ended: **07/01/2104**

Time:

05:25 pm

Location:

3400 Coventry Lane, manhole 2004-1180 & clean out, ditch behind residence, in wooded, undeveloped area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type: **clean out**

(Enter overflow type if not listed)

Volume:

2375

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Public Land Only (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Leroy Jeremiah**

Title **Superintendent**

Telephone Number **(479) 784-2344**

Additional Comments if Needed:

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 5247B16A-4DAC-4793-AD70-3DD84356BD94

Date Sent: 7/6/2014

SSO Bypass Upset

Facility Permit Number: **AR0021750**

Facility name:

Massard WWTP

Date Overflow Began: **07/05/2014**

Time:

06:45 pm

Date Overflow Ended: **07/05/2014**

Time:

08:38 pm

Location:

7 Eastwood Dr. Basin S003. USMH 0860. DSMH 0850

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
 Lift Station Overflow
 Main Line Overflow
 Service Line Overflow
 Other Overflow Type:

(Enter overflow type if not listed)

Volume: **2825**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Public Land Only (ground)**

Cause of Overflow

- I & I - Rainfall
 Roots
 Grease
 Debris
 Equipment Failure
 Construction
 Vandalism
 Power Failure
 Line Failure/Break
 Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
 Jet-Vac Hydro Cleaned
 Hand rodded Spread Lime on Affected Area
 Used Generator To Power Pumps/Equipment Public Notification

Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
 OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number

Additional
Comments
if Needed:

CONFIRMATION NUMBER

19188D47-F847-4CAF-876F-FDA0C3D549FB

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 19188D47-F847-4CAF-876F-FDA0C3D549FB

Date Sent: 7/7/2014

SSO Bypass Upset

Facility Permit Number:	AR0021750	Facility name:	Massard WWTP
Date Overflow Began:	07/07/2014	Time:	7:50 am
Date Overflow Ended:	07/07/2014	Time:	9:20 am
Location:	#7 Eastwood Drive, Basin S003, USMH 0860, DSMH 0850.		

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume: **450**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- | | |
|--|--|
| <input type="checkbox"/> Machine rodded | <input checked="" type="checkbox"/> Disinfected and Deodorized |
| <input checked="" type="checkbox"/> Jet-Vac | <input type="checkbox"/> Hydro Cleaned |
| <input type="checkbox"/> Hand rodded | <input type="checkbox"/> Spread Lime on Affected Area |
| <input type="checkbox"/> Used Generator To Power Pumps/Equipment | <input type="checkbox"/> Public Notification |
| <input type="checkbox"/> Other: Describe | |

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Superintendent** Telephone Number **(479) 461-0914**

Additional Comments if Needed: **Odo-Ban applied to area. Cleanup scheduled.**

CONFIRMATION NUMBER

9F5AA1A7-6E0B-4F23-ADEB-527C0B375385

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 9F5AA1A7-6E0B-4F23-ADEB-527C0B375385

Date Sent: 7/21/2014

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P Street WWTP

Date Overflow Began: **7/21/2014**

Time:

10:05 am

Date Overflow Ended: **7/21/2014**

Time:

10:10 am

Location: **7200 South Q Street USMH: 0800 DSMH: 0770 Overflow occurred in yard at the cleanout on the service line.**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

Cause of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

(Enter overflow type if not listed)

Volume: **25**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Superintendent** Telephone Number **(479) 461-0914**

Additional Comments if Needed: Further clean up is scheduled.

CONFIRMATION NUMBER

9A83FDD4-B308-4EC7-9D91-AED1B3F24587

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 9A83FDD4-B308-4EC7-9D91-AED1B3F24587
Date Sent: 7/22/2014

SSO Bypass Upset

Facility Permit Number: **AR0033278**
 Date Overflow Began: **7/22/2014**
 Date Overflow Ended: **7/22/2014**
 Location:

Facility name: **P Street WWTP**
 Time: **10:23 am**
 Time: **11:40 am**

4607 North 33 St. USMH: 0730 DSMH: 0720 Overflow on service line cleanout due to stoppage in main line.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **385**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number **(479) 784-2331**

Additional Comments if Needed: Cleanup Scheduled.

From: (479) 784-2330
Steve Floyd
City of Fort Smith
3900 Kelley Highway

Fort Smith, AR 72904

Origin ID: FSMA



J142014061903uv

Ship Date: 21AUG14
ActWgt: 0.5 LB
CAD: 1731127/INET3550

Delivery Address Bar Code




Ref #
Invoice #
PO #
Dept #

SHIP TO: (501) 682-0638 **BILL SENDER**
NPDES Enforcement Section, Water
ADEQ
5301 Northshore Drive

North Little Rock, AR 72118


MON - 25 AUG AA
**** 2DAY ****

TRK# **7709 0235 6092**
0201



SA LITA

72118
AR-US
LIT



522G1/ECF2/8AC9

After printing this label:

1. Use the 'Print' button on this page to print your label to your laser or inkjet printer.
2. Fold the printed page along the horizontal line.
3. Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number.

Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$1,000, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written claims must be filed within strict time limits, see current FedEx Service Guide.

FSMA 70