

CONFIRMATION NUMBER

FDE3D6C5-B04A-492C-AFA8-53CC36306591

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: FDE3D6C5-B04A-492C-AFA8-53CC36306591

Date Sent: 2/26/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P Street

Date Overflow Began: **2-5/25/2015**

Time:

2:05 pm 1:50 pm

Date Overflow Ended: **2-5/25/2015**

Time:

2:20 pm

Location:

3820 Free Ferry, Manhole P007-1180, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 750

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Removed debris from manhole by hand.

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

2ADED508-30E0-492A-A113-5F2245BF5EDE

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 2ADED508-30E0-492A-A113-5F2245BF5EDE

Date Sent: 2/23/2015

SSO Bypass Upset

Facility Permit Number: **AR0021750**

Date Overflow Began: **2/23/2015**

Date Overflow Ended: **2/23/2015**

Location:

Facility name:

Time:

Time:

Massard

8:10 am

9:40 am

3600 North 50th Street, Manhole S009-1100, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **270**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

B6ADCBB6-B1FB-4FAB-9AFA-8D8B0E0A5816

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: B6ADCBB6-B1FB-4FAB-9AFA-8D8B0E0A5816
Date Sent: 2/23/2015

SSO Bypass Upset

Facility Permit Number:	AR0021750	Facility name:	Massard
Date Overflow Began:	2/22/2015	Time:	6:15 pm
Date Overflow Ended:	2/22/2015	Time:	8:30 pm
Location:	4619 South Q Street, Clean out between Manholes S003-1660 and S003-1650, yard		

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **192**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & J).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments If Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

7C3974CB-2F4F-49A8-B901-D57DEDE3B112

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 7C3974CB-2F4F-49A8-B901-D57DEDE3B112

Date Sent: 2/22/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P Street WWTP

Date Overflow Began: **2/21/2015**

Time:

3:45 pm

Date Overflow Ended: **2/21/2015**

Time:

8:30 pm

Location:

4601 Irene St. FL01-0760 to 0800 & 0710 to 0720 Service line clean out.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 285

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number **(479) 784-2331**

Additional Comments if Needed:

Cleanup scheduled.

Email a Copy of This Report to the Email Address:

Sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

E98C2F8C-B066-4817-8012-ABC8DC2ADB51

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: E98C2F8C-B066-4817-8012-ABC8DC2ADB51
Date Sent: 2/20/2015

SSO Bypass Upset

Facility Permit Number:	AR0033278	Facility name:	P Street
Date Overflow Began:	2/19/2015	Time:	4:45 pm
Date Overflow Ended:	2/19/2015	Time:	5:45 pm
Location:	200 Cornell Avenue, Manhole Z006-0230, yard		

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

- Type of Overflow**
- Manhole Overflow
 - Lift Station Overflow
 - Main Line Overflow
 - Service Line Overflow
 - Other Overflow Type:

(Enter overflow type if not listed)

Volume: **60**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

- Cause of Overflow**
- I & I - Rainfall
 - Roots
 - Grease
 - Debris
 - Equipment Failure
 - Construction
 - Vandalism
 - Power Failure
 - Line Failure/Break
 - Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson** Title **Superintendent** Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

64932F93-BBF3-406F-BB2D-E543C6E43E40

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 64932F93-BBF3-406F-BB2D-E543C6E43E40

Date Sent: 2/17/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P Street

Date Overflow Began: **2/17/2015**

Time:

11:50 am

Date Overflow Ended: **2/17/2015**

Time:

1:00 pm

Location:

8220 Highway 271, Service between manholes 2006-1940 and 2006-1870, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **70**

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

1E00ED3D-3930-478A-917F-FF8554C47599

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 1E00ED3D-3930-478A-917F-FF8554C47599
Date Sent: 2/17/2015

SSO Bypass Upset

Facility Permit Number: AR0033278
Date Overflow Began: 2/16/2015
Date Overflow Ended: 2/16/2015
Location: 4110 South 34th Street, Manhole MC07-1450, yard

Facility name: P Street
Time: 4:28 pm
Time: 5:56 pm

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
Lift Station Overflow
Main Line Overflow
Service Line Overflow
Other Overflow Type:

(Enter overflow type if not listed)

Volume: 440

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
Roots
Grease
Debris
Equipment Failure
Construction
Vandalism
Power Failure
Line Failure/Break
Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
Disinfected and Deodorized
Jet-Vac
Hydro Cleaned
Hand rodded
Spread Lime on Affected Area
Used Generator To Power Pumps/Equipment
Public Notification
Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
NEAH - No Evidence of Adverse Health/Environmental Impact
OEEI - Observed or Evidence of Environmental Impact
EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (476) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

6F4437D5-B86E-4426-8FB0-BDE2AD1FFCFF

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 6F4437D5-B86E-4426-8FB0-BDE2AD1FFCFF
Date Sent: 2/13/2015

SSO Bypass Upset

Facility Permit Number: AR0033278
Date Overflow Began: 2/13/2015
Date Overflow Ended: 2/13/2015
Location: 2404 Edwards St., Cleanout between Manholes P004-2180 and P004-2170, yard

Facility name:
Time:
Time:

P Street
12:40 pm
12:53 pm

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
Lift Station Overflow
Main Line Overflow
Service Line Overflow
Other Overflow Type:

(Enter overflow type if not listed)

Volume: 23

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
Roots
Grease
Debris
Equipment Failure
Construction
Vandalism
Power Failure
Line Failure/Break
Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
Disinfected and Deodorized
Jet-Vac
Hydro Cleaned
Hand rodded
Spread Lime on Affected Area
Used Generator To Power Pumps/Equipment
Public Notification
Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
NEAH - No Evidence of Adverse Health/Environmental Impact
OEEI - Observed or Evidence of Environmental Impact
EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

71A0EB75-E26B-46A2-A87C-321E2A3A491C

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 71A0EB75-E26B-46A2-A87C-321E2A3A491C
Date Sent: 2/12/2015

SSO Bypass Upset

Facility Permit Number: AR0033278

Date Overflow Began: 2/11/2015

Date Overflow Ended:

Location:

Facility name:

Time:

Time:

P Street

11:03 am

2207 and 2225 Rogers Avenue, Manhole P005-2290, Storm Sewer

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river, stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause: **Manhole is connected to Storm Sewer**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Requires construction of new sewer line

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

An engineer has been retained to design needed improvements to disconnect the sanitary sewer from the storm sewer and route it to the nearest sanitary sewer.

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

715871EA-0841-4919-B49D-A96CAB4B9FB9

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 715871EA-0841-4919-B49D-A96CAB4B9FB9

Date Sent: 2/10/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P Street

Date Overflow Began: **2/9/2015**

Time:

9:30 am

Date Overflow Ended:

Time:

Location:

2321 Rogers Avenue, Nearest manhole P005-2290, storm sewer

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause: **service tied to storm drain**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe **construct line extension**
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

600 feet of new sewer main will have to be constructed to tie this customer on to a public sewer. An Engineer has been hired to design the new sewer line.

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

05965DF9-0925-4F1B-AD29-C3B5F779AE94

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 05965DF9-0925-4F1B-AD29-C3B5F779AE94

Date Sent: 2/10/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Date Overflow Began: **2/9/2015**

Date Overflow Ended:

Location:

Facility name:

Time:

Time:

P Street

11:07 am

2309 Rogers Avenue, Nearest manhole P005-2290, storm sewer

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause: **service tied to storm drain**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe **construct line extension**
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

600 feet of new sewer main will have to be constructed to tie this customer on to a public sewer. An Engineer has been hired to design the new sewer line.

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

12BC24C6-45D0-48FC-8AB3-518A48249342

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 12BC24C6-45D0-48FC-8AB3-518A48249342

Date Sent: 2/9/2015

SSO Bypass Upset

Facility Permit Number:

AR0033278

Facility name:

P Street Wastewater Treatment Plant

Date Overflow Began:

02/08/2015

Time:

1:00 pm

Date Overflow Ended:

02/08/2015

Time:

2:19 pm

Location:

4506 South 22nd Street Manhole number MC07-0220 Overflow reached adjacent roadway ditch.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

79

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Parke**

Title **Director of Utilities**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fortsmithar.gov

CONFIRMATION NUMBER

A5DCF56D-1D77-4D23-9411-34F981700C15

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: A5DCF56D-1D77-4D23-9411-34F981700C15

Date Sent: 2/8/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P Street WWTP

Date Overflow Began: **2/7/2015**

Time:

8:15 am

Date Overflow Ended: **2/7/2015**

Time:

9:26 am

Location:

2720 South S Street P009-0380

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume:

71

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number **(479) 784-2331**

Additional Comments if Needed:

Immediate cleanup.

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

4E0239A5-D06A-4DFD-AE35-F8B0D0399571

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 4E0239A5-D06A-4DFD-AE35-F8B0D0399571

Date Sent: 2/6/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Date Overflow Began: **2/6/2015**

Date Overflow Ended: **2/6/2015**

Location:

Facility name:

Time:

Time:

P Street

10:00 am

10:45 am

4615 North 30th Street, cleanout between manholes FL01-0900 and FL01-0880, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 225

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

A00CDCDB-2B32-4A86-86E2-735F8506D27B

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: A00CDCDB-2B32-4A86-86E2-735F8506D27B

Date Sent: 2/6/2015

SSO Bypass Upset

Facility Permit Number: **AR0021750**

Facility name:

Massard

Date Overflow Began: **2/5/2015**

Time:

8:08 am

Date Overflow Ended: **2/5/2015**

Time:

9:26 am

Location:

5311 Birnie Avenue, cleanout between manholes S005-1450 ans S005-14440, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 78

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 184-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

2912EC22-0236-4C0E-B057-3896DAA16ABD

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 2912EC22-0236-4C0E-B057-3896DAA16ABD

Date Sent: 2/6/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P Street

Date Overflow Began: **2/5/2015**

Time:

3:34 pm

Date Overflow Ended: **2/5/2015**

Time:

4:14 pm

Location:

3201 North 28th Street, Manhole P001-0510, ditch

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

40

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

4D6983C8-F127-421F-A4C2-7461FBEE65B1

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 4D6983C8-F127-421F-A4C2-7461FBEE65B1
Date Sent: 2/6/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**
 Date Overflow Began: **2/5/2015**
 Date Overflow Ended: **2/5/2015**
 Location: **7906 Hermitage Drive, Cleanout between manholes 2006-1270 and 2006-1260, yard**

Facility name:
 Time:
 Time:

P Street
1:15 pm
2:15 pm

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume: **300**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

559AE676-C8E1-4271-A0B9-2988FA11COF5

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 559AE676-C8E1-4271-A0B9-2988FA11COF5

Date Sent: 2/2/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P Street

Date Overflow Began: **2/2/2015**

Time:

10:00 am

Date Overflow Ended: **2/2/2015**

Time:

11:10 am

Location: **900 South 16th Street, Manhole P011-1940**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 450

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

527B3F5A-E6F9-4EEB-A8E8-FB4087C99F79

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 527B3F5A-E6F9-4EEB-A8E8-FB4087C99F79
Date Sent: 2/2/2015

SSO Bypass Upset

Facility Permit Number: AR0021750
Date Overflow Began: 2/2/2015
Date Overflow Ended: 2/2/2015
Location:

Facility name: Massard
Time: 9:00 am
Time: 9:55 am

511 North 47th Street, Clean out between manholes S006-0950 and S006-0940, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 275

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill


Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com



CONFIRMATION NUMBER

21EC0C01-B8A9-44DA-A5B5-1190F6842278

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 21EC0C01-B8A9-44DA-A5B5-1190F6842278

Date Sent: 2/2/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P Street WWTP

Date Overflow Began: **2/1/2015**

Time:

5:30 pm

Date Overflow Ended: **2/1/2015**

Time:

6:15 pm

Location: **8828 South 28th Street
Z005-0090**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume: **450**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 784-2331**

Additional Comments if Needed:

cleanup scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

EBFA074A-93ED-4A56-B33B-180A23DEA0FE

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: EBFA074A-93ED-4A56-B33B-180A23DEA0FE
Date Sent: 2/2/2015

SSO Bypass Upset

Facility Permit Number:	AR0033278	Facility name:	P Street WWTP
Date Overflow Began:	2/1/2015	Time:	2:30 pm
Date Overflow Ended:	2/1/2015	Time:	5:15 pm
Location:	7500 Cypress Avenue Z002-0290		

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **525**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number **(479) 784-2331**

Additional Comments if Needed:

Cleanup scheduled.

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

970137EB-877F-4001-9D4B-96C9FB688D7E

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 970137EB-877F-4001-9D4B-96C9FB688D7E

Date Sent: 2/2/2015

SSO Bypass Upset

Facility Permit Number: AR0033278

Facility name:

P Street

Date Overflow Began: 2/1/2015

Time:

10:00 am

Date Overflow Ended: 2/1/2015

Time:

10:30 am

Location:

8224 Cypress Ave, clean out between manholes Z006-1530 and Z006-1470, yard and building

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume:

600 500

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river, stream)

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

[Empty box for additional comments]

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

6E4F49AE-DBB-410A-BBD7-EAB71BBD0C50

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 6E4F49AE-1DB8-410A-BBD7-EAB71BBD0C50
Date Sent: 2/2/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**
 Date Overflow Began: **2/1/2015**
 Date Overflow Ended: **2/1/2015**
 Location:

Facility name:
 Time:
 Time:

P Street
7:50 am
10:00 am

1600 Holley Circle, clean out between manholes Z006-1530 and Z006-1470, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **2600**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

Monthly SSO Report February 2015

Permit Number	Manhole Number	Location	Receiving Water	Duration	Cause	Volume	Component	Date	Started	Stopped	Steps Taken
AR0033278	Z006-1530 to 1470	1600 Holly Circle	Yard	130 min	Grease	2600 gal	Service line overflow	2/1/2015	7:50 AM	10:00 AM	Jet-Vac, disinfected and deodorized
AR0033278	Z006-1530 to 1470	8224 Cypress Avenue	Yard/Building	25 min	Grease	500 gal	Service line overflow	2/1/2015	10:05 AM	10:30 AM	Inadvertantly reported twice.
AR0033278	Z002-0290	7500 Cypress Avenue	Yard	105 min	Grease	525 gal	Manhole	2/1/2015	2:30 PM	5:15 PM	Jet-Vac, disinfected and deodorized
AR0033278	Z005-0090	8828 South 28th Street	Yard	45 min	Grease	450 gal	Manhole	2/1/2015	5:30 PM	6:15 PM	Inadvertantly reported twice. Jet-Vac, disinfected and deodorized
AR0021750	S006-0950 to 0940	511 North 47th Street	Yard	55 min	Grease	275 gal	Service line overflow	2/2/2015	9:00 AM	9:55 AM	Jet-Vac, disinfected and deodorized
AR0033278	P011-1940	900 South 16th Street	River/Stream	70 min	Grease	450 gal	Manhole	2/2/2015	10:00 AM	11:10 AM	Jet-Vac, disinfected and deodorized
AR0033278	Z006-1270 to 1260	7906 Hermitage Drive	Yard	60 min	Grease	300 gal	Service line overflow	2/5/2015	1:15 PM	2:15 PM	Jet-Vac, disinfected and deodorized
AR0033278	P001-0510	3201 North 28th Street	Ditch	40 min	Roots/Grease	40 gal	Manhole	2/5/2015	3:34 PM	4:14 PM	Jet-Vac, disinfected and deodorized
AR0021750	S005-1450 to 1440	5311 Birnie Avenue	River/Stream	78 min	Roots	78 gal	Service line overflow	2/5/2015	8:08 AM	9:26 AM	Jet-Vac, disinfected and deodorized
AR0033278	FL01-0900 to 0880	4615 North 30th Street	Yard	45 min	Grease	225 gal	Service line overflow	2/6/2015	10:00 AM	10:45 AM	Jet-Vac, disinfected and deodorized
AR0033278	P009-0380	2720 South S Street	River/Stream	71 min	Roots	71 gal	Manhole	2/7/2015	8:15 AM	9:26 AM	Jet-Vac, disinfected and deodorized
AR0033278	MC07-0220	4506 South 22nd Street	River/Stream	79 min	Roots/Grease	79 gal	Manhole	2/8/2015	1:00 PM	2:19 PM	Jet-Vac, disinfected and deodorized
AR0033278	P005-2290	2309 Rogers Avenue	River/Stream		Service to Storm Drain		Service line overflow	2/9/2015	11:07 AM		600 feet of new sewer main to be constructed to tie this customer to a public sewer.
AR0033278	P005-2290	2321 Rogers Avenue	River/Stream		Service to Storm Drain		Service line overflow	2/9/2015	9:30 AM		600 feet of new sewer main to be constructed to tie this customer to a public sewer.
AR0033278	P005-2290	2207 and 2225 Rogers Avenue	River/Stream		Service to Storm Drain		Service line overflow	2/11/2015	11:03 AM		600 feet of new sewer main to be constructed to tie this customer to a public sewer.
AR0033278	P004-2180 to 2170	2404 Edwards Street	Yard	23 min	Grease	23 gal	Service line overflow	2/13/2015	12:40 PM	12:53 PM	Jet-Vac, disinfected and deodorized
AR0033278	MC07-1450	4110 South 34th Street	Yard	88 min	Roots	440 gal	Manhole	2/16/2015	4:28 PM	5:56 PM	Jet-Vac, disinfected and deodorized
AR0033278	Z006-1940 to 1870	8220 Highway 271 South	Yard	70 min	Grease	70 gal	Service line overflow	2/17/2015	11:50 AM	1:00 PM	Jet-Vac, disinfected and deodorized
AR0033278	Z006-0230	200 Cornell Avenue	Yard	60 min	Roots	60 gal	Manhole	2/19/2015	4:45 PM	5:45 PM	Jet-Vac, disinfected and deodorized, public notified
AR0033278	FL01-0760 to 0800	4601 Irene Street	Yard	285 min	Grease	285 gal	Service line overflow	2/21/2015	3:45 PM	8:30 PM	Jet-Vac, disinfected and deodorized, public notified
AR0021750	S003-1660 to 1650	4619 South Q Street	Yard	192 min	Line Failure/Break	192 gal	Service line overflow	2/22/2015	6:15 PM	8:30 PM	Jet-Vac, disinfected and deodorized, public notified
AR0021750	S009-1100	3600 North 50th Street	Yard	90 min	Debris	270 gal	Manhole	2/23/2015	8:10 AM	9:40 AM	Jet-Vac, disinfected and deodorized
AR0033278	P007-1180	3820 Free Ferry	Yard	30 min	Debris	750 gal	Manhole	2/25/2015	1:50 PM	2:20 PM	Removed debris from manhole be hand

X[®]
press

0 23
RT 177
ST 2
16:30
A
9266
03.24
y Urgent

Page 1 of 1

From: (479) 784-2330
Steve Floyd
City of Fort Smith
3900 Kelley Highway
Fort Smith, AR 72904

Origin ID: FSMA



Ship Date: 19MAR15
ActWgt: 0.5 LB
CAD: 1731127/INET3610

Delivery Address Bar Code



SHIP TO: (501) 682-0638
NPDES Enforcement Section, Water
ADEQ
5301 Northshore Drive


BILL SENDER

North Little Rock, AR 72118

Ref #
Invoice #
PO #
Dept #


TUE - 24 MAR 4:30P
EXPRESS SAVER

TRK# 7731 6298 9266
0201



SA LITA

72118
AR-US
LIT



537J1/879A/EE4B

Insert shipping document here.