

Monthly SSO Report November 2015

Manhole Number	Location	Receiving Water	Duration Min.	Cause	Volume (Gallons)	Component	Date Overflow Started	Date Overflow Stopped	Started	Stopped	Steps Taken
005-0720 to 0710	2016 North 53 Street	yard	180	Line Failure/Break	1800	Service Line	11/12/2015	11/12/2015	9:00 AM	12:00 PM	Repair
001-0682	1601 South 74th Street	yard	25	Grease	250	Manhole	11/13/2015	11/13/2015	10:30 AM	10:55 AM	Jet-Vac, Disinfected and Deodorized
004-1140	5600 Rogers Avenue	storm drain	90	I & I - Rainfall	1800	Manhole	11/5/2015	11/6/2015	7:45 PM	9:30 PM	originally reported as occurring on 11/15, 11/16
001-0670	1601 South 74th Street	paved area	385	I & I - Rainfall	9628	Manhole	11/15/2015	11/16/2015	8:20 PM	2:45 AM	
001-1090 to 1080	8815 Fresno Street	yard	30	Grease	150	Service Line	11/5/2015	11/5/2015	4:30 PM	5:00 PM	Jet-Vac, Disinfected and Deodorized, Originally reported as occurring on 11/15, and Manhole M001-1220 to 1080
001-0015	So. 66th & Kinkead	yard	360	I & I - Rainfall	99000	Manhole	11/17/2015	11/17/2015	10:20 AM	4:20 PM	
001-0670	1601 So. 74th	yard	1364	I & I - Rainfall	272800	Manhole	11/17/2015	11/18/2015	9:25 AM	8:35 AM	
008-2000	3100 Kelley Hwy	Storm Drain	580	I & I - Rainfall	14500	Manhole	11/17/2015	11/17/2015	9:20 AM	7:00 PM	
001-0140	#9 Riverlyn Terrace	yard	1350	I & I - Rainfall	270000	Manhole	11/17/2015	11/18/2015	10:00 AM	8:30 AM	
004-1140	South 56th & Rogers Ave	Storm Drain	480	I & I - Rainfall	120000	Manhole	11/17/2015	11/17/2015	9:20 AM	5:20 PM	
001-1072	7400 Euper Lane	Storm Drain	439	I & I - Rainfall	43900	Manhole	11/17/2015	11/17/2015	9:36 AM	4:55 PM	
001-1120	2002 So. 71st Street	Storm Drain	370	I & I - Rainfall	18500	Manhole	11/17/2015	11/17/2015	10:55 AM	5:05 PM	
001-1070	So. 74th Street	Storm Drain	440	I & I - Rainfall	44000	Manhole	11/17/2015	11/17/2015	9:30 AM	4:50 PM	
001-1080	2000 74th St	Storm Drain	436	I & I - Rainfall	21800	Manhole	11/17/2015	11/17/2015	9:24 AM	4:40 PM	
001-1060	1801 So. 74th St.	yard	421	I & I - Rainfall	63150	Manhole	11/17/2015	11/17/2015	9:44 AM	4:45 PM	
001-1060	1801 South 74th Street	yard	1230	I & I - Rainfall	23800	Manhole	11/27/2015	11/28/2015	8:40 PM	4:30 PM	
004-1140	5600 Rogers Avenue	Paved area	120	I & I - Rainfall	600	Manhole	11/27/2015	11/27/2015	7:05 AM	9:00 AM	
002-0860	12920 Britteny Drive	yard	1310	I & I - Rainfall	600	Manhole	11/27/2015	11/28/2015	7:30 PM	4:40 AM	This was reported as going to Massard, AR0021750 but does not.
001-0670	Carol Ann Cross Park	paved area	1260	I & I - Rainfall	25100	Manhole	11/27/2015	11/28/2015	8:35 PM	5:30 PM	
001-0680	Carol Ann Cross Park	paved area	1070	I & I - Rainfall	26750	Manhole	11/29/2015	11/30/2015	3:30 PM	9:20 PM	
009-0825	2001 Old Greenwood Rd.	yard	100	Roots	5000	Manhole	11/02/2015	11/2/2015	11:40 AM	1:00 PM	Jet-Vac
002-1620	1323 North 56th Terrace	yard	65	Roots	650	Manhole	11/03/2015	11/3/2015	3:50 PM	4:55 PM	Jet-Vac
002-1590	1422 North 56 Terrace	paved area	55	Grease	550	Manhole	11/16/2015	11/16/2015	6:50 PM	7:45 PM	Jet-Vac
009-0490 to 0480	2104 Garner - Ln	yard	440	Line Failure/Break	2200	Gravity Main	11/16/2015	11/16/2015	11:10 AM	6:30 PM	Jet-Vac, Originally reported as occurring at 2100
009-2890 to 0350	1901 Greenwood Ave.	Building	105	Roots	1050	Service Line	11/16/2015	11/16/2015	9:15 PM	11:00 PM	Jet-Vac, Disinfected and Deodorized
009-0240	1823 South 31st St.	Storm Drain	159	I & I - Rainfall	4770	Manhole	11/17/2015	11/17/2015	11:00 AM	1:39 PM	
005-3000	1415 North 32nd	ditch	1180	I & I - Rainfall	118000	Manhole	11/17/2015	11/18/2015	11:25 AM	8:15 AM	
005-1860	North 20th & E St.	Storm Drain	1290	I & I - Rainfall	129000	Manhole	11/17/2015	11/18/2015	11:55 AM	9:25 AM	
005-1920	North 20th & North D Street	Storm Drain	1264	I & I - Rainfall	63450	Manhole	11/17/2015	11/18/2015	12:11 PM	9:20 AM	
008-1300 to 1290	528 N 31st Street	ditch	1350	Construction, I & I - Rain	405000	Gravity Main	11/17/2015	11/18/2015	9:30 AM	8:00 AM	Overflow occurred at open trench during main repair.
007-0060	1400 North 34th St.	Storm Drain	1315	I & I - Rainfall	52600	Manhole	11/17/2015	11/18/2015	11:37 AM	9:32 AM	
002-1140 to 1120	501 North 11th	Building	15	I & I - Rainfall	15	Service Line	11/17/2015	11/17/2015	11:40 AM	11:55 AM	Public Notification
004-0320	5100 Towson Ave.	Paved area	25	Grease	125	Manhole	11/17/2015	11/17/2015	9:50 AM	10:15 AM	Jet-Vac, Disinfected and Deodorized

Monthly SSO Report November 2015

AR0033278	MC02-0230	2100 Towson Ave	creek	105	Roots	525	Manhole	11/17/2015	11/17/2015	12:50 PM	2:35 PM	Jet-Vac
AR0033278	P007-0480	3710 Kinkead Ave.	ditch	1323	I & I - Rainfall	39690	Manhole	11/17/2015	11/18/2015	11:25 AM	9:28 AM	
AR0033278	Z003-1540 to 1410	8617 So. 31st Terrace	Building	100	Grease	500	Service Line	11/17/2015	11/17/2015	1:20 PM	3:00 PM	Jet-Vac
AR0033278	P007-0065	1425 North 34th St.	Storm Drain	1315	I & I - Rainfall	78900	Manhole	11/17/2015	11/18/2015	11:38 AM	9:33 AM	
AR0033278	MC06-1120	1413 Phoenix Ave	Storm Drain	460	I & I - Rainfall	46000	Manhole	11/17/2015	11/17/2015	8:50 AM	4:30 PM	
AR0033278	P006-0930 to 0910	2223 South S Street	Building	240	Line Failure/Break	1250	Service Line	11/17/2015	11/17/2015	10:20 AM	2:20 PM	Jet-Vac, Disinfected and Deodorized, Public Notice
AR0033278	W001-0580	North 25th Street	Paved area	15	Grease	75	Manhole	11/18/2015	11/18/2015	3:50 PM	4:04 PM	Jet-Vac, Disinfected and Deodorized
AR0033278	Z001-2510 to 2500	4818 South 31st	yard	1	I & I - Rainfall	1	Service Line	11/18/2015	11/18/2015	11:40 PM	12:00 PM	
AR0033278	P009-0490	2104 Garner Ln P009-0490	yard	57	Roots	285	Manhole	11/18/2015	11/18/2015	9:53 AM	10:50 AM	Jet-Vac
AR0033278	W001-0580	North 25th Street and Spradling Avenue	Paved Area	15	Grease	75	Manhole	11/18/2015	11/18/2015	3:50 PM	4:10 PM	Jet-Vac, Disinfected and Deodorized, Public Notice
AR0033278	P007-0482	3700 Kinkead Avenue	yard	735	I & I - Rainfall	7350	Manhole	11/27/2015	11/28/2015	8:10 PM	8:25 PM	
AR0033278	P005-3030	3200 North M Street	yard	910	I & I - Rainfall	16200	Manhole	11/27/2015	11/28/2015	5:40 PM	8:10 AM	
AR0033278	P009-0480	2200 Garner Lane	yard	120	Roots	600	Manhole	11/28/2015	11/28/2015	11:25 AM	1:25 PM	Jet-Vac
AR0033278	P005-3030	3200 North M Street	paved area	977	I & I - Rainfall	19540	Manhole	11/29/2015	11/30/2015	4:40 PM	8:57 AM	
AR0033278	P004-0860	North 31st and North S Streets	Strom Drain	35	Roots, grease	525	Manhole	11/30/2015	11/30/2015	10:40 AM	11:15 AM	Machine Rodded

15-0452

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 41920E4D-7CC6-4CFD-AF88-5A4508A78E69

Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number: AR0033278

Facility name:

P Street WWTP

Date Overflow Began: 11-16-15

Time:

11:10 am

Date Overflow Ended: 11-16-15

Time:

6:30 pm

Location: 2100 Garner Ln P009 - USMH 0490, DSMH 0480 Line Failure

2104 JB

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 2200

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By Steve Floyd

Title Supt

Telephone Number (479) 461-0914

Additional Comments if Needed:

Clean up scheduled.

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

401FF196-25CD-4334-B2CD-AD7B98B11C4E

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 401FF196-25CD-4334-B2CD-AD7B98B11C4E

Date Sent: 11/18/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

N/A

11-17-2015

11-18-2015

Facility name:

Time:

Time:

None

12:35 pm

9:00 am

12920 →
JBT

1290 Brittany Dr. Overflow on Manhole #0860, maintained by the City and owned by Fort Chaffee Redevelopment Authority. Flow from this line flows to the City of Barling treatment works.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
 Lift Station Overflow
 Main Line Overflow
 Service Line Overflow
 Other Overflow Type:

(Enter overflow type if not listed)

Volume: 336875

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
 Roots
 Grease
 Debris
 Equipment Failure
 Construction
 Vandalism
 Power Failure
 Line Failure/Break
 Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
 Jet-Vac Hydro Cleaned
 Hand rodded Spread Lime on Affected Area
 Used Generator To Power Pumps/Equipment Public Notification
 Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
 OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By Steve Floyd

Title Supt.

Telephone Number (479) 784-2331

Additional Comments if Needed:

cleanup scheduled

Email a Copy of This Report to the Email Address:

sflloyd@fortsmithar.gov

CONFIRMATION NUMBER

CB242B01-1B98-43C9-86F7-28D43EF8112F

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: CB242B01-1B98-43C9-86F7-28D43EF8112F

Date Sent: 11/30/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number: **n/a**
 Date Overflow Began: **11/29/2015**
 Date Overflow Ended: **11/30/2015**
 Location: **12920 Brittany Drive, FC02-0860, Yard**

Facility name: **n/a**
 Time: **3:30 pm**
 Time: **9:20 am**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **37450**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I):

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

The is owned by Fort Chaffee Redevelopment Authority and Ran by the city of Fort Smith. The flow goes to the City of Barling.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

B495B610-F81D-46FD-933B-874B6957AE79

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: B495B610-F81D-46FD-933B-874B6957AE79
Date Sent: 11/30/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
11/30/2015
11/30/2015

Facility name:
 Time:
 Time:

P Street
10:40 am
11:15 am

North 31st and North S Streets, P004-0860, Storm Drain

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 525

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

A2AD8C63-33E5-4B82-8104-1C894E3BF363

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: A2AD8C63-33E5-4B82-8104-1C894E3BF363
Date Sent: 12/1/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
11/18/2015
11/18/2015

Facility name:
 Time:
 Time:

P Stree
3:50 pm
4:10 pm

North 25th Street and Spradling Avenue, W001-0580, Paved Area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **75**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OE EI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

No ADEQ confirmation for this overflow could be found.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

4D16941A-274B-4ED8-B8C3-5675CF0A6436

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 4D16941A-274B-4ED8-B8C3-5675CF0A6436
Date Sent: 11/30/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
11/29/2015
11/30/2015

Facility name:
 Time:
 Time:

P Stree
4:40 pm
8:57 an

3200 North M Street, P005-3030, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 19540

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

999FC436-208B-43F5-A900-6ED42A39CC89

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 999FC436-208B-43F5-A900-6ED42A39CC89
 Date Sent: 11/30/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0021750
 11/29/2015
 11/30/2015

Facility name:
 Time:
 Time:

Massart
 3:30 pm
 9:20 am

Carol Ann Cross Park, RL01-0680, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 26750

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 1E8DA065-91E9-4F14-86EC-A8E4E613DBB6

Date Sent: 11/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard

Date Overflow Began:

11/27/2015

Time:

7:30 pm

Date Overflow Ended:

11/28/2015

Time:

4:40 pm

Location:

12920 Britteny Drive, FC02-0860, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type: 31750

(Enter overflow type if not listed)

Volume:

600

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river, stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: A4F2F58D-DA34-4AFA-8272-EF67AC0569AE

Date Sent: 11/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

11/27/2015

Time:

5:40 pm

Date Overflow Ended:

11/28/2015

Time:

8:10 am

Location:

3200 North M Street, P005-3030, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

16200

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: C6374B8A-6564-45FC-BCBF-1F6AB0DA2F0D

Date Sent: 11/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:	AR0021750	Facility name:	Massard
Date Overflow Began:	11/27/2015	Time:	8:40 pm
Date Overflow Ended:	11/28/2015	Time:	4:30 pm
Location:	1801 South 74th Street, RL01-1060, yard		

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 23800

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 31F459D1-1804-4F6D-B171-60E80617EB45

Date Sent: 11/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard

Date Overflow Began:

11/27/2015

Time:

8:35 pm

Date Overflow Ended:

11/28/2015

Time:

5:30 pm

Location:

Carol Ann Cross Park, RL01-0670, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

25100

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 85D8CEB5-EF8E-4905-9E96-5C9D3BDFE3B5

Date Sent: 11/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

11/27/2015

Time:

8:10 pm

Date Overflow Ended:

11/28/2015

Time:

8:25 am

Location:

3700 Kinkead Avenue, P007-0482, yardd

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

7350

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 184-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: BF1D46C2-1DEE-4CE1-AC8A-D05A7659672F

Date Sent: 11/28/2015

<input checked="" type="checkbox"/> SSO	<input type="checkbox"/> Bypass	<input type="checkbox"/> Upset	<input type="checkbox"/> Unpermitted Discharge	Facility name:	Massard
Facility Permit Number:	AR0021750			Time:	7:05 pm
Date Overflow Began:	11/27/2015			Time:	9:00 am
Date Overflow Ended:	11/27/2015				
Location:	5600 Rogers Avenue, S004-1140, Paved area				

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow		Cause of Overflow	
<input checked="" type="checkbox"/> Manhole Overflow		<input checked="" type="checkbox"/> I & I - Rainfall	
<input type="checkbox"/> Lift Station Overflow		<input type="checkbox"/> Roots	
<input type="checkbox"/> Main Line Overflow		<input type="checkbox"/> Grease	
<input type="checkbox"/> Service Line Overflow		<input type="checkbox"/> Debris	
<input type="checkbox"/> Other Overflow Type:		<input type="checkbox"/> Equipment Failure	
	(Enter overflow type if not listed)	<input type="checkbox"/> Construction	
Volume:	600	<input type="checkbox"/> Vandalism	
	(Give an estimate in gallons)	<input type="checkbox"/> Power Failure	
Impact of SSO Event:	SSO Reached Receiving Water (river,stream)	<input type="checkbox"/> Line Failure/Break	
		<input type="checkbox"/> Other Cause:	

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

<input type="checkbox"/> Machine rodded	<input type="checkbox"/> Disinfected and Deodorized
<input type="checkbox"/> Jet-Vac	<input type="checkbox"/> Hydro Cleaned
<input type="checkbox"/> Hand rodded	<input type="checkbox"/> Spread Lime on Affected Area
<input type="checkbox"/> Used Generator To Power Pumps/Equipment	<input type="checkbox"/> Public Notification
<input type="checkbox"/> Other: Describe	

Environmental Damage

<input type="checkbox"/> OEHC - Observed or Evidence of Human Contact	<input checked="" type="checkbox"/> NEAH - No Evidence of Adverse Health/Environmental Impact
<input type="checkbox"/> OEEI - Observed or Evidence of Environmental Impact	<input type="checkbox"/> EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson Title Superintendent Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: A95AA884-1F2E-413F-A88E-995C3FF9EA1D

Date Sent: 11/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

11/28/2015

Time:

11:25 am

Date Overflow Ended:

11/28/2015

Time:

1:25 pm

Location:

2200 Garner Lane, P009-0480, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

600

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river, stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEL - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

920185E1-A53F-440C-A75E-6B436C255663

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 920185E1-A53F-440C-A75E-6B436C255663

Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard WWTP

Date Overflow Began:

11-17-2015

Time:

9:24 am

Date Overflow Ended:

11-17-2015

Time:

4:40 pm

Location:

2000 74th St RL01- overflow MH 1080

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, stor

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

21800

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number **(479) 461-0914**

Additional Comments if Needed:

clean up scheduled

Email a Copy of This Report to the Email Address:

sfloys@fortsmithar.gov

CONFIRMATION NUMBER

15DBF5AE-EDD0-4247-9E8B-8D8DEF943DE

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 15DBF5AE-EDD0-4247-9E8B-8D8DEF943DE
Date Sent: 11/18/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
11-18-2015
11-18-2015

Facility name:
 Time:
 Time:

P Street WWTP
9:53 am
10:50 am

2104 Garner Ln Basin P009- USMH 0490, DSMH 0480 Overflow@ MH#0490

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 285

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OE EI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 784-2331**

Additional Comments if Needed:

clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

04D8A0F5-AB58-40B0-B1FE-E00D90BF0874

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 04D8A0F5-AB58-40B0-B1FE-E00D90BF0874

Date Sent: 11/18/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
11-18-2015
11-18-2015

Facility name:
 Time:
 Time:

P Street WWTP
11:40 am
12:00 pm

4818 South 31st Basin Z001- USMH 2510, DSMH 2500

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **1**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 784-2331**

Additional Comments if Needed:

Clean up scheduled.

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

BEC608AA-1A75-444B-89B1-201B47DE1D0F

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: BEC608AA-1A75-444B-89B1-201B47DE1D0F

Date Sent: 11/19/2015

SSO Bypass Upset Unpermitted Discharge
Facility Permit Number:
Date Overflow Began:
Date Overflow Ended:
Location:

AR0033278
11-18-2015
11-18-2015

Facility name:
Time:
Time:

P Street WWTP
3:50 pm
4:05 pm

North 25th Street Basin W001 Overflow@ MH#0580

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
Lift Station Overflow
Main Line Overflow
Service Line Overflow
Other Overflow Type:

(Enter overflow type if not listed)

Volume: 75

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
Roots
Grease
Debris
Equipment Failure
Construction
Vandalism
Power Failure
Line Failure/Break
Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
Disinfected and Deodorized
Jet-Vac
Hydro Cleaned
Hand rodded
Spread Lime on Affected Area
Used Generator To Power Pumps/Equipment
Public Notification
Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
NEAH - No Evidence of Adverse Health/Environmental Impact
OEEI - Observed or Evidence of Environmental Impact
EFK - Evidence of Fish Kill

Reported By Steve Floyd

Title Supt.

Telephone Number (479) 784-2331

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

ADD78D09-FD22-4875-8634-D22BCCAF653E

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: ADD78D09-FD22-4875-8634-D22BCCAF653E
Date Sent: 11/18/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number: **AR0033278**
 Date Overflow Began: **11-17-2015**
 Date Overflow Ended: **11-18-2015**
 Location: **North 20th & North D Street**

Facility name: **P Street WWTP**
 Time: **12:11 pm**
 Time: **9:20 am**

Basin P005 Overflow@ MH# 1920

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 63450

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEET - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number **(479) 784-2331**

Additional Comments If Needed:

clean up scheduled

Email a Copy of This Report to the Email Address:
sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

A0317E0F-4D21-44DA-A2CB-4FBFFBA1F355

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: A0317E0F-4D21-44DA-A2CB-4FBFFBA1F355

Date Sent: 11/18/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street WWTP

Date Overflow Began:

11-17-2015

Time:

11:55 am

Date Overflow Ended:

11-18-2015

Time:

9:25 am

Location:

North 20th & E St. Basin P005 Overflow@ MH# 1860

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 129000

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By Steve Floyd

Title Supt.

Telephone Number (479) 784-2331

Additional Comments if Needed:

Clean up scheduled.

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

F9878370-E8F4-4B45-85E4-1CE9CBC2DBCC

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: F9878370-E8F4-4B45-85E4-1CE9CBC2DBCC

Date Sent: 11/18/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0033278

11-17-2015

11-18-2015

Facility name:

Time:

Time:

P Street WWTP

11:25 am

9:28 am

3710 Kinkead Ave. Basin P007 Overflow@ MH# 0480

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

Manhole Overflow

Lift Station Overflow

Main Line Overflow

Service Line Overflow

Other Overflow Type:

(Enter overflow type if not listed)

Volume: 39690

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

I & I - Rainfall

Roots

Grease

Debris

Equipment Failure

Construction

Vandalism

Power Failure

Line Failure/Break

Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

Machine rodded

Disinfected and Deodorized

Jet-Vac

Hydro Cleaned

Hand rodded

Spread Lime on Affected Area

Used Generator To Power Pumps/Equipment

Public Notification

Other: Describe

Environmental Damage

OEHC - Observed or Evidence of Human Contact

NEAH - No Evidence of Adverse Health/Environmental Impact

OEEI - Observed or Evidence of Environmental Impact

EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 784-2331**

Additional Comments if Needed:

clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

5ED96F5A-412B-4298-82E7-C53803036ECB

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 5ED96F5A-412B-4298-82E7-C53803036ECB

Date Sent: 11/18/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0033278

11-17-2015

11-17-2015

Facility name:

Time:

Time:

P Street WWTP

11:38 am

9:33 am

1425 North 34th St. Basin P007 Overflow@ MH# 0065

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume:

78900

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 784-2331**

Additional Comments if Needed:

clean up scheduled.

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

293C464D-63B9-4A11-8BF1-A822B1D9FE53

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 293C464D-63B9-4A11-8BF1-A822B1D9FE53
Date Sent: 11/18/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number: **AR0033278**
 Date Overflow Began: **11-17-2015**
 Date Overflow Ended: **11-18-2015**
 Location: **1400 North 34th St. Basin P007 Overflow@ MH# 0060**

Facility name: **Massard WWTP**
 Time: **11:37 am**
 Time: **9:32 am**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type: *(Enter overflow type if not listed)*

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume: **52600**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEL - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt**

Telephone Number **(479) 784-2331**

Additional Comments if Needed:

clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

6F45E074-1469-479A-9A8C-8BFCAF077D23

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 6F45E074-1469-479A-9A8C-8BFCAF077D23

Date Sent: 11/18/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard WWTP

Date Overflow Began:

11-17-2015

Time:

10:55 am

Date Overflow Ended:

11-17-2015

Time:

5:05 pm

Location:

2002 So. 71st Street Basin RL01 Overflow@ MH# 1120

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
 Lift Station Overflow
 Main Line Overflow
 Service Line Overflow
 Other Overflow Type:

(Enter overflow type if not listed)

Volume: 18500

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
 Roots
 Grease
 Debris
 Equipment Failure
 Construction
 Vandalism
 Power Failure
 Line Failure/Break
 Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
 Jet-Vac Hydro Cleaned
 Hand rodded Spread Lime on Affected Area
 Used Generator To Power Pumps/Equipment Public Notification
 Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
 OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By Steve Floyd

Title Supt.

Telephone Number (479) 784-2331

Additional Comments if Needed:

clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

200597F0-5D0C-4153-88D0-019A82D223A1

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 200597F0-5D0C-4153-88D0-019A82D223A1
Date Sent: 11/18/2015

SSO Bypass Upset Unpermitted Discharge
Facility Permit Number: AR0021750
Date Overflow Began: 11-17-2015
Date Overflow Ended: 11-17-2015
Location: So. 66th & Kinkead Basin S001 Overflow@ MH#0015

Facility name: Massard WWTP
Time: 10:20 am
Time: 4:20 pm

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
Lift Station Overflow
Main Line Overflow
Service Line Overflow
Other Overflow Type:

(Enter overflow type if not listed)

Volume:

99000

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
Roots
Grease
Debris
Equipment Failure
Construction
Vandalism
Power Failure
Line Failure/Break
Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
Disinfected and Deodorized
Jet-Vac
Hydro Cleaned
Hand rodded
Spread Lime on Affected Area
Used Generator To Power Pumps/Equipment
Public Notification
Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
NEAH - No Evidence of Adverse Health/Environmental Impact
OEEI - Observed or Evidence of Environmental Impact
EFK - Evidence of Fish Kill

Reported By Steve Floyd

Title Supt

Telephone Number (479) 784-2331

Additional Comments if Needed:

clean up scheduled

Email a Copy of This Report to the Email Address: sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

B1810596-43CF-4131-B535-D79A863A56AC

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: B1810596-43CF-4131-B535-D79A863A56AC

Date Sent: 11/18/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0021750

11-17-2015

11-18-2015

1601 So. 74th Basin RL01 Overflow@ MH# 0670

Facility name:

Time:

Time:

Massard WWTP

9:52 am

8:35 am

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 272800

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt**

Telephone Number **(479) 784-2331**

Additional Comments if Needed:

clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

DFA4001E-4396-4D2D-900D-CFE47C88D95E

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: DFA4001E-4396-4D2D-900D-CFE47C88D95E
Date Sent: 11/18/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number: **AR0021750**
 Date Overflow Began: **11-17-2015**
 Date Overflow Ended: **11-18-2015**
 Location:

Facility name: **Massard WWTP**
 Time: **10:00 am**
 Time: **8:30 am**

#9 Riverlyn Terrace Overflow@ MH # 0140

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 270000

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 784-2331**

Additional Comments if Needed:

clean up scheduled

Email a Copy of This Report to the Email Address:
sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

65A5E065-726B-4828-BDAA-4238E16A397A

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 65A5E065-726B-4828-BDAA-4238E16A397A
Date Sent: 11/18/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number: **AR0033278**
 Date Overflow Began: **11-17-2015**
 Date Overflow Ended: **11-18-2015**
 Location:

Facility name: **P Street WWTP**
 Time: **9:30 am**
 Time: **8:00 am**

528 N 31st Street Basin P008- USMH 1300, DSMH 1290 Overflow occurred at open trench during main repair.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 405000

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OE EI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt**

Telephone Number **(479) 784-2331**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

CF07D7C9-9C03-43B0-80C5-075F37C0D3D2

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: CF07D7C9-9C03-43B0-80C5-075F37C0D3D2

Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard WWTP

Date Overflow Began:

11-17-2015

Time:

9:44 am

Date Overflow Ended:

11-17-2015

Time:

4:45 pm

Location:

1801 So. 74th St. Basin RL01 Overflow @ MH #1060

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, stor

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

63150

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number **(479) 784-2331**

Additional Comments if Needed:

Clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

B7850908-2697-4D83-A1E9-BF27D4E08D5A

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: B7850908-2697-4D83-A1E9-BF27D4E08D5A

Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard WWTP

Date Overflow Began:

11-17-2015

Time:

9:30 am

Date Overflow Ended:

11-17-2015

Time:

4:50 pm

Location:

So. 74th Street Basin RL01 Overflow @ MH #1070

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, stor

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

44000

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number **(479) 461-0914**

Additional Comments if Needed:

Clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

D43F4E7F-BBFC-4C00-A8EB-430DC7E5A334

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: D43F4E7F-BBFC-4C00-A8EB-430DC7E5A334

Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard WWTP

Date Overflow Began:

11-17-2015

Time:

9:36 am

Date Overflow Ended:

11-17-2015

Time:

4:55 pm

Location:

7400 Euper Ln. Basin RL01 Overflow @ MH #1072

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, stor

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

43900

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEL - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number **(479) 461-0914**

Additional Comments if Needed:

Clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

3C41EBA9-3DE2-4F3A-81A4-7A0A5A8D6F10

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 3C41EBA9-3DE2-4F3A-81A4-7A0A5A8D6F10

Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number: AR0021750 Facility name: Massard WWTP
Date Overflow Began: 11-17-2015 Time: 9:20 am
Date Overflow Ended: 11-17-2015 Time: 5:20 pm
Location: South 56th & Rogers Ave Basin S004-Overflow@ MH 1140

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, stor

Type of Overflow

- (x) Manhole Overflow
() Lift Station Overflow
() Main Line Overflow
() Service Line Overflow
() Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- (x) I & I - Rainfall
() Roots
() Grease
() Debris
() Equipment Failure
() Construction
() Vandalism
() Power Failure
() Line Failure/Break
() Other Cause:

Volume: 120000

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- () Machine rodded () Disinfected and Deodorized
() Jet-Vac () Hydro Cleaned
() Hand rodded () Spread Lime on Affected Area
() Used Generator To Power Pumps/Equipment () Public Notification
() Other: Describe

Environmental Damage

- () OEHC - Observed or Evidence of Human Contact (x) NEAH - No Evidence of Adverse Health/Environmental Impact
() OE EI - Observed or Evidence of Environmental Impact () EFK - Evidence of Fish Kill

Reported By Steve Floyd Title Supt. Telephone Number (479) 461-0914

Additional Comments if Needed:

Clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

E3E5E5E0-4BA0-4DE0-A7B7-99A3D0F18005

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: E3E5E5E0-4BA0-4DE0-A7B7-99A3D0F18005

Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street WWTP

Date Overflow Began:

11-17-2015

Time:

8:50 am

Date Overflow Ended:

11-17-2015

Time:

4:30 pm

Location:

1413 Phoenix Ave MC06-Overflow@MH 1120

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, stor

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type: _____

(Enter overflow type if not listed)

Volume:

46000

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe _____

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number **(479) 461-0914**

Additional Comments if Needed:

Clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

15E8CA62-2C63-4ECC-B4B2-EB929DE2A562

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 15E8CA62-2C63-4ECC-B4B2-EB929DE2A562

Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard WWTP

Date Overflow Began:

11-17-2015

Time:

9:20 am

Date Overflow Ended:

11-17-2015

Time:

7:00 pm

Location:

3100 Kelley Hwy S008- overflow @ MH 2000

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, stor

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

14500

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number **(479) 461-0914**

Additional Comments if Needed:

Clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

4BF70967-267D-4539-A910-C36A3FD89CAA

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 4BF70967-267D-4539-A910-C36A3FD89CAA
Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge
Facility Permit Number: AR0033278
Date Overflow Began: 11-17-2015
Date Overflow Ended: 11-17-2015
Location:

Facility name: P Street WWTP
Time: 12:50 pm
Time: 2:35 pm

2100 Towson Ave, MC02- USMH 0230, DSMH 0220 Overflow at MH 0230

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume: 525

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 461-0914**

Additional Comments if Needed:

clean up scheduled

Email a Copy of This Report to the Email Address:
sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

8989F483-1381-4127-92C6-32102FC655F3

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 8989F483-1381-4127-92C6-32102FC655F3

Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street WWTP

Date Overflow Began:

11-17-2015

Time:

1:20 pm

Date Overflow Ended:

11-17-2015

Time:

3:00 pm

Location:

8617 So. 31st Terrace Z003- USMH 1540, DSMH 1410 Backup into building.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

Manhole Overflow

Lift Station Overflow

Main Line Overflow

Service Line Overflow

Other Overflow Type: **backup into building**

(Enter overflow type if not listed)

Volume: 500

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

I & I - Rainfall

Roots

Grease

Debris

Equipment Failure

Construction

Vandalism

Power Failure

Line Failure/Break

Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

Machine rodded

Disinfected and Deodorized

Jet-Vac

Hydro Cleaned

Hand rodded

Spread Lime on Affected Area

Used Generator To Power Pumps/Equipment

Public Notification

Other: Describe

Environmental Damage

OEHC - Observed or Evidence of Human Contact

NEAH - No Evidence of Adverse Health/Environmental Impact

OEEI - Observed or Evidence of Environmental Impact

EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 461-0914**

Additional Comments if Needed:

clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

216D4894-F67B-4DC3-BDAC-3CBBAC566C97

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 216D4894-F67B-4DC3-BDAC-3CBBAC566C97

Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0033278

11-17-2015

11-17-2015

Facility name:

Time:

Time:

P Street WWTP

10:20 am

2:20 pm

2223 South S Street P006- USMH 0930, DSMH 0910 Backup into building.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type: **building backup**

(Enter overflow type if not listed)

Volume: **1250**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEET - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 461-0914**

Additional Comments if Needed:

clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

4412F43E-0DB1-4EA0-879A-03109D5B2D81

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 4412F43E-0DB1-4EA0-879A-03109D5B2D81

Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0033278

11-17-2015

11-17-2015

Facility name:

Time:

Time:

P Street WWTP

11:40 am

11:55 am

501 North 11th Street P002- USMH 1140, DSMH 1120 Backup into building due to heavy rainfall

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **15**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 461-0914**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

8B529998-C6AB-4B7A-87AD-2047C2C957B9

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 8B529998-C6AB-4B7A-87AD-2047C2C957B9

Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0033278

11-17-2015

11-17-2015

Facility name:

Time:

Time:

P Street WWTP

9:50 am

10:15 am

5100 Towson Ave. MC04 - USMH 0320, DSMH 0310 Overflow at manhole 0320

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **125**

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Public Land Only (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 461-0914**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 31B747FB-B167-4AB1-94E5-382298E0C594

Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street WWTP

Date Overflow Began:

11-16-2015

Time:

9:15 pm

Date Overflow Ended:

11-16-2015

Time:

11:00 pm

Location:

1901 Greenwood Ave. P009 - USMH 2890, DSMH 0350

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow

Other Overflow Type: **Building**

(Enter overflow type if not listed)

Volume: 1050

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river, stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Steve Floyd

Title Supt.

Telephone Number (479) 461-0914

Additional Comments if Needed:

clean up scheduled

Email a Copy of This Report to the Email Address:

floyd@fortsmithar.gov

CONFIRMATION NUMBER

41920E4D-7CC6-4CFD-AF88-5A4508A78E69

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 41920E4D-7CC6-4CFD-AF88-5A4508A78E69
Date Sent: 11/17/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
11-16-15
11-16-15

Facility name:
 Time:
 Time:

P Street WWTP
11:10 am
6:30 pm

2100 Garner Ln P009 - USMH 0490, DSMH 0480 Line Failure

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **2200**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEL - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt**

Telephone Number **(479) 461-0914**

Additional Comments if Needed:

clean up scheduled.

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

38E98C5F-7F33-4D44-8644-9D6098830FCA

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 38E98C5F-7F33-4D44-8644-9D6098830FCA

Date Sent: 11/13/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard

Date Overflow Began:

11/13/2015

Time:

10:30 am

Date Overflow Ended:

11/13/2015

Time:

10:55 am

Location:

1601 South 74th Street, RL01-0682, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

250

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 76D2D68C-F3C7-467E-B8C5-3B71AFCB4F67

Date Sent: 11/6/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard

Date Overflow Began:

11/5/2015

Time:

8:20 pm

Date Overflow Ended:

11/6/2015

Time:

2:45 am

Location:

1601 South 74th Street, RL01-0670, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

9628

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

471AD22B-19A8-4795-ABC9-BDEC1F65D54A

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 471AD22B-19A8-4795-ABC9-BDEC1F65D54A
 Date Sent: 11/6/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0021750
 11/05/2015 *JBJ*
 11/06/2015

Facility name: Massart
 Time: 7:45 pm
 Time: 9:30 pm

5600 Rogers Avenue, S004-1140, storm drain

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 1800

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEL - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

EB4572B4-CCE9-443D-8458-5E7F9E8A205B

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: EB4572B4-CCE9-443D-8458-5E7F9E8A205B
Date Sent: 11/12/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0021750
11/12/2015
11/12/2015

Facility name:
 Time:
 Time:

Massard
9:00 am
12:00 pm

2016 North 53 Street, S005-0720 to 0710, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm .

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **1800**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe **repair**
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

5BAA90D5-443C-4CD3-8C68-ADCE307AE3D8

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 5BAA90D5-443C-4CD3-8C68-ADCE307AE3D8

Date Sent: 11/6/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0021750

11/5/2015

11/5/2015

8815 Fresno Street, M001-1220 to 1080, yard

Facility name:

Time:

Time:

Massari

4:30 pm

5:00 pm

11/6/15 JBJ
11/5/15
1090 JBJ

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

150

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

81C63221-4A06-484E-83A5-91F113F1E41A

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 81C63221-4A06-484E-83A5-91F113F1E41A
Date Sent: 11/6/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
11/16/2015
11/16/2015

Facility name:
 Time:
 Time:

P Stree
6:50 an
7:45 an

1422 North 56 Terrace, S002-1590, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm .

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **550**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

ORIGIN ID:FSMA (479) 784-2330
STEVE FLOYD
CITY OF FORT SMITH
3900 KELLEY HIGHWAY
FORT SMITH, AR 72904
UNITED STATES US

SHIP DATE: 18DEC15
ACTWGT: 0.50 LB
CAD: 1731127/INET3670


BILL SENDER

TO NPDES ENFORCEMENT SECTION, WATER
ADEQ
5301 NORTSHORE DRIVE

NORTH LITTLE ROCK AR 72118

(501) 682-0638 REF:
INV: DEPT:

536J1430681D0




4157416816010101

WED - 23 DEC 4:30P
EXPRESS SAVER

TRK# 7752 4491 6808
0201

SA LITA

72118
AR-US LIT



After printing this label:

1. Use the 'Print' button on this page to print your label to your laser or inkjet printer.
2. Fold the printed page along the horizontal line.
3. Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number. Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$1,000, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written claims must be filed within strict time limits, see current FedEx Service Guide.