



January 19, 2016

Ms. Nancy Williams
EPA, Region 6
Compliance Assurance and Enforcement Division
1445 Ross Avenue
Dallas, TX 75202-2733

Re: AR0021750, Massard WWTP

Dear Ms. Williams:

The following violation was noted for the above referenced permit for December 2015.

Total Suspended Solids, Effluent Loading – 3,772 ppd, Permit Limit - 2502 ppd

No harmful effects were reported by the public or noted by utility personnel in the receiving stream.

The total monthly rainfall measured during the month of December was 10.81 inches, which is 7.20 inches above normal. The allowable monthly average mass loading for this facility is based upon a design flow of 10 mgd which provides for a permitted average mass loading of 2502 ppd. During December 2015 influent flows significantly exceeded the 10 mgd design flow for 26 days of the month. Washout of the treatment system due to high flows caused higher than normal effluent TSS levels resulting in the mass loading violation.

Should you require additional information, please contact Steve Floyd at 479-784-2331 or sfloyd@fortsmithar.gov.

Sincerely,

A handwritten signature in black ink, appearing to be "SP", written over a printed name.

Steve Parke
Director of Utilities

Pc: ADEQ, NPDES Section, Water Division
Steve Floyd, Manager, Water/Wastewater Treatment

Utility Department • 3900 Kelley Hwy.
Fort Smith, Arkansas 72904
(479) 784-2231 • FAX (479) 784-2358

Monthly SSO Report December 2015

Permit Number	Manhole Number	Location	Receiving Water	Duration Min.	Cause	Volume (Gallons)	Component	Date Overflow Started	Date Overflow Stopped	Started	Stopped	Steps Taken
AR0021750	M005-1520	7700 Rogers Avenue	Storm Drain	80	Roots, grease	1200	Manhole	12/01/2015	12/1/2015	1:00 PM	2:20 PM	
AR0021750	M002-0230 to 0220	8824 Meandering Way	creek	1	I & I Rainfall	1	Service Line	12/01/2015	12/1/2015	9:02 AM	9:02 AM	
AR0021750	HL01-0070	3100 South 105th Street	Yard	324	Roots, grease	324	Manhole	12/03/2015	12/3/2015	3:52 PM	9:16 PM	Machine Rodded, Jet-Vac
AR0021750	RL01-2110	2012 Massard Road	paved area	216	Roots	216	Manhole	12/06/2015	12/6/2015	12:15 PM	3:51 PM	Disinfected and Deodorized
AR0021750	Riley Farms Lift Station Force Main (RF01)	6707 Woodland Drive	Storm Drain	160	Line Failure/Break	320	Force Main	12/11/2015	12/11/2015	9:20 AM	12:00 PM	Repair
AR0021750	S004-1420	5600 Rogers Avenue	Storm drain	540	I & I Rainfall	108000	Manhole	12/13/2015	12/13/2015	11:50 AM	8:00 PM	
AR0021750	RL01-0670	Carol Ann Cross Park	paved area	996	I & I Rainfall	19920	Manhole	12/13/2015	12/14/2015	4:20 PM	9:56 AM	
AR0021750	RL01-1060	1801 South 74th Street	yard	1008	I & I Rainfall	20160	Manhole	12/13/2015	12/14/2015	5:10 PM	9:58 AM	
AR0021750	S009-0780	North 50th Street and Armour Street	Ditch	1256	I & I Rainfall	6290	Manhole	12/13/2015	12/14/2015	1:10 PM	9:08 AM	
AR0021750	MC01-1000 to 0990	912 South I Street	Building	150	Line Failure/Break	1500	Service Line	12/14/2015	12/14/2015	5:30 AM	8:00 AM	Jet-Vac, repaired, Disinfected and Deodorized
AR0021750	MC01-1000 to 0990	910 South 10th Street	yard	150	Line Failure/Break	1500	Service Line	12/14/2015	12/14/2015	5:30 AM	8:00 AM	Jet-Vac, repaired, Disinfected and Deodorized
AR0021750	Z004-1420	3124 Glen Flora Way	yard	90	Grease	900	Manhole	12/15/2015	12/15/2015	7:50 AM	9:10 AM	Jet-Vac, Disinfected and Deodorized
AR0021750	M003-0928 to 0924	8425 Highway 45 South	building	110	Roots, Grease	550	Service Line	12/15/2015	12/15/2015	9:00 AM	10:50 AM	Machine Rodded, Disinfected and Deodorized
AR0021750	S005-1380 to 0560	5101 Birnie Avenue	yard	60	Grease	300	Service Line	12/17/2015	12/17/2015	3:20 PM	3:30 PM	Jet-Vac, Disinfected and Deodorized
AR0021750	S007-3160 to 3150	2004 North 46 Terrace	yard	123	Roots	246	Service Line	12/24/2015	12/24/2015	3:35 PM	4:58 PM	Machine Rodded
AR0021750	S007-1130	4512 North O Street	yard	1219	I & I Rainfall	243800	Manhole	12/27/2015	12/28/2015	4:14 PM	1:33 PM	Public Notification
AR0021750	RL01-1072	7400 Euper Lane	paved area	1128	I & I Rainfall	5640	Manhole	12/27/2015	12/28/2015	5:00 PM	11:48 AM	
AR0021750	S002-1310	Sunnymede Creek	ditch	2563	I & I Rainfall	704825	Manhole	12/27/2015	12/29/2015	4:37 PM	11:20 AM	Public Notification
AR0021750	S007-1060	4905 North O Street	paved area	1276	I & I Rainfall	255200	Manhole	12/27/2015	12/28/2015	4:19 PM	1:35 PM	Public Notification
AR0021750	RL01-1070	7400 Euper Lane	storm drain	1426	I & I Rainfall	14260	Manhole	12/27/2015	12/28/2015	5:00 PM	11:46 AM	
AR0021750	Z004-0740	3125 Edinburgh Drive	yard	2716	I & I Rainfall	54326	Manhole	12/27/2015	12/29/2015	5:35 PM	9:36 AM	
AR0021750	RL01-1120	South 71st & Euper Lane	paved area/stream	2387	I & I Rainfall	230870	Manhole	12/27/2015	12/29/2015	4:58 PM	8:45 AM	
AR0021750	RL01-0670.	1601 South 74 Street	Paved are	1376	I & I Rainfall	13760	Manhole	12/27/2015	12/28/2015	5:14 PM	12:10 AM	
AR0021750	S009-0780	North 50th and Armour Avenue	paved area	1191	I & I Rainfall	59550	Manhole	12/27/2015	12/28/2015	1:52 PM	9:42 AM	Public Notification
AR0021750	S009-0712	4831 Armour Avenue	paved area	1177	I & I Rainfall	117700	Manhole	12/27/2015	12/28/2015	1:55 PM	9:32 AM	Public Notification
AR0021750	RL01-0140	#9 Riverlyn Terrace	yard	915	I & I Rainfall	18300	Manhole	12/27/2015	12/28/2015	5:30 PM	8:45 AM	
AR0021750	RL01-1060	1801 South 74th Street	yard	1126	I & I Rainfall	11260	Manhole	12/27/2015	12/28/2015	5:09 PM	11:55 AM	initially reported at MH RL01-1060
AR0021750	S004-1140	South 56th and Rogers	stream	2019	I & I Rainfall	100950	Manhole	12/27/2015	12/29/2015	10:30 AM	8:09 AM	
AR0021750	RL01-1280	2116 South 70th Street	yard	1165	I & I Rainfall	11650	Manhole	12/27/2015	12/28/2015	4:55 PM	12:20 PM	
AR0021750	RL01-1080	1801 South 74th Street	yard	1126	I & I Rainfall	11260	Manhole	12/27/2015	12/28/2015	5:09 PM	11:55 AM	
AR0021750	RL01-1080	2000 South 74th Street	Paved area	1424	I & I Rainfall	7120	Manhole	12/27/2015	12/28/2015	5:00 PM	11:44 AM	
AR0021750	S007-0710	3916 Morris Drive	yard	1068	I & I Rainfall	106800	Manhole	12/27/2015	12/28/2015	4:11 PM	9:59 AM	
AR0021750	RL01-0680	1601 South 74th Street	Yard	2359	I & I Rainfall	23580	Manhole	12/27/2015	12/29/2015	5:11 PM	8:29 AM	

Monthly SSO Report December 2015

AR0021750	S006-1390	212 North 49th Street	Ditch	34	Roots, Grease	510	Manhole	12/28/2015	12/28/2015	3:36 PM	4:10 PM	Machine Rodded
AR0021750	S007-0450	1728 North Albert Pike Avenue	Ditch	30	Roots	150	Service Line	12/31/2015	12/31/2015	5:00 PM	5:25 PM	Machine Rodded, Disinfected and Deodorized
TOTAL					35	2152938						
AR0033278	P011-2600 to 2590	1820 South C Street	yard	740	Grease	740	Service Line	12/01/2015	12/1/2015	9:45 AM	10:22 AM	Jet-Vac, Disinfected and Deodorized
AR0033278	HL01-0070	3100 South 105th Street	yard	324	Roots	324	Manhole	12/03/2015	12/4/2015	3:52 PM	9:16 PM	Machine Rodded, Jet-Vac, Disinfected and Deodorized
AR0033278	Z007-0430	127 Perth Court	paved area	145	Grease	145	Manhole	12/03/2015	12/3/2015	7:45 PM	7:45 PM	Machine Rodded, Disinfected and Deodorized
AR0033278	MC03-0260 to 0240	2412 Towson Avenue	Storm Drain	64	Line Failure/Break	1600	Mainline	12/03/2015	12/3/2015	8:15 AM	9:19 AM	Machine rodded
AR0033278	MC03-0580	1000 Cartage Street	Storm Drain	1	I & I Rainfall	1	Manhole	12/04/2015	12/4/2015	9:26 AM	9:26 AM	
AR0033278	RL01-0682	1601 South 74th Street	Strom Drain	50	Roots, grease	250	Manhole	12/04/2015	12/4/2015	9:25 AM	10:15 AM	Public Notification
AR0033278	Z001-3520 to 0510	1924 Zero Street	yard	50	Grease	50	Service Line	12/05/2015	12/5/2015	3:55 PM	4:45 PM	Disinfected and Deodorized
AR0033278	P008-2840 to 2834	1514 Hendricks Blvd.	yard	1282	Line Failure/Break	1282	Service Line	12/07/2015	12/8/2015	3:45 PM	1:07 PM	Disinfected and Deodorized
AR0033278	P007-0482	3700 Kinkead Avenue	yard	1102	I & I Rainfall	27550	Manhole	12/13/2015	12/14/2015	3:55 PM	9:17 AM	
AR0033278	P005-0050	1425 North 34th Street	creek	1229	I & I Rainfall	6145	Manhole	12/13/2015	12/14/2015	1:47 PM	9:17 AM	
AR0033278	P005-3030	3200 North M Street	creek	1246	I & I Rainfall	31150	Manhole	12/13/2015	12/14/2015	1:33 PM	9:10 AM	
AR0033278	P007-2040	4221 Park Avenue	yard	1031	I & I Rainfall	5155	Manhole	12/13/2015	12/14/2015	4:09 PM	9:20 AM	
AR0033278	P005-0060	1412 North 34th Street	yard	1234	I & I Rainfall	30850	Manhole	12/13/2015	12/14/2015	1:41 PM	9:14 AM	
AR0033278	Z001-0540 to 0530	1806 Zero Street	paved area	34	Roots, grease	68	Service Line	12/14/2015	12/14/2015	12:16 PM	12:50 PM	
AR0033278	P008-3100 to 2090	3400 South M Street	yard	30	Roots	300	Mainline	12/14/2015	12/14/2015	12:15 PM	12:45 PM	
AR0033278	P006-2350	1622 South 28th Street	storm drain	16	Roots, grease, debris	36	Manhole	12/14/2015	12/14/2015	1:00 PM	1:18 PM	Machine Rodded
AR0033278	P005-0220 to 0210	1501 May Avenue	yard	180	Grease	1800	Service Line	12/15/2015	12/15/2015	9:30 AM	12:30 PM	Jet-Vac Disinfected and Deodorized
AR0033278	FL01-0340 to 0350	3417 Santa Fe Street	yard	104	Grease	208	Service Line	12/22/2015	12/22/2015	6:13 PM	7:57 PM	Machine Rodded
AR0033278	P006-0380 to 0360	1319 South 17th Street	stream	3334	I & I Rainfall	330304	Service Line	12/27/2015	12/29/2015	2:30 PM	10:04 PM	
AR0033278	P007-2070	4221 Park Avenue	yard	1274	I & I Rainfall	254800	Manhole	12/27/2015	12/28/2015	3:26 PM	12:40 PM	Public Notification
AR0033278	MH P005-3030	3200 North M Street	paved area/river	2663	I & I Rainfall	732325	Manhole	12/27/2015	12/29/2015	2:20 PM	10:43 AM	Public Notification
AR0033278	P005-1390	1018 North 18th Street	paved area	1410	I & I Rainfall	141000	Manhole	12/27/2015	12/28/2015	3:10 PM	10:40 AM	Public Notification
AR0033278	P007-0314	North 37th and North J Street	yard	1368	I & I Rainfall	68400	Manhole	12/27/2015	12/28/2015	2:38 PM	1:26 PM	Public Notification
AR0033278	P005-1750	722 N. 20th Street	paved area	1420	I & I Rainfall	14200	Manhole	12/27/2015	12/28/2015	3:25 PM	3:05 PM	
AR0033278	P007-1880	4110 Kinkead Avenue	yard	1430	I & I Rainfall	35750	Manhole	12/27/2015	12/28/2015	3:08 PM	3:00 PM	
AR0033278	P007-0316	1201 North 37th Street	yard	1348	I & I Rainfall	269600	Manhole	12/27/2015	12/28/2015	2:40 PM	1:08 PM	Public Notification
AR0033278	MC01-0100	301 South U Street	yard	1382	I & I Rainfall	138200	Manhole	12/27/2015	12/28/2015	6:22 PM	5:20 PM	
AR0033278	P007-0050	1425 North 34th Street	yard/river	2667	I & I Rainfall	533400	Manhole	12/27/2015	12/29/2015	2:23 PM	10:50 AM	Public Notification
AR0033278	P005-1520	1013 North 18th Street	yard/river	2607	I & I Rainfall	391050	Manhole	12/27/2015	12/29/2015	3:08 PM	10:35 AM	Public Notification

Monthly SSO Report December 2015

AR0033278	P007-0060	1412 North 34th Street	yard	2668	I & I Rainfall	400200	Manhole	12/27/2015	12/29/2015	2:26 PM	10:54 AM	Public Notification
AR0033278	MH P006-0370 to 0360	1307 South 17th Street	yard	2837	I & I Rainfall	140185	Service Line	12/27/2015	12/29/2015	10:59 AM	10:16 AM	
AR0033278	P004-2190	Kelley Highway and North 31st Street	paved area	1153	I & I Rainfall	230600	Manhole	12/27/2015	12/28/2015	2:05 PM	9:18 PM	Public Notification
AR0033278	MC07-0430 to 0420	4608 South 25th Street	yard	1251	I & I Rainfall	12510	Service Line	12/27/2015	12/28/2015	1:09 PM	10:00 AM	
AR0033278	P004-0380 to 0370	2004 North 13th Street	yard	1188	I & I Rainfall	11880	Service Line	12/27/2015	12/28/2015	2:42 PM	10:30 AM	
AR0033278	P007-1550	1124 North 40th Street	paved area	1350	I & I Rainfall	202500	Manhole	12/27/2015	12/28/2015	2:45 PM	1:15 PM	Public Notification
AR0033278	MC06-1040 to 0990	5410 South 17th Street	yard	1415	I & I Rainfall	14150	Service Line	12/27/2015	12/28/2015	2:05 PM	1:40 PM	
AR0033278	P007-0065	1410 North 34th Street	yard	2671	I & I Rainfall	734525	Manhole	12/27/2015	12/29/2015	2:27 PM	10:58 PM	Public Notification
AR0033278	P007-0482	3700 Kinkaid Avenue	yard	1256	I & I Rainfall	345400	Manhole	12/27/2015	12/28/2015	3:37 PM	12:56 PM	Public Notification
AR0033278	P009-0200	Old Greenwood Road and South P Street	storm drain	1273	I & I Rainfall	127300	Manhole	12/27/2015	12/28/2015	5:40 PM	2:53 PM	
AR0033278	P009-0820	1801 Old Greenwood Road	ditch	1264	I & I Rainfall	18960	Manhole	12/27/2015	12/28/2015	5:52 PM	2:57 PM	
AR0033278	MC03-0630	Wheeler Avenue and Fresno Street	storm drain	1135	I & I Rainfall	11350	Manhole	12/27/2015	12/28/2015	8:30 PM	3:25 PM	
AR0033278	P009-1350	North 19th and North L Street	paved area river & stream	2719	I & I Rainfall	270190	Manhole	12/27/2015	12/29/2015	1:10 PM	10:29 AM	
AR0033278	MC03-0582	1000 Carthage Avenue	Ditch	1367	I & I Rainfall	683500	Manhole	12/27/2015	12/28/2015	4:22 PM	3:09 PM	Public Notification
AR0033278	P005-1410 to 1400	1906 North K Street	yard	20	I & I Rainfall	510	Service Line	12/28/2015	12/28/2015	12:55 PM	1:15 PM	Machine Rodded
AR0033278	Z007-0440	127 Perth Court	Storm Drain	10	Roots, Grease	40	Manhole	12/30/2015	12/30/2015	10:20 AM	10:30 AM	Machine Rodded
AR0033278	MC01-0080	South U Street and State Line Road	creek	3301	I & I Rainfall	16505	Manhole	12/31/2015	1/2/2016	8:59 AM	4:00 PM	
AR0033278	P007-1180	3804- Free Ferry Road	yard	110	Roots	1100	Manhole	12/30/2015	12/30/2015	6:59 PM	8:48 PM	Remove roots from manhole by hand
TOTAL					47	6238088						

CONFIRMATION NUMBER

E725DACB-F897-4F17-90C7-D8704E1E3B73

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: E725DACB-F897-4F17-90C7-D8704E1E3B73
Date Sent: 12/1/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0021750
12/1/2015
12/1/2015

Facility name:
 Time:
 Time:

Massard
1:00 pm
2:20 pm

7700 Rogers Avenue, M005-1520, Storm Drain

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **1200**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: C5D9708C-611F-442F-BB30-49F01F1D9987

Date Sent: 12/6/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard

Date Overflow Began:

12/6/2015

Time:

12:15 pm

Date Overflow Ended:

12/6/2015

Time:

3:51 pm

Location:

2012 Massard Road, RL01-2110, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

216

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

E6962A19-D369-4C49-ADFA-B5CDFD204B20

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: E6962A19-D369-4C49-ADFA-B5CDFD204B20

Date Sent: 12/11/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0021750

12/11/2015

12/11/2015

Facility name:

Time:

Time:

Massard

9:20 am

12:00 pm

6707 Woodland Drive, Riley Farms Lift Station Force Main (RF01), Storm Drain

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
 Lift Station Overflow
 Main Line Overflow
 Service Line Overflow
 Other Overflow Type: Force Main

(Enter overflow type if not listed)

Volume: 320

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
 Roots
 Grease
 Debris
 Equipment Failure
 Construction
 Vandalism
 Power Failure
 Line Failure/Break
 Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
 Jet-Vac Hydro Cleaned
 Hand rodded Spread Lime on Affected Area
 Used Generator To Power Pumps/Equipment Public Notification
 Other: Describe repair

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
 OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

This List Station has to force mains. The other force main will be used until repair is completed. Clean up is Scheduled.

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

04EFB439-AD5A-451D-85CB-8A44FF9B9F57

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 04EFB439-AD5A-451D-85CB-8A44FF9B9F57
Date Sent: 12/14/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0021750
12/13/2015
12/13/2015

Facility name:
 Time:
 Time:

Massard
11:50 am
8:00 pm

5600 Rogers Avenue, S004-1420, Storm drain

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 108000

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

9823CAE1-A092-499A-B373-C96BBF195182

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 9823CAE1-A092-499A-B373-C96BBF195182
Date Sent: 12/14/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massart

Date Overflow Began:

12/13/2015

Time:

5:20 pm

Date Overflow Ended:

12/14/2015

Time:

9:56 am

Location:

Carol Ann Cross Park, RL01-0670, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 19920

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

0136BC3B-954B-4800-998D-8310D33F038C

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 0136BC3B-954B-4800-998D-8310D33F038C
Date Sent: 12/14/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0021750
12/13/2015
12/14/2015

Facility name:
 Time:
 Time:

Massar
5:10 pm
9:58 am

1801 South 74th Street, RL01-1060, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **20,160**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

AD48849C-E9AF-48E8-9073-5920D8CACB66

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: AD48849C-E9AF-48E8-9073-5920D8CACB66

Date Sent: 12/14/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0021750
12/13/2015
12/14/2015

Facility name:
 Time:
 Time:

Massari
1:10 pm
9:08 am

North 50th Street and Armour Street, S009-0780, Ditch

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 6290

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

24A74A8C-2FB2-4640-A77E-DDD6CF1F38AD

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 24A74A8C-2FB2-4640-A77E-DDD6CF1F38AD

Date Sent: 12/14/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0021750

12/14/2015

12/14/2015

Facility name:

Time:

Time:

Massar

5:30 am

8:00 am

910 South 10th Street, MC01-1000 to 0990, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

1500

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I-& I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

repair

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

F639B4F4-7BCA-4C41-9EE8-1BC680D819F4

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: F639B4F4-7BCA-4C41-9EE8-1BC680D819F4
Date Sent: 12/15/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0021750
12/15/2015
12/15/2015
3124 Glen Flora Way, Z004-1420, yard

Facility name: **Massart**
 Time: **7:50 am**
 Time: **9:10 am**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 900

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

4CE28590-91DB-454E-96E4-C066A7622052

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 4CE28590-91DB-454E-96E4-C066A7622052

Date Sent: 12/15/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0021750

12/15/2015

12/15/2015

8425 Highway 45 South, M003-0928 to 0924, building

Facility name:

Time:

Time:

Massard

9:00 am

11:00 am

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm .

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

550

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

A4FBE96B-0C08-479E-A99D-B3EFBF0C4DAE

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: A4FBE96B-0C08-479E-A99D-B3EFBF0C4DAE
Date Sent: 12/18/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0021750
12/17/2015
12/17/2015

Facility name:
 Time:
 Time:

Massari
2:30 pm
3:30 pm

5101 Birnie Avenue, S005-1380 to 0560, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **300**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 3A3E56CD-E04D-4786-B6C1-D13C6286187C

Date Sent: 12/24/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard

Date Overflow Began:

12/24/2015

Time:

3:35 pm

Date Overflow Ended:

12/24/2015

Time:

4:58 pm

Location:

2004 North 46 Terrace, S007-3160 to 3150, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

246

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

4E14DA03-8407-4B50-B9A3-98F8238DBAE3

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 4E14DA03-8407-4B50-B9A3-98F8238DBAE3
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0021750
12/27/2015
12/28/2015

Facility name: **Massart**
 Time: **4:14 pm**
 Time: **1:33 pm**

4512 North.O Street, S007-1130, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm .

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 243800

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

2CB86DD0-17AB-4456-80A6-A995F408167D

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 2CB86DD0-17AB-4456-80A6-A995F408167D

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard

Date Overflow Began:

12/27/2015

Time:

5:00 pm

Date Overflow Ended:

12/28/2015

Time:

11:48 am

Location:

7400 Euper Lane, RL01-1072, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

5640

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

B948C76F-5D11-4FC6-9303-27DD24F15222

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: B948C76F-5D11-4FC6-9303-27DD24F15222
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR002
12/27/2015

Facility name:
 Time:
 Time:

Massari
4:37 pm

Sunnymede Creek, S002-1310, ditch

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & T).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

This overflow is still active.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

A1AD0B63-3693-48D4-A847-6EE19B3D5AB4

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: A1AD0B63-3693-48D4-A847-6EE19B3D5AB4

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massari

Date Overflow Began:

12/27/2015

Time:

4:19 pm

Date Overflow Ended:

12/28/2015

Time:

1:35 pm

Location:

4905 North O Street, S007-1060, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 255200

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OBEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments If Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

1CA349B0-3D30-4EFE-B27D-C02925C1118F

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 1CA349B0-3D30-4EFE-B27D-C02925C1118F
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0021750
12/27/2015
12/28/2015

Facility name:
 Time:
 Time:

Massard
5:00 pm
11:46 am

7400 Euper Lane, RL01-1070, storm drain

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **14260**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

1AAC70DD-795C-477D-BD4B-7C6D2196D53B

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 1AAC70DD-795C-477D-BD4B-7C6D2196D53B

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massarr

Date Overflow Began:

12/27/2015

Time:

4:25 pm

Date Overflow Ended:

Time:

Location:

3125 Edinburgh Drive, Z004-0740, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OE EI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

This overflow is still active.

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 2DFA8337-F5E7-49E8-8ACD-6859A004609A

Date Sent: 12/28/2015

 SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR002 1750
12/27/2015

Facility name:

Massard

Date Overflow Began:

Time:

4:58 pm

Date Overflow Ended:

Time:

Location:

~~7400~~ Euper Lane, RL01-1120, paved area
South 71st JBT

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
 Lift Station Overflow
 Main Line Overflow
 Service Line Overflow
 Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river, stream)

Cause of Overflow

- I & I - Rainfall
 Roots
 Grease
 Debris
 Equipment Failure
 Construction
 Vandalism
 Power Failure
 Line Failure/Break
 Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
 Jet-Vac Hydro Cleaned
 Hand rodded Spread Lime on Affected Area
 Used Generator To Power Pumps/Equipment Public Notification
 Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
 OEEL - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

This overflow is still active.

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

152E4B4F-1C6E-4051-BD2C-0D4136A183E6

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 152E4B4F-1C6E-4051-BD2C-0D4136A183E6

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard

Date Overflow Began:

12/27/2015

Time:

5:14 pm

Date Overflow Ended:

12/28/2015

Time:

12:10 am

Location:

1601 South 74 Street, RL01-0670.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

13760

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

0DED1D06-4106-4336-B885-077FD7482030

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 0DED1D06-4106-4336-B885-077FD7482030
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
Facility Permit Number:
Date Overflow Began:
Date Overflow Ended:
Location:

AR0021750
12/27/2015
12/28/2015

Facility name:
Time:
Time:

Massar
1:52 pm
9:43 pm

North 50th and Armour Avenue, S009-0780, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **59550**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

CFB6810C-1BE5-40C0-A9B7-A74450A476FC

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: CFB6810C-1BE5-40C0-A9B7-A74450A476FC
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
Facility Permit Number:
Date Overflow Began:
Date Overflow Ended:
Location:

AR0021750
12/27/2015
12/28/2015

Facility name:
Time:
Time:

Massar
1:55 pm
9:32 am

4831 Armour Avenue, S009-0712, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 117700

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

21246E05-80A5-47BC-AD29-D26514729A57

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 21246E05-80A5-47BC-AD29-D26514729A57
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
Facility Permit Number: **AR0021750**
Date Overflow Began: **12/27/2015**
Date Overflow Ended: **12/28/2015**
Location: **#9 Riverlyn Terrace, RL01-0140, yard**

Facility name: **Massarr**
Time: **5:30 pm**
Time: **3:09 pm**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume:

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

This overflow is still active.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

33A5DDE7-42EE-4C52-929A-F8988F80E006

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 33A5DDE7-42EE-4C52-929A-F8988F80E006
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0021750
12/27/2015
12/28/2015

Facility name: **Massard**
 Time: **5:09 pm**
 Time: **11:55 am**

1801 South 74th Street, RL01-1080, yard
1060 JBJ

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 11260

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

594F40B5-1100-4B04-8EC6-13F028D31D56

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 594F40B5-1100-4B04-8EC6-13F028D31D56
 Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0021750
12/27/2015

Facility name:
 Time:
 Time:

Massard
10:31 am

South 56th and Rogers, S004-1140,

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Over flow is still active.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

3CD67082-4ED2-447B-A0D2-7EA912AB0858

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 3CD67082-4ED2-447B-A0D2-7EA912AB0858
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:	AR0021750	Facility name:	Massard
Date Overflow Began:	12/27/2015	Time:	4:55 pm
Date Overflow Ended:	12/28/2015	Time:	12:20 pm
Location:	2116 South 70th Street, RL01-1280, yard		

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **11650**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- | | |
|--|---|
| <input type="checkbox"/> Machine rodded | <input type="checkbox"/> Disinfected and Deodorized |
| <input type="checkbox"/> Jet-Vac | <input type="checkbox"/> Hydro Cleaned |
| <input type="checkbox"/> Hand rodded | <input type="checkbox"/> Spread Lime on Affected Area |
| <input type="checkbox"/> Used Generator To Power Pumps/Equipment | <input type="checkbox"/> Public Notification |
| <input type="checkbox"/> Other: Describe | |

Environmental Damage

- | | |
|--|---|
| <input type="checkbox"/> OEHC - Observed or Evidence of Human Contact | <input checked="" type="checkbox"/> NEAH - No Evidence of Adverse Health/Environmental Impact |
| <input type="checkbox"/> OEEI - Observed or Evidence of Environmental Impact | <input type="checkbox"/> EFK - Evidence of Fish Kill |

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

15-0589

SSO ID#: 33A5DDE7-42EE-4C52-929A-F8988F80E006

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:	AR0021750	Facility name:	Massard
Date Overflow Began:	12/27/2015	Time:	5:09 pm
Date Overflow Ended:	12/28/2015	Time:	11:55 am
Location:	1801 South 74th Street, RL01-1080, yard		

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 11260

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

[Empty box for additional comments]

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

5076C73F-D495-4ACB-80B2-2C99B9B0E0A7

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 5076C73F-D495-4ACB-80B2-2C99B9B0E0A7

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard

Date Overflow Began:

12/27/2015

Time:

5:00 pm

Date Overflow Ended:

12/28/2015

Time:

11:44 am

Location:

2000 South 74th Street, RL01-1080, Paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume:

7120

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

84216659-794B-45D2-AF90-07EC21865362

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 84216659-794B-45D2-AF90-07EC21865362

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massarr

Date Overflow Began:

12/27/2015

Time:

4:11 pm

Date Overflow Ended:

12/28/2015

Time:

9:59 am

Location:

3916 Morris Drive, S007-0710, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

106800

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

C38F8B32-BCB7-407D-A4F1-8A96DAFCC572

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: C38F8B32-BCB7-407D-A4F1-8A96DAFCC572

Date Sent: 12/30/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massari

Date Overflow Began:

12/27/2015

Time:

5:11 pm

Date Overflow Ended:

12/29/2015

Time:

8:29 am

Location:

1601 South 74th Street, RL01-0680, Yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

23580

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

No confirmation for this overflow on ADEQ web site. So it is being resubmitted.

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

90329085-10CA-471D-83F0-0D9FA16FD22E

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 90329085-10CA-471D-83F0-0D9FA16FD22E
Date Sent: 12/29/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0021750
12/28/2015
12/28/2015

Facility name:
 Time:
 Time:

Massar
3:36 pm
4:10 pm

212 North 49th Street, S006-1390, Ditch

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **510**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OE EI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

15-0604

24-Hour Sanitary Sewer Overflow Report

SSO ID#: E972591B-0B62-4EE0-8F9A-1F78B14A9E8D

Date Sent: 1/1/2016

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard

Date Overflow Began:

12/31/2015

Time:

5:00 pm

Date Overflow Ended:

12/31/2015

Time:

6:25 pm

Location:

1728 North Albert Pike Avenue, S007-0450. ditch

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

150

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

[Empty box for additional comments]

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

C49BC933-A40A-41B4-BAE9-2BD33C1D1918

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: C49BC933-A40A-41B4-BAE9-2BD33C1D1918

Date Sent: 12/1/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

12/1/2015

Time:

9:45 am

Date Overflow Ended:

12/1/2015

Time:

10:22 am

Location:

1820 South C Street, P011-2600 to 2590, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

740

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

15-0509

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 3555E52E-D96B-45E9-9A55-2188557F3BE8

Date Sent: 12/4/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

12/3/2015

Time:

3:52 pm

Date Overflow Ended:

12/4/2015

Time:

9:16 pm

Location:

3100 South 105th Street, HL01-0070, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

324

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

36AE8D1E-7170-44AE-8F86-09C1ACEF87E7

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 36AE8D1E-7170-44AE-8F86-09C1ACEF87E7

Date Sent: 12/4/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

12/3/2015

Time:

5:20 pm

Date Overflow Ended:

12/3/2015

Time:

7:45 pm

Location:

127 Perth Court, 2007-0430, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

145

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

E8101333-6674-4A7A-8F84-E4A2CD66503C

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: E8101333-6674-4A7A-8F84-E4A2CD66503C
Date Sent: 12/4/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
12/3/2015
12/3/2015

Facility name:
 Time:
 Time:

P Street
8:15 am
9:19 am

2412 Towson Avenue, MC03-0260 to 0240, Storm Drain

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm .

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **1600**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe **line to be repaired**

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

0486126C-7612-4ECE-ACC9-997ECEC108D5

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 0486126C-7612-4ECE-ACC9-997ECEC108D5
Date Sent: 12/4/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:	AR0033278	Facility name:	P Street
Date Overflow Began:	12/4/2015	Time:	9:26 am
Date Overflow Ended:	12/4/2015	Time:	9:26 am
Location:	1000 Cartage Street, MC03-0580, Storm Drain		

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **1**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- | | |
|--|---|
| <input type="checkbox"/> Machine rodded | <input type="checkbox"/> Disinfected and Deodorized |
| <input type="checkbox"/> Jet-Vac | <input type="checkbox"/> Hydro Cleaned |
| <input type="checkbox"/> Hand rodded | <input type="checkbox"/> Spread Lime on Affected Area |
| <input type="checkbox"/> Used Generator To Power Pumps/Equipment | <input type="checkbox"/> Public Notification |
| <input type="checkbox"/> Other: Describe | |

Environmental Damage

- | | |
|---|---|
| <input type="checkbox"/> OEHC - Observed or Evidence of Human Contact | <input checked="" type="checkbox"/> NEAH - No Evidence of Adverse Health/Environmental Impact |
| <input type="checkbox"/> OE EI - Observed or Evidence of Environmental Impact | <input type="checkbox"/> EFK - Evidence of Fish Kill |

Reported By **Jimmie B. Johnson** Title **Deputy Director of Systems** Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Crew found evidence of overflow that most likely occurred during the rain storm on 11/29-30/2015.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

15-0511

CONFIRMATION NUMBER

D270E6A4-C145-4CC6-8C9F-C23C8E0B0D5E

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: D270E6A4-C145-4CC6-8C9F-C23C8E0B0D5E
Date Sent: 12/4/2015

SSO Bypass Upset Unpermitted Discharge
Facility Permit Number:
Date Overflow Began:
Date Overflow Ended:
Location:

AR0033278
12/4/2015
12/4/2015

Facility name:
Time:
Time:

P Street
9:25 am
10:15 am

1601 South 74th Street, RL01-0682, Strom Drain

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

250

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: EC29F4D1-574E-4AC0-B182-B9994225BF60

Date Sent: 12/6/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:	AR0033278	Facility name:	P Street
Date Overflow Began:	12/5/2015	Time:	3:55 pm
Date Overflow Ended:	12/5/2015	Time:	4:45 pm
Location:	1924 Zero Street, Z001-3520 to 0510, yard		

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

50

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

D5B7F0A7-B5BE-47C4-9F95-B6E56F126A61

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: D5B7F0A7-B5BE-47C4-9F95-B6E56F126A61

Date Sent: 12/8/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number: **AR0033278**
 Date Overflow Began: **12/7/2015**
 Date Overflow Ended: **12/8/2015**
 Location:

Facility name: **P Street WWTP**
 Time: **3:45 pm**
 Time: **1:07 pm**

1514 Hendricks Blvd. Basin: P008 USMH: 2840 DSMH: 2834 Clean Out Overflow caused by main line failure.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume: **1282**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

line repaired

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Superintendent**

Telephone Number **(479) 784-2331**

Additional Comments If Needed:

Immediate clean up.

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

F3A44216-CAA8-48CA-A0A7-410EBD3FC5EF

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: F3A44216-CAA8-48CA-A0A7-410EBD3FC5EF

Date Sent: 12/14/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

12/13/2015

Time:

3:55 pm

Date Overflow Ended:

12/14/2015

Time:

9:17 am

Location:

3700 Kinkead Avenue, P007-0482, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

27550

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

31191624-F083-4449-9B85-02693E26883B

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 31191624-F083-4449-9B85-02693E26883B

Date Sent: 12/14/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

12/13/2015

Time:

1:47 pm

Date Overflow Ended:

12/14/2015

Time:

9:17 am

Location:

1425 North 35th Street, P005-0050, creek

Y J&J

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

6145

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & J).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

1EBEE20E-428F-487E-903C-E8FACB75E7DE

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 1EBEE20E-428F-487E-903C-E8FACB75E7DE

Date Sent: 12/14/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

12/13/2015

Time:

1:33 pm

Date Overflow Ended:

12/14/2015

Time:

9:13 am

Location:

3200 North M Street, P005-3030, creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

31,150

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

EAFBFCF5-A516-4109-AB27-DEFACF99B73E

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: EAFBFCF5-A516-4109-AB27-DEFACF99B73E
Date Sent: 12/14/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
12/13/2015
12/14/2015

Facility name: **P Stree**
 Time: **4:09 pm**
 Time: **9:20 an**

4221 Park Avenue, P007-2040, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 5155

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

207E2733-2FA5-4EB8-A42F-359BAEBDBEF8

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 207E2733-2FA5-4EB8-A42F-359BAEBDBEF8
Date Sent: 12/14/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:	AR0033278	Facility name:	P Stree
Date Overflow Began:	12/13/2015	Time:	1:41 pm
Date Overflow Ended:	12/14/2015	Time:	9:14 am
Location:	1412 North 34th Street, P005-0060, yard		

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **30850**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- | | |
|--|---|
| <input type="checkbox"/> Machine rodded | <input type="checkbox"/> Disinfected and Deodorized |
| <input type="checkbox"/> Jet-Vac | <input type="checkbox"/> Hydro Cleaned |
| <input type="checkbox"/> Hand rodded | <input type="checkbox"/> Spread Lime on Affected Area |
| <input type="checkbox"/> Used Generator To Power Pumps/Equipment | <input type="checkbox"/> Public Notification |
| <input type="checkbox"/> Other: Describe | |

Environmental Damage

- | | |
|--|---|
| <input type="checkbox"/> OEHC - Observed or Evidence of Human Contact | <input checked="" type="checkbox"/> NEAH - No Evidence of Adverse Health/Environmental Impact |
| <input type="checkbox"/> OEEI - Observed or Evidence of Environmental Impact | <input type="checkbox"/> EFK - Evidence of Fish Kill |

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

1CBC2303-23F2-4DA5-9AB2-492D59491726

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 1CBC2303-23F2-4DA5-9AB2-492D59491726.
Date Sent: 12/15/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:	AR0033278	Facility name:	P Street
Date Overflow Began:	12/14/2015	Time:	12:16 pm
Date Overflow Ended:	12/14/2015	Time:	12:50 pm
Location:	1806 Zero Street, Z001-0540 to 0530, paved area		

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **68**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson** Title **Deputy Director of Systems** Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

FC970D77-2D8C-4432-82FD-39B4F02D0B27

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: FC970D77-2D8C-4432-82FD-39B4F02D0B27
Date Sent: 12/15/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
12/14/2015
12/14/2015

Facility name:
 Time:
 Time:

P Street
12:15 pm
12:45 pm

3400 South M Street, P008-3100 to 2090, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **300**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OE EI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

47A0EB4C-DB14-4B00-9334-E6B028D9B38E

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 47A0EB4C-DB14-4B00-9334-E6B028D9B38E

Date Sent: 12/15/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Stree

Date Overflow Began:

12/14/2015

Time:

1:00 pm

Date Overflow Ended:

12/14/2015

Time:

1:18 pm

Location:

1622 South 28th Street, P006-2350, storm drain

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

363625 *JBJ*

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

0B56A6FA-F485-4CFF-A9F4-D9AAFD5D05C3

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 0B56A6FA-F485-4CFF-A9F4-D9AAFD5D05C3
Date Sent: 12/15/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number: **AR0033278**
 Date Overflow Began: **12/15/2015**
 Date Overflow Ended: **12/15/2015**
 Location: **1501 May Avenue, P005-0220 to 0210, yard**

Facility name: _____
 Time: _____
 Time: _____
P Street
9:30 am
12:30 pm

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **1800**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

81D76DB2-7E63-4C15-9DE2-CB8B71B004C4

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 81D76DB2-7E63-4C15-9DE2-CB8B71B004C4

Date Sent: 12/23/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Stree

Date Overflow Began:

12/22/2015

Time:

6:13 pm

Date Overflow Ended:

12/22/2015

Time:

7:57 pm

Location:

3417 Santa Fe Street, FL01-0340 to 0350, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

208

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 09C80293-A15F-4FA9-B31B-1A8990EDF2FA

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

12/27/2015

Time:

2:54 pm

Date Overflow Ended:

Time:

Location:

1319 South 17th Street, P006-0380 to 0360

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, b

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow *JBJ*
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

The overflow is still active.

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

8AB05D99-08C2-478F-90A9-66E701905DE1

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 8AB05D99-08C2-478F-90A9-66E701905DE1

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

12/27/2015

Time:

3:26 pm

Date Overflow Ended:

12/28/2015

Time:

12:40 pm

Location:

4221 Park Avenue, P007-2070, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

254800

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

7DE2D57E-E5E7-4E53-9594-A12048F71327

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 7DE2D57E-E5E7-4E53-9594-A12048F71327

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
 12/27/2015

Facility name:
 Time:
 Time:

P Street
 2:54 pm

3200 North M Street, P005-3030, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I-& I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

The overflow is still active.

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

89B87CAE-E4D8-4C0B-B0E0-43EA95FAF788

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 89B87CAE-E4D8-4C0B-B0E0-43EA95FAF788

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

12/27/2015

Time:

3:10 pm

Date Overflow Ended:

12/28/2015

Time:

10:40 pm

Location:

1018 North 18th Street, P005-1390, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

141000

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

6A93C2AC-57C0-4AE5-BD3E-69D8D7C316A5

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 6A93C2AC-57C0-4AE5-BD3E-69D8D7C316A5
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
12/27/2015
12/28/2015

Facility name:
 Time:
 Time:

P Stree
2:38 pm
1:26 pm

North 37th and North J Street, P007-0314, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **68400**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

AC754C03-7165-4597-A56E-AE3ECA60FBF2

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: AC754C03-7165-4597-A56E-AE3ECA60FBF2

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Stree

Date Overflow Began:

12/27/2015

Time:

3:25 pm

Date Overflow Ended:

12/28/2015

Time:

3:05 pm

Location:

~~1900 Fikes Avenue, P005-1750, paved area~~

722 North 20th JBJ

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

14200

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEL - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

8474EF18-8EA4-4A31-BFE1-E89C47EE6CD0

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 8474EF18-8EA4-4A31-BFE1-E89C47EE6CD0
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:	AR0033278	Facility name:	P Stree
Date Overflow Began:	12/27/2015	Time:	3:08 pm
Date Overflow Ended:	12/28/2015	Time:	3:00 pm
Location:	4110 Kinkead Avenue, P007-1880, yard		

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **35750**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- | | |
|--|---|
| <input type="checkbox"/> Machine rodded | <input type="checkbox"/> Disinfected and Deodorized |
| <input type="checkbox"/> Jet-Vac | <input type="checkbox"/> Hydro Cleaned |
| <input type="checkbox"/> Hand rodded | <input type="checkbox"/> Spread Lime on Affected Area |
| <input type="checkbox"/> Used Generator To Power Pumps/Equipment | <input type="checkbox"/> Public Notification |
| <input type="checkbox"/> Other: Describe | |

Environmental Damage

- | | |
|--|---|
| <input type="checkbox"/> OEHC - Observed or Evidence of Human Contact | <input checked="" type="checkbox"/> NEAH - No Evidence of Adverse Health/Environmental Impact |
| <input type="checkbox"/> OEEL - Observed or Evidence of Environmental Impact | <input type="checkbox"/> EFK - Evidence of Fish Kill |

Reported By **Jimmie B. Johnson** Title **Deputy Director of Systems** Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

898E2A49-81CB-44D7-9F26-962E72212B1B

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 898E2A49-81CB-44D7-9F26-962E72212B1B
Date Sent: 12/28/2015

[X]SSO []Bypass []Upset []Unpermitted Discharge
Facility Permit Number:
Date Overflow Began:
Date Overflow Ended:
Location:

AR0033278
12/27/2015
12/28/2015

Facility name:
Time:
Time:

P Stree
2:40 pm
1:08 pm

1201 North Street, P007-0316, yard
37th JB5

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.

Type of Overflow

- [X] Manhole Overflow
[] Lift Station Overflow
[] Main Line Overflow
[] Service Line Overflow
[] Other Overflow Type:

(Enter overflow type if not listed)

Volume: 269600

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- [X] I & I - Rainfall
[] Roots
[] Grease
[] Debris
[] Equipment Failure
[] Construction
[] Vandalism
[] Power Failure
[] Line Failure/Break
[] Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- [] Machine rodded [] Disinfected and Deodorized
[] Jet-Vac [] Hydro Cleaned
[] Hand rodded [] Spread Lime on Affected Area
[] Used Generator To Power Pumps/Equipment [X] Public Notification
[] Other: Describe

Environmental Damage

- [] OEHC - Observed or Evidence of Human Contact [X] NEAH - No Evidence of Adverse Health/Environmental Impact
[] OEEI - Observed or Evidence of Environmental Impact [] EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

17A446C9-0F73-47A2-8257-942B0978377E

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 17A446C9-0F73-47A2-8257-942B0978377E

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Stree

Date Overflow Began:

12/27/2015

Time:

6:22 pm

Date Overflow Ended:

12/28/2015

Time:

5:20 pm

Location:

301 South U Street, MC01-0100, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm .

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

138200

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & J).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

11A23072-CE4C-4CE3-86AF-94A0D72E87B1

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 11A23072-CE4C-4CE3-86AF-94A0D72E87B1
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
12/27/2015

Facility name:
 Time:
 Time:

P Stree
2:23 pm

1425 North 34th Street, P007-0050, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm .

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume:

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

The overflow is still active.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

E7D39191-34C0-4ECA-B7AF-7DFB644B69D4

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: E7D39191-34C0-4ECA-B7AF-7DFB644B69D4
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
12/27/2015

Facility name:
 Time:
 Time:

P Street
3:08 pm

1013 North 18th Street, P005-1520, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

This overflow is still active.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

04C5AC19-6F6A-4176-A956-B786CDFB64C0

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 04C5AC19-6F6A-4176-A956-B786CDFB64C0
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
12/27/2015

Facility name:
 Time:
 Time:

P Street
10:31 am

1307 South 17th Street, P006-0370 to 0360

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEL - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Over flow is still active.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

885827EE-386C-407E-A7CC-FB2FCBE57E5E

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 885827EE-386C-407E-A7CC-FB2FCBE57E5E
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
12/27/2015
12/28/2015

Facility name:
 Time:
 Time:

P Stree
2:05 pm
9:18 an

Kelley Highway and North 31st Street, P004-2190, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm .

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 230600

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

BE9A90A1-2A3A-4E30-B299-BA7D353C9AF3

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: BE9A90A1-2A3A-4E30-B299-BA7D353C9AF3

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0033278

12/27/2015

12/28/2015

Facility name:

Time:

Time:

P Street

1:09 pm

10:00 am

4608 South 25th Street, MC07-0430 to 0420, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

12510

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEL - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

91E702F6-00C0-4FD7-837A-7ACD4CBB4EE5

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 91E702F6-00C0-4FD7-837A-7ACD4CBB4EE5

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

12/27/2015

Time:

2:42 pm

Date Overflow Ended:

12/28/2015

Time:

10:30 am

Location:

2004 north 13th Street, P004-0380 to 0370, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

11880

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

35788F5D-606F-4C5B-B5ED-25CC82D8F480

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 35788F5D-606F-4C5B-B5ED-25CC82D8F480

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

12/27/2015

Time:

2:45 pm

Date Overflow Ended:

12/28/2015

Time:

1:15 pm

Location:

1124 North 7th Street, P007-1550, paved area

40th

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

202500

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river, stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

E93A1FC9-B534-4C2A-8DEC-60720B5E040A

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: E93A1FC9-B534-4C2A-8DEC-60720B5E040A

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Stree

Date Overflow Began:

12/27/2015

Time:

2:05 pm

Date Overflow Ended:

12/28/2015

Time:

1:40 pm

Location:

5410 South 17th Street, MC06-1040 to 0990, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

14150

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

3F184B89-4D24-429D-BFD8-C398170AE8BF

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 3F184B89-4D24-429D-BFD8-C398170AE8BF
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
12/27/2015

Facility name:
 Time:
 Time:

P Stree
2:27 pm

1410 North 34th Street, P007-0065, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

- Type of Overflow**
- Manhole Overflow
 - Lift Station Overflow
 - Main Line Overflow
 - Service Line Overflow
 - Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

- Cause of Overflow**
- I & I - Rainfall
 - Roots
 - Grease
 - Debris
 - Equipment Failure
 - Construction
 - Vandalism
 - Power Failure
 - Line Failure/Break
 - Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

The overflow is still active.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

8DBB0C03-C0B3-4144-B757-1D7632FDA0E3

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 8DBB0C03-C0B3-4144-B757-1D7632FDA0E3
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:	AR0033278	Facility name:	P Street
Date Overflow Began:	12/27/2015	Time:	3:37 pm
Date Overflow Ended:	12/28/2015	Time:	12:56 pm
Location:	3700 Kinkaid Avenue, P007-0482, yard		

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **345400**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- | | |
|--|---|
| <input type="checkbox"/> Machine rodded | <input type="checkbox"/> Disinfected and Deodorized |
| <input type="checkbox"/> Jet-Vac | <input type="checkbox"/> Hydro Cleaned |
| <input type="checkbox"/> Hand rodded | <input type="checkbox"/> Spread Lime on Affected Area |
| <input type="checkbox"/> Used Generator To Power Pumps/Equipment | <input checked="" type="checkbox"/> Public Notification |
| <input type="checkbox"/> Other: Describe | |

Environmental Damage

- | | |
|--|---|
| <input type="checkbox"/> OEHC - Observed or Evidence of Human Contact | <input checked="" type="checkbox"/> NEAH - No Evidence of Adverse Health/Environmental Impact |
| <input type="checkbox"/> OEEI - Observed or Evidence of Environmental Impact | <input type="checkbox"/> EFK - Evidence of Fish Kill |

Reported By **Jimmie B. Johnson** Title **Deputy Director of Systems** Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

54523E26-65C7-4943-9AEA-183F0D95E417

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 54523E26-65C7-4943-9AEA-183F0D95E417

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

12/27/2015

Time:

5:40 pm

Date Overflow Ended:

12/28/2015

Time:

2:53 pm

Location:

Old Greenwood Road and South P Street, P009-0200, storm drain

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 127300

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEL - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

DB7E08F0-D366-4A02-84FC-370517B32754

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: DB7E08F0-D366-4A02-84FC-370517B32754
Date Sent: 12/28/2015

[X] SSO [] Bypass [] Upset [] Unpermitted Discharge

Facility Permit Number:
Date Overflow Began:
Date Overflow Ended:
Location:

AR0033278
12/27/2015
12/28/2015

Facility name:
Time:
Time:

P Street
5:53 pm
2:57 pm

1801 Old Greenwood Road, P009-0820, ditch

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- [X] Manhole Overflow
[] Lift Station Overflow
[] Main Line Overflow
[] Service Line Overflow
[] Other Overflow Type:

(Enter overflow type if not listed)

Volume: 18960

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- [X] I & I - Rainfall
[] Roots
[] Grease
[] Debris
[] Equipment Failure
[] Construction
[] Vandalism
[] Power Failure
[] Line Failure/Break
[] Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- [] Machine rodded [] Disinfected and Deodorized
[] Jet-Vac [] Hydro Cleaned
[] Hand rodded [] Spread Lime on Affected Area
[] Used Generator To Power Pumps/Equipment [] Public Notification
[] Other: Describe

Environmental Damage

- [] OEHC - Observed or Evidence of Human Contact [X] NEAH - No Evidence of Adverse Health/Environmental Impact
[] OEEI - Observed or Evidence of Environmental Impact [] EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

0E2A49D4-44B0-41BA-B04C-E5E2F6683EE9

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 0E2A49D4-44B0-41BA-B04C-E5E2F6683EE9

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Stree

Date Overflow Began:

12/27/2015

Time:

8:30 pm

Date Overflow Ended:

12/28/2015

Time:

3:25 pm

Location:

Wheeler Avenue and Fresno Street, MC03-0630, storm drain

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm .

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

11350

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

1881E385-62CA-418D-8BAB-305D4FE48232

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 1881E385-62CA-418D-8BAB-305D4FE48232
Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge
Facility Permit Number:
Date Overflow Began:
Date Overflow Ended:
Location:

AR0033278
12/27/2015

Facility name:
Time:
Time:

P Street
1:10 pm

North 19th and North L Street, P009-1350, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

This overflow is still active.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

976D1E7E-7316-4FD6-834B-C189C166B642

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 976D1E7E-7316-4FD6-834B-C189C166B642

Date Sent: 12/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Stree

Date Overflow Began:

12/27/2015

Time:

4:22 pm

Date Overflow Ended:

12/28/2015

Time:

3:09 pm

Location:

1000 Carthage Avenue, MC03-0582, Ditch

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

683500

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

8310DCEB-FA52-4B35-B0F0-941973888EA3

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 8310DCEB-FA52-4B35-B0F0-941973888EA3
Date Sent: 12/29/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
12/28/2015
12/28/2015

Facility name:
 Time:
 Time:

P Street
12:55 pm
1:15 pm

1906 North K Street, P005-1410 to 1400, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **510**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

B2C8F125-94C3-43AD-9269-DC0C0AEBE76C

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: B2C8F125-94C3-43AD-9269-DC0C0AEBE76C

Date Sent: 12/30/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

Date Overflow Began:

Date Overflow Ended:

Location:

AR0033278

12/30/2015

12/30/2015

Facility name:

Time:

Time:

P Street

10:20 am

10:30 am

127 Perth Court, Z007-0440, Storm Drain

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.)

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

40

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEL - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

73324A7C-8082-4E25-BF8B-D2DDB53511AB

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 73324A7C-8082-4E25-BF8B-D2DDB53511AB
Date Sent: 12/31/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
12/31/2015

Facility name:
 Time:
 Time:

P Stree
9:10 an

South U Street and State Line Road. MC01-0080, creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Deputy Director of Systems**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Flooding from the Arkansas is covering manholes in this sewer shed causing high I & I. This overflow is still active.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

402EFC34-1BDD-4410-9855-4616B20D6AE7

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 402EFC34-1BDD-4410-9855-4616B20D6AE7
Date Sent: 12/31/2015

[X]SSO []Bypass []Upset []Unpermitted Discharge
Facility Permit Number:
Date Overflow Began:
Date Overflow Ended:
Location:

AR0033278
12/31/2015
12/31/2015

Facility name:
Time:
Time:

P Stree
6:59 pm
8:48 pm

3804- Free Ferry Road, P007-1180, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm.

Type of Overflow

- [X] Manhole Overflow
[] Lift Station Overflow
[] Main Line Overflow
[] Service Line Overflow
[] Other Overflow Type:

(Enter overflow type if not listed)

Volume: 1100

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- [] I & I - Rainfall
[X] Roots
[] Grease
[] Debris
[] Equipment Failure
[] Construction
[] Vandalism
[] Power Failure
[] Line Failure/Break
[] Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- [] Machine rodded [] Disinfected and Deodorized
[] Jet-Vac [] Hydro Cleaned
[] Hand rodded [] Spread Lime on Affected Area
[] Used Generator To Power Pumps/Equipment [] Public Notification

[] Other: Describe Removed Roots from manhole by hand.

Environmental Damage

- [] OEHC - Observed or Evidence of Human Contact [X] NEAH - No Evidence of Adverse Health/Environmental Impact
[] OEEI - Observed or Evidence of Environmental Impact [] EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Deputy Director of Systems

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com