

Monthly SSO Report April 2015

Permit Number	Manhole Number	Location	Receiving Water	Duration Min.	Cause	Volume (gal)	Component	Date	Started	Stopped	Steps taken
AR0033278	FL02-1010 to 1000	4610 Arlington Ave.	Clean out overflow	105	Grease	525	Service Line Overflow	4/3/2015	8:00:00 AM	9:45:00 AM	Jet-Vac, Disinfected and Deodorized
AR0033278	MC03-0445 to 0440	2821 South 12th Street	Service line clean out overflow	45	Roots	90	Service Line Overflow	4/6/2015	10:35:00 AM	11:20:00 AM	Machine Rodded
AR0033278	FL01-2380 to 0810	3109 Willow Street	Service line failure	50	Line Failure/Break	100	Service Line Overflow	4/7/2015	11:30:00 AM	12:20:00 PM	Machine Rodded, Disinfected and Deodorized
AR0033278	Z003-1730	8319 South 35th Street	overflow into yard	45	Debris	135	Manhole	4/8/2015	2:15:00 PM	3:00:00 PM	Machine Rodded
AR0033278	P007-2200 and P007-2210	4320 Presley Street	cleanout in yard	50	Roots	200	Service Line Overflow	4/9/2015	7:50:00 AM	8:40:00 AM	Machine Rodded
AR0033278	MC06-0305	1412 Phoenix Avenue	paved area	900	I & I - Rainfall	18000	Manhole	4/13/2015	7:50:00 AM	10:50:00 AM	Disinfected and Deodorized
AR0033278	CS01-1150 to 1130	6221 South 10th Street	yard and Building	40	Roots	200	Main Line Overflow	4/13/2015	4:20:00 PM	5:00:00 PM	Jet-Vac, Disinfected and Deodorized
AR0033278	MC07-1570	3115 Cliff Drive	ditch	65	Roots	1625	Manhole	4/14/2015	12:45:00 PM	1:50:00 PM	Machine Rodded
AR0033278	P011-1940 to 1930	South 16th and South H Street	storm drain	180	Construction	900	Main Line Overflow	4/15/2015	12:00:00 PM	3:00:00 PM	Repaired
AR0033278	MC07-0230	4406 South 22nd Street	Yard	45	Roots	45	Manhole	4/23/2015	1:45:00 PM	2:30:00 PM	Jet-Vac, Disinfected and Deodorized, Public Notice
AR0033278	P007-1170	3704 Free Ferry Rd. -	Yard	85	Roots	2125	Manhole	4/25/2015	10:00:00 AM	2:45:00 PM	Jet-Vac, Disinfected and Deodorized, Public Notice
AR0033278	P007-1140	4000 Free Ferry Road	yard	60	Roots	3000	Manhole	4/27/2015	5:20:00 PM	6:20:00 PM	Machine Rodded, Disinfected and Deodorized
AR0033278	P005-2290	2309 Rogers Avenue	Storm Drain	80 days	Service tied to Storm Drain	164000	Service Line Overflow	2/9/2015	11:07:00 AM	8:00:00 AM	Construct Line Extension
AR0033278	P005-2290	2307 and 2225 Rogers Avenue	Storm Drain	78 days	Service tied to Storm Drain	58000	Manhole	2/11/2015	11:07:00 AM	8:00:00 AM	Construct Line Extension
AR0021750	Z001-0820 to 0210	2311 Ingersoll Circle	creek	230	Debris	14500	Main Line Overflow	4/2/2015	11:00:00 AM	2:50:00 PM	Machine Rodded
AR0021750	S003-0960	1331 South 46th Street	yard	404	Roots	404	Manhole	4/2/2015	10:20:00 AM	5:04:00 PM	Jet-Vac, Repair
AR0021750	RL01-3000 to 0700	1821 South 73rd Circle	clean out overflow	60	Grease	200	Manhole & Service line	4/3/2015	3:10:00 PM	4:10:00 PM	Jet-Vac, Disinfected and Deodorized
AR0021750	M002-1320 to 1330	Between manhole numbers	natural drainage waterway	390	Line Failure/Break	352010	Main Line Overflow	4/9/2015	12:30:00 PM	7:00:00 PM	Excavation
AR0021750	S009-1420 to 1410	4019 Wirsing Avenue	yard	1221	Line Failure/Break	6105	Main Line Overflow	4/13/2015	6:44:00 PM	3:05:00 PM	Machine Rodded, Scheduled repair
AR0021750	RL01-1080	7400 Euper Lane	paved area	900	I & I - Rainfall	4500	Manhole	4/13/2015	7:50:00 PM	10:50:00 PM	Disinfected and Deodorized
AR0021750	S004-1140	5600 Rogers Avenue	paved area	1080	I & I - Rainfall	10800	Manhole	4/13/2015	4:20:00 PM	10:20:00 AM	Disinfected and Deodorized
AR0021750	RL01-1060	1801 South 74th Street	paved area	885	I & I - Rainfall	13275	Manhole	4/13/2015	8:15:00 AM	11:00:00 AM	Disinfected and Deodorized
AR0021750	RL01-0680	1601 South 74th Street	river/stream	870	I & I - Rainfall	8700	Manhole	4/13/2015	8:40:00 PM	11:10:00 AM	Disinfected and Deodorized
AR0021750	S004-1340	5700 Rogers Avenue	storm drain	600	Line Failure/Break	60000	Manhole	4/14/2015	2:00:00 PM	12:00:00 AM	Repaired
AR0021750	S003-0210	5705 Gordon Lane	ditch	155	Debris	1550	Manhole	4/16/2015	12:05:00 PM	2:40:00 PM	Removed debris by hand
AR0021750	S003-0200 to 0100	5704 Free Ferry Road	creek	540	Debris, Line Failure	54000	Main Line Overflow	4/16/2015	2:30:00 PM	12:00:00 AM	Jet-Vac
AR0021750	S007-3160	2004 North 46th Terrace	yard	40	Grease	200	Manhole	4/24/2015	10:10:00 AM	10:50:00 AM	Jet-Vac, Disinfected and Deodorized
AR0021750	S005-1170 to 0230	2221 North 56th Lane	yard	45	Roots	225	Main Line Overflow	4/30/2015	8:00:00 AM	8:45:00 AM	Jet-Vac, Disinfected and Deodorized

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 00020621-9A74-4CC4-A7D8-7266AEFCD31C

Date Sent: 4/10/2015

 SSO Bypass Upset

Facility Permit Number: AR0033278

Facility name:

P Street

Date Overflow Began: 04/08/2015

Time:

02:15 pm

Date Overflow Ended: 04/08/2015

Time:

03:00 pm

Location: 8319 South 35th Street manhole 2003-1730, overflow into yard

*(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).***Type of Overflow****Cause of Overflow** Manhole Overflow I & I - Rainfall Lift Station Overflow Roots Main Line Overflow Grease Service Line Overflow Debris Other Overflow Type: Equipment Failure*(Enter overflow type if not listed)* Construction

Volume: 135

 Vandalism*(Give an estimate in gallons)* Power Failure

Impact of SSO Event: SSO Affected Private Property (ground)

 Line Failure/Break Other Cause:**Action Taken - Check all that apply***(Short term and long-term action, including clean-up and any plans to remediate I & I).* Machine rodded Disinfected and Deodorized Jet-Vac Hydro Cleaned Hand rodded Spread Lime on Affected Area Used Generator To Power Pumps/Equipment Public Notification Other: Describe**Environmental Damage** OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By Steve Parke

Title

Director of Utilities

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fortsmithar.gov

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 2299DDBA-4B1E-43A2-BA5D-A3C141228433

Date Sent: 4/10/2015

 SSO Bypass Upset

Facility Permit Number: AR0033278

Facility name: P Street

Date Overflow Began: 04/09/2015

Time: 07:50 am

Date Overflow Ended: 04/09/2015

Time: 08:40 am

Location: 4320 Presley Street, between manholes P007-2200 and P007-2210, cleanout in yard

*(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).***Type of Overflow**

- Manhole Overflow
 Lift Station Overflow
 Main Line Overflow
 Service Line Overflow
 Other Overflow Type:

(Enter overflow type if not listed)

Volume: 200

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
 Roots
 Grease
 Debris
 Equipment Failure
 Construction
 Vandalism
 Power Failure
 Line Failure/Break
 Other Cause:

Action Taken - Check all that apply*(Short term and long-term action, including clean-up and any plans to remediate I & I).*

- Machine rodded Disinfected and Deodorized
 Jet-Vac Hydro Cleaned
 Hand rodded Spread Lime on Affected Area
 Used Generator To Power Pumps/Equipment Public Notification
 Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
 OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By Steve Parke

Title Director of Utilities

Telephone Number (479) 784-2231

Additional Comments if Needed:

Building backup

Email a Copy of This Report to the Email Address:

jjohnson@fortsmithar.gov

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 699FDBE8-56A9-40A6-9078-A0E9820CEF7D

Date Sent: 4/26/2015

SSO Bypass Upset

Facility Permit Number: AR0033278

Facility name:

P Street WWTP

Date Overflow Began: 4/25/2015

Time:

10:00 am

Date Overflow Ended: 4/25/2015

Time:

2:45 pm

Location:

3704 Free Ferry Rd. Manhole #1170

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume:

2125

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Steve Floyd

Title Supt.

Telephone Number (479) 784-2331

Additional Comments if Needed:

Cleanup Scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

9C27CF41-5916-48F9-B25F-B2712F8A7F01

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 9C27CF41-5916-48F9-B25F-B2712F8A7F01
Date Sent: 4/30/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**
 Date Overflow Began: **2/11/2015**
 Date Overflow Ended: **4/30/2015**
 Location: **2207 and 2225 Rogers Avenue, Nearest Manhole P005-2290, Storm Drain**

Facility name:
 Time:
 Time:

P Street
11:07 am
8:00 am

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **58000**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause: **Manhole is connected to Storm Sewer**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe **construct line extension**
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

This is close out to Confirmation Number 71A0EB75-E26B-46A2-A87C-321E2A3A491C. New line has been constructed and service tied to sanitary sewer line.

Email a Copy of This Report to the Email Address:

CONFIRMATION NUMBER

D8B48FAE-989B-48CD-BD8E-483F8270F7D3

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: D8B48FAE-989B-48CD-BD8E-483F8270F7D3
Date Sent: 4/30/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**
 Date Overflow Began: **2/9/2015**
 Date Overflow Ended: **4/30/2015**
 Location: **2309 Rogers Avenue, Nearest Manhole P005-2290, storm Drain**

Facility name:
 Time:
 Time:

P Street
11:07 am
8:00 am

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **164000**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause: **service tied to storm drain**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe **construct line extension**
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

This is close out to Confirmation Number 05965DF9-0925-4F1B-AD29-C3B5F779AE94. New line has been constructed and service tied to sanitary sewer ine.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

DE5201D9-D5BB-40F6-9524-A8B3FEF1C10A

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: DE5201D9-D5BB-40F6-9524-A8B3FEF1C10A

Date Sent: 4/30/2015

SSO Bypass Upset

Facility Permit Number: **AR0021750**

Facility name:

Massard

Date Overflow Began: **4-30-2015**

Time:

8:00 am

Date Overflow Ended: **4-30-2015**

Time:

8:45 am

Location: **2221 North 56th Lane, S005-1170 to 0230, yard**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **225**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

918BBE63-4000-486F-854F-DC96BBDD6A89

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 918BBE63-4000-486F-854F-DC96BBDD6A89

Date Sent: 4/28/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Date Overflow Began: **4/27/2015**

Date Overflow Ended: **4/27/2015**

Location: **4000 Free Ferry Road, Manhole P007-1140, yard**

Facility name:

Time:

Time:

P Street

5:20 pm

6:20 pm

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **3000**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

883E8CBB-6AD4-4E75-A538-DDB07F5DF718

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 883E8CBB-6AD4-4E75-A538-DDB07F5DF718

Date Sent: 4/24/2015

SSO Bypass Upset

Facility Permit Number: **AR0021750**

Facility name:

Massard

Date Overflow Began: **4/24/2015**

Time:

10:10 am

Date Overflow Ended: **4/24/2015**

Time:

10:50 am

Location:

2004 North 46th Terrace, Manhole S007-3160, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

200

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

2BFFA2F8-7B11-44CC-B8EF-BAF63C5D7740

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 2BFFA2F8-7B11-44CC-B8EF-BAF63C5D7740
Date Sent: 4/24/2015

SSO Bypass Upset

Facility Permit Number: AR0033278
Date Overflow Began: 4/23/2015
Date Overflow Ended: 4/23/2015
Location: 4406 South 22nd Street, Manhole MC07-0230, Yard

Facility name:
Time:
Time:

P Street
1:45 pm
2:30 pm

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
Lift Station Overflow
Main Line Overflow
Service Line Overflow
Other Overflow Type:

(Enter overflow type if not listed)

Volume:

45

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
Roots
Grease
Debris
Equipment Failure
Construction
Vandalism
Power Failure
Line Failure/Break
Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
Disinfected and Deodorized
Jet-Vac
Hydro Cleaned
Hand rodded
Spread Lime on Affected Area
Used Generator To Power Pumps/Equipment
Public Notification
Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
NEAH - No Evidence of Adverse Health/Environmental Impact
OEEI - Observed or Evidence of Environmental Impact
EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

102A8841-53A7-4F37-81F6-FA75B12F2E61

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 102A8841-53A7-4F37-81F6-FA75B12F2E61

Date Sent: 4/17/2015

SSO Bypass Upset

Facility Permit Number: **AR0021750**

Facility name:

Massard

Date Overflow Began: **4/16/2015**

Time:

2:30 pm

Date Overflow Ended: **4/17/2015**

Time:

12:00 am

Location:

5704 Free Ferry Road, Manhole S003-0200 to 0100, creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

54000

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

1A29BB6E-48BF-4F07-9889-B02F71C64332

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 1A29BB6E-48BF-4F07-9889-B02F71C64332

Date Sent: 4/16/2015

SSO Bypass Upset

Facility Permit Number: **AR0021750**
 Date Overflow Began: **4/16/2015**
 Date Overflow Ended: **4/16/2015**
 Location: **5705 Gordon Lane, Manhole S003-0210, ditch**

Facility name: **Massard**
 Time: **12:05 pm**
 Time: **2:40 pm**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **1550**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Removed debris from manhole by hand.

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

C152398E-4744-43E6-AAC8-DB83C2B59F7F

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: C152398E-4744-43E6-AAC8-DB83C2B59F7F
Date Sent: 4/16/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**
 Date Overflow Began: **4/15/2015**
 Date Overflow Ended: **4/15/2015**
 Location:

Facility name:
 Time:
 Time:

P Street
12:00 pm
3:00 pm

South 16th and South H Street, Manhole P011-1940 to 1930, storm drain

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 900

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe **repaired**
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Street Department crew was installing a storm drain and removed a section of sewer line. They pumped sewer out of the excavation into the storm drain.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

E8A0F334-FE58-4BFC-8941-9AC14CC71831

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: E8A0F334-FE58-4BFC-8941-9AC14CC71831
Date Sent: 4/15/2015

SSO Bypass Upset

Facility Permit Number:	AR0021750	Facility name:	Massard
Date Overflow Began:	4/14/2015	Time:	2:00 pm
Date Overflow Ended:	4/14/2015	Time:	12:00 am
Location:	5700 Rogers Avenue, manhole S004-1340, storm drain		

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **60000**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe **repaired**
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson** Title **Superintendent** Telephone Number **(479) 784-2231**

Additional Comments if Needed:

A contractor, Big M Ranch Inc., bored through the sewer line and then into a water line, while installing a fiber optic line. Most of the water flowing out of the manhole entered the sewer line from the water line leak.

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

273194DA-8FE1-43D3-91B9-40FADBB3A297

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 273194DA-8FE1-43D3-91B9-40FADBB3A297
Date Sent: 4/14/2015

SSO Bypass Upset

Facility Permit Number: **AR0021750**
 Date Overflow Began: **4/13/2015**
 Date Overflow Ended: **4/14/2015**
 Location: **4019 Wirsing Avenue, manhole S009-1420 to 1410, yard**

Facility name: **Massard**
 Time: **6:44 pm**
 Time: **3:05 pm**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 6105

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe **scheduled repair**
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

A4E6FD8F-C928-4273-9ABA-802357CE8C18

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: A4E6FD8F-C928-4273-9ABA-802357CE8C18
Date Sent: 4/14/2015

SSO Bypass Upset

Facility Permit Number: AR0033278
Date Overflow Began: 4/14/2015
Date Overflow Ended: 4/14/2015
Location: 3115 Cliff Drive, Manhole MC07-1570, ditch

Facility name:
Time:
Time:

P Street
12:45 pm
1:50 pm

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
Lift Station Overflow
Main Line Overflow
Service Line Overflow
Other Overflow Type:

(Enter overflow type if not listed)

Volume: 1625

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
Roots
Grease
Debris
Equipment Failure
Construction
Vandalism
Power Failure
Line Failure/Break
Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
Disinfected and Deodorized
Jet-Vac
Hydro Cleaned
Hand rodded
Spread Lime on Affected Area
Used Generator To Power Pumps/Equipment
Public Notification
Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
NEAH - No Evidence of Adverse Health/Environmental Impact
OEEI - Observed or Evidence of Environmental Impact
EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (479) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

BE0E6D66-5DBA-446F-A5E6-8FD925BFABB1

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: BE0E6D66-5DBA-446F-A5E6-8FD925BFABB1
Date Sent: 4/14/2015

SSO Bypass Upset

Facility Permit Number: AR0033278
Date Overflow Began: 4/13/2015
Date Overflow Ended: 4/13/2015
Location:

Facility name:
Time:
Time:

P Street
4:20 pm
5:00 pm

6221 South 10th Street, Manhole CS01-1150 to 1130, yard and Building

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 200

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

9D72762D-E1CC-436A-B840-2E548C985F04

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 9D72762D-E1CC-436A-B840-2E548C985F04

Date Sent: 4/14/2015

SSO Bypass Upset

Facility Permit Number: **AR0021750**
 Date Overflow Began: **4/13/2015**
 Date Overflow Ended: **4/14/2015**
 Location: **1601 South 74th Street, Manhole RL01-0680**

Facility name: **Massard**
 Time: **8:40 pm**
 Time: **11:10 am**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

8700

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

43C25C95-0596-4E0C-A8A6-BA7B86766027

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 43C25C95-0596-4E0C-A8A6-BA7B86766027
Date Sent: 4/14/2015

SSO Bypass Upset

Facility Permit Number: AR0021750
Date Overflow Began: 4/13/2015
Date Overflow Ended: 4/14/2015
Location: 5600 Rogers Avenue, Manhole S004-1140, paved area

Facility name:
Time:
Time:

Massard
4:20 pm
10:20 am

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
Lift Station Overflow
Main Line Overflow
Service Line Overflow
Other Overflow Type:

(Enter overflow type if not listed)

Volume: 10800

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
Roots
Grease
Debris
Equipment Failure
Construction
Vandalism
Power Failure
Line Failure/Break
Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
Disinfected and Deodorized
Jet-Vac
Hydro Cleaned
Hand rodded
Spread Lime on Affected Area
Used Generator To Power Pumps/Equipment
Public Notification
Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
NEAH - No Evidence of Adverse Health/Environmental Impact
OEEI - Observed or Evidence of Environmental Impact
EFK - Evidence of Fish Kill

Reported By Jimmie B. Johnson

Title Superintendent

Telephone Number (470) 784-2231

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

48B129CD-10B3-44D0-BD83-D261C65B18E9

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 48B129CD-10B3-44D0-BD83-D261C65B18E9
Date Sent: 4/14/2015

SSO Bypass Upset

Facility Permit Number: AR0021750
Date Overflow Began: 4/13/2015
Date Overflow Ended: 4/14/2015
Location:

Facility name: Massard
Time: 7:50 pm
Time: 10:50 am

7400 Euper Lane, manhole RL01-1080, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 4500

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

14CE8796-54F7-4F6B-934F-9286591A906B

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 14CE8796-54F7-4F6B-934F-9286591A906B

Date Sent: 4/14/2015

SSO Bypass Upset

Facility Permit Number: **AR0021750**

Facility name:

Massard

Date Overflow Began: **4/13/2015**

Time:

8:15 pm

Date Overflow Ended: **4/14/2015**

Time:

11:00 am

Location:

1801 South 74th Street, manhole RL01-1060, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 13275

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

B8606DE4-DE22-4663-8F57-DC358B4F73AF

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: B8606DE4-DE22-4663-8F57-DC358B4F73AF

Date Sent: 4/14/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Date Overflow Began: **4/13/2015**

Date Overflow Ended: **4/14/2015**

Location:

Facility name:

Time:

Time:

P Street

7:50 pm

10:50 am

1412 Phoenix Avenue, Manhole MC06-0305, paved area

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 18000

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:

jjohnson@fsark.com

CONFIRMATION NUMBER

6765F5A8-4324-43BA-8123-EA687E76D5D8

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 6765F5A8-4324-43BA-8123-EA687E76D5D8

Date Sent: 4/10/2015

SSO Bypass Upset

Facility Permit Number: **AR0021750**

Facility name:

Massard WWTP

Date Overflow Began: **04/09/2015**

Time:

12:30 pm

Date Overflow Ended: **04/09/2015**

Time:

07:00 pm

Location:

Between manhole numbers M002-1320 and M002-1330, overflow from line failure reached natural drainage water

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 352,010

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe **excavation**
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area.
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Parke**

Title **Director of Utilities**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fortsmithar.gov

CONFIRMATION NUMBER

6C481136-877B-4422-9434-D742D9E1C987

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 6C481136-877B-4422-9434-D742D9E1C987

Date Sent: 4/8/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P Street WWTP

Date Overflow Began: **4/7/2015**

Time:

11:30 am

Date Overflow Ended: **4/7/2015**

Time:

12:20 pm

Location: **3109 Willow Street FL01-2380 to 0810 Service line failure**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume: **100**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 784-2331**

Additional Comments if Needed:

Cleanup Scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

19A6E4EB-7ED0-4215-BA71-B29C33643CC8

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 19A6E4EB-7ED0-4215-BA71-B29C33643CC8

Date Sent: 4/6/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Date Overflow Began: **4/6/2015**

Date Overflow Ended: **4/6/2015**

Location:

Facility name:

Time:

Time:

P Street WWTP

10:35 am

11:20 am

2821 South 12th Street MC03-0445 to 0440 Service line clean out overflow

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 90

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd**

Title **Supt.**

Telephone Number **(479) 784-2331**

Additional Comments if Needed:

Cleanup Scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

407D69E7-EE95-4B1C-9937-232F1DFB91E5

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 407D69E7-EE95-4B1C-9937-232F1DFB91E5

Date Sent: 4/3/2015

SSO Bypass Upset

Facility Permit Number: **AR0021750**

Facility name:

Massard WWTP

Date Overflow Began: **4/3/2015**

Time:

3:10 pm

Date Overflow Ended: **4/3/2015**

Time:

4:10 pm

Location:

1821 South 73rd Circle RL01-3000 to 0700 manhole overflow 3000, clean out overflow

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **200**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number **(479) 784-2331**

Additional Comments if Needed:

clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

60791CCE-C12C-427F-B939-9E267EAFBE9C

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 60791CCE-C12C-427F-B939-9E267EAFBE9C

Date Sent: 4/3/2015

SSO Bypass Upset

Facility Permit Number: **AR0033278**

Facility name:

P Street WWTP

Date Overflow Began: **4/3/2015**

Time:

8:00 am

Date Overflow Ended: **4/3/2015**

Time:

9:45 am

Location:

4610 Arlington Ave. FL02-1010 to 1000 Clean out overflow

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

525

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Public Land Only (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Steve Floyd** Title **Supt.** Telephone Number **(479) 784-2331**

Additional Comments if Needed:

Clean up scheduled

Email a Copy of This Report to the Email Address:

sfloyd@fortsmithar.gov

CONFIRMATION NUMBER

6F508B4D-0C44-43D6-884F-AB09187436A3

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 6F508B4D-0C44-43D6-884F-AB09187436A3
Date Sent: 4/2/2015

SSO Bypass Upset

Facility Permit Number: **AR0021750**
 Date Overflow Began: **4/2/2015**
 Date Overflow Ended: **4/2/2015**
 Location: **2311 Ingersol Circle, Z001-0820 to 0210, creek**

Facility name:
 Time:
 Time:

Massard
11:00 am
2:50 pm

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **14500**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

D6C2145F-21D3-45E2-B8E8-3B76F3E0F649

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: D6C2145F-21D3-45E2-B8E8-3B76F3E0F649

Date Sent: 4/2/2015

SSO Bypass Upset

Facility Permit Number: AR0021750

Date Overflow Began: 4/2/2015

Date Overflow Ended: 4/2/2015

Location:

Facility name:

Time:

Time:

Massard

10:20 am

5:04 pm

1331 South 46th Street, S003-0960, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

404

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe **made repair**

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

From: (479) 784-2330
Steve Floyd
City of Fort Smith
3900 Kelley Highway

Fort Smith, AR 72904

Origin ID: FSMA



Ship Date: 18MAY15
ActWgt: 0.5 LB
CAD: 1731127/INET3610

Delivery Address Bar Code




SHIP TO: (501) 682-0638 **BILL SENDER**
NPDES Enforcement Section, Water
ADEQ
5301 Northshore Drive

North Little Rock, AR 72118

Ref #
Invoice #
PO #
Dept #


WED - 20 MAY AA
**** 2DAY ****

TRK# 7736 2722 6426
0201



SA LITA

72118
AR-US
LIT



537J3/C918/EE4B

After printing this label:

1. Use the 'Print' button on this page to print your label to your laser or inkjet printer.
2. Fold the printed page along the horizontal line.
3. Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number.

Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$1,000, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written claims must be filed within strict time limits, see current FedEx Service Guide.