

CONFIRMATION NUMBER

5DE687B9-3B17-44C2-807F-4DFF6BA52DAC

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 5DE687B9-3B17-44C2-807F-4DFF6BA52DAC

Date Sent: 8/27/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0033278

Facility name:

P Street

Date Overflow Began:

8/26/2015

Time:

12:37 pm

Date Overflow Ended:

8/26/2015

Time:

2:00 pm

Location:

2312 Ingersol Circle, 2002-0860 to 0850, creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

415

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe **repair**

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

D8566A3C-2FBB-464F-939B-D8324E5F51DE

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: D8566A3C-2FBB-464F-939B-D8324E5F51DE

Date Sent: 8/28/2015

SSO Bypass Upset Unpermitted Discharge

Facility Permit Number:

AR0021750

Facility name:

Massard

Date Overflow Began:

8/28/2015

Time:

8:30 am

Date Overflow Ended:

8/28/2015

Time:

9:00 am

Location:

5604 Gordon, S003-0600, ditch

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

60

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com

CONFIRMATION NUMBER

854E5382-EAD0-4E98-AE06-5705001B4671

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 854E5382-EAD0-4E98-AE06-5705001B4671
Date Sent: 8/31/2015

SSO Bypass Upset Unpermitted Discharge
 Facility Permit Number:
 Date Overflow Began:
 Date Overflow Ended:
 Location:

AR0033278
8/31/2015
8/31/2015

Facility name:
 Time:
 Time:

P Street
10:00 am
12:30 pm

7411 Holly Avenue, 2002-0190, yard

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **1500**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Affected Private Property (ground)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEL - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Jimmie B. Johnson**

Title **Superintendent**

Telephone Number **(479) 784-2231**

Additional Comments if Needed:

Email a Copy of This Report to the Email Address:
jjohnson@fsark.com



CONFIRMATION NUMBER

FE967DA4-2304-405B-B60F-244BC4720ED2

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: FE967DA4-2304-405B-B60F-244BC4720ED2
Date Sent: 8/18/2015

[X] SSO [] Bypass [] Upset [] Unpermitted Discharge
Facility Permit Number:
Date Overflow Began:
Date Overflow Ended:
Location:

AR0021750
8/17/2015
8/17/2015

Facility name:
Time:
Time:

Massard WWTP
1:45 pm
2:20 pm

4217 South 22nd Street Basin: MC05 USMH: 0710 DSMH: 0690 Overflow at clean out.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- [] Manhole Overflow
[] Lift Station Overflow
[] Main Line Overflow
[X] Service Line Overflow
[] Other Overflow Type:

(Enter overflow type if not listed)

Volume: 350

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Cause of Overflow

- [] I & I - Rainfall
[] Roots
[X] Grease
[] Debris
[] Equipment Failure
[] Construction
[] Vandalism
[] Power Failure
[] Line Failure/Break
[] Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- [] Machine rodded [X] Disinfected and Deodorized
[X] Jet-Vac [] Hydro Cleaned
[] Hand rodded [] Spread Lime on Affected Area
[] Used Generator To Power Pumps/Equipment [] Public Notification
[] Other: Describe

Environmental Damage

- [] OEHC - Observed or Evidence of Human Contact [X] NEAH - No Evidence of Adverse Health/Environmental Impact
[] OEEI - Observed or Evidence of Environmental Impact [] EFK - Evidence of Fish Kill

Reported By Steve Floyd

Title Supt.

Telephone Number (479) 461-0914

Additional Comments if Needed:

Email a Copy of This Report to the Email Address: sfloyd@fortsmithar.gov

Monthly SSO Report August 2015

Permit Number	Manhole Number	Location	Receiving Water	Duration Min.	Cause	Volume (Gallons)	Component	Date Overflow Started	Date Overflow Stopped	Started	Stopped	Steps Taken
AR0021750	4217 South 22nd Street	MC05-0710 to 0690	yard	35	Grease	350	Service Line	08/17/2015	8/17/2015	1:45 PM	2:20 PM	Jet-Vac, Disinfected and Deodorized
AR0021750	5604 Gordon	S003-0600	ditch	30	Roots, Grease	60	Manhole	08/28/2015	8/28/2015	8:30 AM	9:00 AM	Machine rodded
AR0033278	2312 Ingersol Circle	Z002-0860 to 0850	creek	83	Line Failure	415	Mainline	08/26/2015	8/26/2015	12:37 PM	2:00 PM	repaired, Disinfected and Deodorized
AR0033278	7411 Holly Avenue	Z002-0190	yard	150	Roots	1500	Manhole	08/31/2015	8/31/2015	10:00 AM	12:30 PM	Jet-Vac, Disinfected and Deodorized

ORIGIN ID:FSMA (479) 784-2330
STEVE FLOYD
CITY OF FORT SMITH
3900 KELLEY HIGHWAY

FORT SMITH, AR 72904
UNITED STATES US

SHIP DATE: 23SEP15
ACTWGT: 0.50 LB
CAD: 1731127/NET3670

BILL SENDER

TO NPDES ENFORCEMENT SECTION, WATER
ADEQ
5301 NORTSHORE DRIVE

NORTH LITTLE ROCK AR 72118


(501) 682-0638

REF:

INV:
PO:

DEPT:

539L2/CBB981D0



FedEx
Express



J182015951001tw

FRI - 25 SEP AA

** 2DAY **

TRK#
0201

7745 7565 3460

SA LITA

72118

AR-US

LIT



After printing this label:

1. Use the 'Print' button on this page to print your label to your laser or inkjet printer.
2. Fold the printed page along the horizontal line.
3. Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number.

Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$1,000, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written claims must be filed within strict time limits, see current FedEx Service Guide.