

# ADEQ

ARKANSAS  
Department of Environmental Quality

June 11, 2010

Mr. Donald Knight, Manager  
Heber Springs Water and Sewer  
1101 West Front Street  
Heber Springs, AR 72543

RE: NPDES Permit No.: AR0022381, AFIN: 12-00029  
Response to Inspection

Dear Mr. Knight:

The Department has received your response to the March 15 & 16, 2010 inspections of your facility by our District Field Inspectors, Mike Kennedy and Brent Walker. Your response has been deemed deficient for the following reasons:

1. The Response did not include detailed plans on the lagoon levee repairs. Please submit a detailed plan on the lagoon levee repairs to the permits section so it can be determined if a construction permit is needed.
2. In response to item no.3, the current flow measurement is not acceptable. Flow must be measured after final treatment.

A copy of the inspection report and the inadequate response is included with this letter for your review. Please submit an adequate response by **June 25, 2010**. Failure to adequately respond by this date will be considered in determining the enforcement action, if required, for this facility.

Thank you for your attention to this matter. Should you have any questions, feel free to contact me at 501-682-0632 or you may e-mail me at [robertsa@adeq.state.ar.us](mailto:robertsa@adeq.state.ar.us).

Sincerely,



Anne Roberts  
Enforcement Analyst  
Water Division Enforcement Section