

(ATTACHMENT)

**BOYD POINT TREATMENT FACILITY
EFFLUENT DISCHARGE MONITORING REPORT
DECEMBER 2015**

COMMENTS:

- DISCARDED THE EFFLUENT BOD ON DECEMBER 13, 2015, DUE TO THE SEED D.O. DEPLETION NOT MEETING THE REQUIREMENTS ACCORDING TO STANDARD METHOD.

SIGNATURE OF PRINCIPAL EXECUTIVE
OFFICER OR AUTHORIZED AGENT