NON-COMPLIANCE LETTER

DATE: May 26, 2015	
ARKANSAS DEPARTMENT OF ENVIRONMENTAL QUALITY 5301 NORTH SHORE DRIVE NORTH LITTLE ROCK, AR 72118-5317 ATTN: ENFORCEMENT SECTION	
RE: NPDES PERMIT NO: AR0034380 DISCHARGE NU	MBER 001-A
CLIENT: STUTTGART, CITY OF ADDRESS:P.O. BOX 130 CITY: STUTTGART STATE: AR ZIP: 72160 PHONE:	
CONTACT: TOMMY LAWSON, MANAGER	
DATE OF PARAMETER NON-COMPLIANCE EXCEEDED CONCENTRATION LOADING	PERMIT LIMITS
04/01-30/15 TRC INST MAX <.050 TSS MO AVG 15.964	.033 15
WE FEEL THIS PROBLEM WAS DUE TO: 1. SO2 mixing moter overloaded not allowing proper mixture was detailed to the solution of t	nich led
2. The Sludge Belt press being down for repairs	
WE PLAN ON CORRECTING THE PROBLEM IN THIS MANNER: 1. The mixing motor has been repaired	
2. The sludge belt will be repaired on the week of June 1st	- 5th by some comp
from the manufacturer	July Servicendi
TIME ESTIMATED THAT IT WILL TAKE:	
Belt Press should be repaired by the second week in June	
YOURS TRULY,	

STUTTGART MUNICIPAL WATER WORKS

612 SOUTH COLLEGE – P.O. BOX 130 STUTTGART, ARKANSAS 72160-0130

RETURN SERVICE REQUESTED



Hasler

\$00.48^o

FIRST-CLASS MAIL

ZIP 72160 011D10608725

ADEQ Enforcement Dection 5301 Northshore Drive N. L. R. AR 12118-5317

72118531799

հեպլիկիիիիիիկիիինիիոկիալիյրիարինրի