


WATER DIVISION CONSTRUCTION STORM WATER COMPLAINT REPORT			
GPS LOCATION:		AFIN: 73-00000	
DATE RECEIVED: 05/18/09		PERMIT#: 00660-WG-P	
COMPLAINANT NAME: Thor Wilson		COUNTY: White	
ADDRESS: 2880 Little Creek Road, Rose Bud		COMPLAINT AGAINST: XTO	
PHONE: 501-827-9330		ADDRESS:	
		PHONE: 479-831-9608	
TRACKING & REFERRAL INFORMATION			
PERSON RECEIVING REPORT: Shiela Keats	DATE: 05/18/09	SUPERVISOR REFERRAL: Eric Fleming	DATE: 05/18/09
INSPECTOR REFERRAL:	DATE:	MEDIA SUPERVISOR REFERRAL:	DATE:
PHONE REFERRAL CONTACT:	DATE:	RECEIVING INSPECTOR: Dennis Benson	DATE: 05/18/09
COMPLAINT RECEIVED BY: "PHONE "LETTER "VERBAL <input checked="" type="checkbox"/> INTERNET "EMAIL			
DETAILED DESCRIPTION			
Complainant was concerned that drilling fluids were being discharged from a black plastic pipe that crosses Little Creek Road from on pit to another..			
LOCATION			
From NLR go north on Highway 67/167 to Cabot. Take the Highway 5 to Rose Bud. In Rose Bud take Highway 36 east toward Searcy. Go left (east) on Highway 310 to Shobe. Little Creek Road is unmarked but it is a right turn. Street to the left is Holeyfield Road. Drilling pad on Highway 310 prior to Little Creek and at the end of Little Creek.			
PREVIOUS COMPLAINT: "YES <input checked="" type="checkbox"/> NO DATES:			
DISCHARGE TO STREAM: "YES <input checked="" type="checkbox"/> NO NAME OF STREAM:			
INVESTIGATION			
INSPECTOR: Dennis Benson		DATE: 05/28/09	
ACTION TAKEN:		PHOTOS TAKEN: "YES <input checked="" type="checkbox"/> NO	
<p>Arrived at XTO Well Bennett 1-15 H at the end of Little Creek Road at 10:15 am on 05/28/09. Met Mr. Ray Ross, Drilling Superintendent with Goober Drilling. Mr. Ross said the black plastic pipe on the road was a fresh water line. Mr. Ross contacted Mr. Billy McCartney, XTO Company representative who came to drilling pad within 10 minutes. We walked black plastic pipe to small pond which will be source water for well drilling, however, pump was not set up. This was the only black pipe on Little Creek Road but water could have been run to the well site on Highway 310 during the drilling process for that well. This well is now complete and undergoing closure.</p> <p>Complaint does not appear to be valid.</p>			
FURTHER ACTION:			
Contact Mr. Wilson and give him an update. No further action required at this time.			
SIGNATURE: 		DATE: 05/29/09	
Dennis Benson			