



<h1 style="margin: 0;">ADEQ</h1> <p style="margin: 0;">A R K A N S A S Department of Environmental Quality</p>		<b>WATER DIVISION COMPLAINT REPORT</b>	
		AFIN: <b>02-00013</b>	PERMIT #: <b>AR0001210</b>
COUNTY: <b>02 Ashley</b>		PDS #: <b>019638</b>	
GPS LOCATION: LAT: <b>33.128174</b> LONG: <b>-91.993497</b> <input type="checkbox"/> Discharge Site / <input checked="" type="checkbox"/> General Area / <input type="checkbox"/> Entrance			
COMPLAINANT NAME: <b>Pastor Bouie</b> MAILING ADDRESS: <b>401 S. Penn</b> CITY, STATE, ZIP: <b>Crossett AR 71635</b> PHONE & EXT: / FAX: / EMAIL: / RESPONSE REQUESTED BY COMPLAINANT: <b>Yes</b>		COMPLAINT AGAINST: <b>Georgia-Pacific Crossett, LLC</b> SITE ADDRESS: <b>100 Mill Supply Road</b> MAILING ADDRESS: <b>P.O. Box 3333</b> CITY, STATE, ZIP: <b>Crossett AR 71635</b> PHONE & EXT: / FAX: / EMAIL: /	
HOW WAS COMPLAINT RECEIVED BY ADEQ: <b>PERS</b>			
PERSON RECEIVING REPORT: <b>Michael Young</b> MEDIA SUPERVISOR REFERRAL:		DATE: <b>12/23/2015</b>	SUPERVISOR REFERRAL: <b>Kerri McCabe</b> RECEIVING INSPECTOR: (ID & Name) <b>101531 Michael Young</b>
		DATE: <b>12/23/2015</b>	DATE: <b>12/23/2015</b>
DETAILED DESCRIPTION OF COMPLAINT			
ADEQ Air Division Inspector Tiffany Wooten informed me of a complaint she worked from Pastor Bouie in which he stated that fog generated from the wastewater treatment process at Georgia-Pacific was causing environmental concerns. Tiffany was unsure if this was a regulated process of treatment.			
DETAILED LOCATION			
Georgia-Pacific WWTP in Crossett, AR.			
PREVIOUS COMPLAINTS: <b>No</b> DATE(S):			
FOLLOW-UP ON COMPLAINT			
NUMBER OF SITE VISITS: <b>0</b> DATES: FIRST SECOND THIRD			
PHOTOS TAKEN: <b>No</b>	DISCHARGE TO WATER OF THE STATE: <b>No</b>	SAMPLES COLLECTED: <b>No</b>	
NAME OF WATERBODY:			
FAYETTEVILLE SHALE RELATED: <b>No</b>		FAYETTEVILLE SHALE VIOLATIONS: <b>No</b>	
INVESTIGATION & ACTION TAKEN			
I called Pastor Bouie on December 23, 2015 and left a message. He returned my call that evening after work hours and stated that he would be out over the holidays. On January 6, 2015 I contacted Pastor Bouie and had a conversation with him regarding his concerns. I informed Pastor Bouie that there are currently no regulations regarding fog generated from a WWTP. He stated that the fog was toxic and caused the bushes and vegetation to die upon contact. I urged Pastor Bouie to contact legislators to discuss his disagreements that ADEQ does not have a regulation regarding fog or steam produced in the treatment process of wastewater.			
REFERRED: <b>No</b>	TO WHOM: <b>N/A</b>	DATE REFERRED:	
RESPONSE TRACKING			
RESPONSE REQUESTED: <b>Yes</b>	RESPONSE PROVIDED: <b>***</b>	RESPONSE PROVIDED DATE:	
BY WHOM?(ID and Name): <b>101531 Michael Young</b>		ASSIGNED TO? (ID and Name):	
RESPONSE COMMENT: <b>I informed Pastor Bouie that fog or steam created as a byproduct of wastewater treatment is not regulated by the ADEQ NPDES permit.</b>			
INSPECTOR:  <b>Michael D. Young</b>		DATE: <b>1/7/2016</b>	
SUPERVISOR:  <b>Kerri McCabe</b>		DATE: <b>1/8/2016</b>	