

From: [Rogers, Mark](#)
To: [Pemberton, Layne](#)
Cc: [Nyander, Tim](#)
Subject: FW: AR0020010 Fville SSO 1/9/20
Date: Thursday, February 13, 2020 3:47:06 PM
Attachments: [image003.png](#)
[image001.png](#)

Hello Layne.

This is in response to your email about the 3220 E. Huntsville Rd. SSO report, to Tim Nyander. The SSO was corrected at the time of the 24-hour report, therefore we do not believe the 5-day report applies. The cause of the SSO was a root and debris blockage which was cleared the same day the overflow was discovered. If we are misinterpreting this requirement, we would request clarification.

Thank you,

Mark Rogers

Water & Sewer Operations Manager

City of Fayetteville, Arkansas 72701

T 479.575.8392 F 479.684.4730

TDD (Telecommunications Device for the Deaf): 479.521.1316

[Website](#) | [Facebook](#) | [Twitter](#) | [Instagram](#) | [YouTube](#)



From: Nyander, Tim <tnyander@fayetteville-ar.gov>
Sent: Thursday, February 13, 2020 2:34 PM
To: Rogers, Mark <mrogers@fayetteville-ar.gov>
Subject: FW: AR0020010 Fville SSO 1/9/20

Mark,

Thank you for responding to this...TN

From: Pemberton, Layne <PEMBERTON@adeq.state.ar.us>
Sent: Thursday, February 13, 2020 12:34 PM
To: Nyander, Tim <tnyander@fayetteville-ar.gov>
Subject: AR0020010 Fville SSO 1/9/20

Tim,

Was the overflow at 3220 E. Huntsville Rd. in the field. sewer manhole number W-(09x)007 significant enough to warrant a 5 day report?

Thanks,

Layne Pemberton | Enforcement Analyst
Office of Water Quality | Enforcement Branch
Arkansas Energy and Environment | [Environmental Quality](#)
5301 Northshore Drive, North Little Rock, AR 72118
t: 501.682.0664 | e: pemberton@adeq.state.ar.us



ARKANSAS
ENERGY & ENVIRONMENT