

UPDATED 12/13/21

Sewer Rehab Manhole Rehabilitation Per SSES					
	Occurrences	Responsible Party	Status	Done	Left to Do
Rehab 1001: Raise Manhole - Unpaved	28	BWU	Complete	28	0
Rehab 1002: Raise Manhole - Paved	3	BWU	Complete	3	0
Rehab 1010: Install Manhole Insert	701	BWU	Complete	701	0
Rehab 1015: Install Chimney Seal	10		6	6	4
Rehab 1020: Realign and Grout Casting - Unpaved	183	BWU	156	156	27
Rehab 1021: Realign and Grout Casting - Paved	36	BWU	32	32	4
Rehab 1022: Replace Manhole Ring & Cover - Unpaved	70	BWU	67	67	3
Rehab 1023: Replace Manhole Ring & Cover - Paved	4	BWU	Complete	4	0
Rehab 1024: Replace Manhole Lid	8	BWU	Complete	8	0
Rehab 1040: Clean Manhole, and Coat - <6 Feet Deep	195	Contractor	56	56	139
Rehab 1041: Clean Manhole, and Coat - >6 Feet Deep	195	Contractor	59	59	136
Rehab 1043: Clean Manhole Wall Lift Holes	60	BWU	32	32	28
Rehab 1047: Repair Manhole Pipe Seals	396	BWU	230	230	166
Rehab 1055: Remove Manhole Steps, Stop I/I and Repair	6	BWU	3	3	3
Rehab 1110: Repair Manhole Bench and Trough	76	BWU	69	69	7
Rehab 1205: Repair Manhole Chimney and Coat	111	Contractor	20	20	91
Subtotals:	2082			1474	608
Sewer Rehab Mainline Rehabilitation Per SSES					
	Occurrences	Responsible Party	Status	Done	Left to Do
Rehab 5010: Clean and CCTV	8	BWU	Complete	8	0
Rehab 5000: Clean Mainline	78	BWU	Complete	78	0
Rehab 4510: Cured in Place Lining or Replace	153	Contractor	65	65	88
Rehab 4360: Point Repair	17	BWU	Complete	17	0
Rehab 4430: Replace Mainline	229	50-60% BWU	104	104	125
Other	2		Complete	2	0
Subtotals:	487			274	213
Sewer Rehab Service Line Rehabilitation Per SSES					
	Occurrences	Responsible Party	Status	Done	Left to Do
Rehab 3350: Disconnect Abandoned Service Line at Property	4	BWU	Complete	4	0
Rehab 3390: Disconnect Area Drain	2	BWU	Complete	2	0
Rehab 3360: Point Repair on Municipal Service Line	9	Property Owner	Complete	9	0
Rehab 3360: Point Repair on Private Service Line	53	Property Owner	44	44	9
Rehab 3340: Repair Broken Cleanout	86	BWU	Complete	86	0
Rehab 3330: Replace Missing Cleanout Cap	123	BWU	Complete	123	0
Rehab 3400: Replace Section of Service Line	11	Property Owner	9	9	2
Subtotals:	288			277	11
Totals:	2857			2025	832