

## Kristen Graham (adpce.ad)

---

**Subject:** FW: Adams Field UV Disinfection (AR0021806)

**From:** John Thompson <[John.Thompson@lrwra.com](mailto:John.Thompson@lrwra.com)>

**Sent:** Friday, March 15, 2024 2:41 PM

**To:** Leslie Allen-Daniel (adpce.ad) <[Leslie.Allen-Daniel@adeq.state.ar.us](mailto:Leslie.Allen-Daniel@adeq.state.ar.us)>

**Cc:** Walter Collins <[Walter.Collins@lrwra.com](mailto:Walter.Collins@lrwra.com)>

**Subject:** Adams Field UV Disinfection (AR0021806)

Good afternoon, I am sending this email to notify you that at 1:30 am 3/15/2024, Adams Field experienced an equipment failure that resulted in the UV Disinfection Area being flooded momentarily. We have two different Trojan models that make up our disinfection system, the Signa and the 3000 Plus. The 3000plus has been placed out of service due to damage it suffered from going under water. We are currently using Peracetic Acid as well as the Trojan Signa system to disinfect our effluent. In accordance with our permit, effluent samples were collected and will be tested for fecal coliform. I will keep you updated as the situation develops.

Mike

### John Thompson

Water Reclamation Facility Supervisor

1001 Temple St.

Little Rock, AR 72202

Office: (501) 688-1543

[www.lrwra.com](http://www.lrwra.com)



This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender. This message may contain confidential information, and is intended only for the individual named.