

4/22/2018

ARKANSAS DEQ

NORTH LITTLE ROCK, AR

Dear ADEQ,

We have a local Goat Milk Processing Plant that dumped raw goat milk into the sanitary sewer on March 13, 2018. I had samples at that time, which caused my BOD composite sample to show that there was an increase in flow and caused a D.O. deficiency. After the dumping of milk occurred, I spoke with the manager of the Goat plant and explained that if this happened again that they would be charged for the BOD loading. This issue has been addressed and if it happens again, I will contact the ADEQ.

SINCERELY,

STUART OXFORD
CITY OF YELLVILLE WASTEWATER SUPERINTENDENT