



ROGERS POLLUTION CONTROL FACILITY

"Serving Rogers - Protecting Our Environment"

Water Division

June 22, 2016

NPDES Enforcement Branch

5301 Northshore Drive

North Little Rock, AR. 72118

Permit Number: AR0043397

To Whom it may concern,

On May the 25th at approximately 9:00 AM the Pollution Control Facility took a direct lightening strike to our Effluent Flow transducer system. As a result we were unable to record flow data from 9:00 AM thru 16:27 PM of that day. At 16:27 PM a new transducer controller was put on line and flow Data once again was being transferred thru our scada system. Since our Effluent Chlorine and Sulfur Dioxide feed systems are flow proportional, both these units were immediately (after the lightening strike) put into manual operation and adjusted accordingly. The Fecal Coliform result for the 25th, which was a grab sample collected at 11:42, showed a result of 34 Colonies / 100 mls, with no chlorine residual. The Effluent sampler, which is also flow proportional, was immediately changed to a timed sample event.

On May the 26th at 9:15 AM, a call was placed to the ADEQ enforcement staff, at which time I was informed that this letter attached to our NETDMR submittal would be sufficient notification.

Yours truly,

A handwritten signature in black ink, appearing to read "David Staib". The signature is fluid and cursive, with a large, sweeping flourish at the end.

David Staib

RWU Operations Supervisor