

STATE OF ARKANSAS DEPARTMENT OF POLLUTION CONTROL AND ECOLOGY

SOLID WASTE MANAGEMENT DIVISION 8017 1-30, P.O. BOX 8913 LITTLE ROCK, ARKANSAS 72219-8913 PHONE: (501) 682-0580 FAX: (501) 682-0611



August 4, 1996

3743

Kevin Hodges, P.E. Sunray Services, Inc. P.O. Box 1310 Springdale, AR 72765-1310

RE: Abandon of Piezometer P-3 at the Sunray Tontitown Facility CSN: 72-0144 Permit No.: 162-S

Dear Kevin:

I am writing in regard to your letter dated June 13, 1996 concerning the decommissioning of waste mass piezometer P-3. This decommissioning was authorizated by Mike Hood and as stated by Mike the piezometer should be re-installed after final grades of the landfill are reached in the area. Please submit a decommissioning report for piezometer P-3 for the files.

It was nice to visit with you last week. If you have any questions or comments, please call me at 682-0606.

Sincerely,

Dave Ann Pennington

Solid Waste Division Geologist

cc: Tom Coleman, District Field Inspector

Dan McCullough, Genesis Environmental, Inc.



June 13, 1996

Mike Hood, Technical Manager Solid Waste Division Arkansas Department of Pollution Control & Ecology P.O. Box 8913 Little Rock, AR 72219-8913

Dear Mr. Hood:

This letter is written regarding the piezometer (P-3) which is located on the north end of Site 3, Permit Number 123-SR-2, at the Sunray Services, Inc. Tontitown facility.

With the implementation of the minor modification on the north end of Site 3, and when fill operations progress to the area where P-3 is located, it will be virtually impossible to try to extend the pipe on the piezometer and fill around it without damaging the piezometer (the piezometer is installed in the waste mass). We are proposing to plug and abandon the piezometer, then reinstall it after final contours are established. Please notify me if this course of action is acceptable.

If you have any questions or comments, please feel free to contact me at (501) 751-7024.

Sincerely,

Kevin E. Hodges, P.E.

District Engineer

G.R. Holcomb, District Manager pc Hon. Charles A. Johnson, Washington County Judge Steve Parker, Director, Four County (NW) RSWMD

5+ 's entry mode 1/8/96 by 1184







DEPARTMENT OF POLLUTION CONTROL AND ECOLOGY SOLID WASTE MANAGEMENT DIVISION

8017 I-30, P.O. BOX 8913 LITTLE ROCK, ARKANSAS 72219-8913 TECHNICAL BRANCH: (501) 682-0602 FAX: (501) 682-0611



FACSIMILE TRANSMISSION

DATE:

July 8, 1996

TO:

Kevin Hodges

COMPANY NAME:

Sunray Sanitation

FAX NO:

751-7524

FROM:

Mike Hood

SUBJECT:

P-3

This is your authorization to plug and abandon piezometer P-3 as shown on the plans. It is my understanding that P-3 will be re-installed after final grades of the landfill are reached in the area.

Thank you for your patience and cooperation.