



103
4-18-97
SW

April 14, 1997

Tom Coleman, Inspector
Solid Waste Division
Arkansas Department of Pollution Control & Ecology
P.O. Box 8913
Little Rock, AR 72219-8913

CSN: 72-0114 Permit No. 167-SR-2
Media: Air, Water, Solid Hazardous
Sort: Permit, Compliance

Dear Mr. Coleman

During your routine monthly inspection of the Tontitown Landfill on February 18, 1997, you noted the presence of some leachate seeps at the site. Sunray Services agrees with the Department of Pollution Control and Ecology that leachate seeps must not be allowed to persist, unattended and must be addressed in a timely manner. We therefore make every effort to promptly repair any leachate seeps which occur at our landfill.

As you are aware, leachate seeps occur primarily during periods of heavy rainfall which was the case around the time of your February inspection. I hope that it was apparent during your inspection that we are diligent about addressing leachate seeps and have implemented measures to properly repair these seeps when they occur. This is one measure taken in our continuing effort to maintain the Tontitown Landfill as the best operated landfill within the State of Arkansas.

I appreciate your cooperation and if you have any questions, please contact me at (501) 361-2069

Ronald K. Hunt
Site Engineer/General Manager

cc: Central Files Heide Love, Inspector Supervisor SWD
Steve Parker, Director, Four County RSWMB
Hon. Charles A. Johnson, Washington County Judge
Dale Stevenor: Sunray