

FOR OFFICE USE ONLY:
AIR HW RST SW WATER MINING

**ARKANSAS DEPARTMENT OF ENVIRONMENTAL QUALITY
5301 NORTSHORE DRIVE
NORTH LITTLE ROCK, AR 72118-5317**

COMPLAINT REPORT

LOCATION:	AFIN#:	PERMIT#:	
DATE RECEIVED: 12/01/10	COUNTY: Stone		
COMPLAINANT NAME: Anonymous	COMPLAINT AGAINST: Ridgewood Timber Corp. Attn: Derrick Spinks		
ADDRESS:	ADDRESS: 4443 Harrison St. Batesville, AR 72501		
PHONE:	PHONE: 870-615-0991 Attn: Rod Davis		
PERSON RECEIVING REPORT: Dale Washam	DATE: 12/02/10	SUPERVISOR REFERRAL: Dale Washam	DATE: 12/02/10
INSPECTOR REFERRED:	DATE:	MEDIA SUPERVISOR REFERRAL:	DATE:
PHONE REFERRAL CONTACT:	DATE:	RECEIVING INSPECTOR: Tony Morris	DATE: 12/02/10

DESCRIPTION (IN DETAIL)

The complaint stated that there is significant runoff into a stream from the site.

LOCATION (IN DETAIL)

Located approximately 10 miles south of Mountain View on Hwy 9.

PREVIOUS COMPLAINT? ___ YES ___X___ NO DATES:

DISCHARGE TO STREAM? ___ YES ___X___ NO NAME OF STREAM: Turkey Creek

HOW COMPLAINT WAS RECEIVED: ___ PHONE ___ LETTER ___ VERBAL ___ FAX ___X___ E-MAIL

FOLLOW UP ON COMPLAINT

COMPLAINT #:

AFIN #:

INSPECTOR: Tony Morris

DATE: 12/07/10

ACTION TAKEN: Site visit on 12/07/10, phone conversation with Rod Davis on 12/09/10.


PHOTOS TAKEN: No

The 38 acre site was visited on 12/07/10. The property had been clear cut approximately 2 years ago. Recently, timber haul roads were graveled and a vented ford crossing was constructed across Turkey Creek near Hwy 9. The property has been listed for sale by LandsofArkansas. The property will not be subdivided and no additional constructions is anticipated by the owners according to Mr. Rod Davis who is acting as the agent for the company.

The property is not being developed and no further construction will take place. The vented ford crossing and improvement of timber haul roads are timber related BMP's intended to reduce the sediment load to the stream. The site does not require regulation by the Storm Water Program.

FURTHER ACTION TAKEN/TO BE TAKEN: No further action.

INSPECTOR SIGNATURE:



Tony L. Morris

DATE: 12/09/10

HOURS WORKED:

2 hrs.