ADEO	WATER DIVISION COMPLAINT REPORT												
ADEU	AFIN: 51-00164		PI	ERMIT #: ARG	G590001								
	COUNTY: 51 News	ton	PI	PDS #: 017201									
A R K A N S A S Department of Environmental Quality	GPS LOCATION:	Entrance											
COMPLAINANT NAME: Pam Fowler MAILING ADDRESS:		C&H HO SITE ADDRESS	g Farm										
CITY, STATE, ZIP:		MAILING ADDRI											
PHONE & EXT: / FAX: 870-434-5550 / EMAIL:	CITY, STATE, ZIP: Mt. Judea AR 72655 PHONE & EXT: / FAX:												
RESPONSE REQUESTED BY COMPLAINANT:		EMAIL:											
	OW WAS COMPLAINT RECEIVED BY ADEQ: PHON ADEQ = ADEQ Personnel EML = E-Mail FAX = PERS = Personal Contact PHON = Telephone V												
PERSON RECEIVING REPORT: Tony Morris	DATE: 4/17/2014	SUPERVISOR R	EFERRAL:		DATE:								
MEDIA SUPERVISOR REFERRAL:	DATE:		PECTOR: (ID & Name)	audh	DATE: 4/17/2014								
DE	B3321 Jason Bolenbaugh DETAILED DESCRIPTION OF COMPLAINT												
Tanker trucks are hauling waste from the C&H hog farm to the closed C&C hog farm for land application. The C&C property is not listed in the NMP for the C&H Farm (ARG590001). Also, with recent early morning inversions, the swine waste odor is particularly bad. In addition to the swine manure odor there is a chemical odor similar to herbicide.													
DETAILED LOCATION													
PREVIOUS COMPLAINTS: *** DATE(S):													
FOLLOW-UP ON COMPLAINT													
NUMBER OF SITE VISITS: 2 DATES: FIRST 4/15/2014 SECOND 4/16/2014 THIRD													
PHOTOS TAKEN: *** DISCHARGE TO WATER OF THE STATE: *** SAMPLES COLLECTED: ***													
NAME OF WATERBODY:		1											
FAYETTEVILLE SHALE RELATED: No		FAYETT	EVILLE SHAL	E VIOLATION	IS: No								
	INVESTIGATION												
I visited all of the application fields during a two day sampling event conducted by EPA, Region 6. During my visit I did not notice any odor from the swine operation at the application fields. I also did not notice any odors pertaining to the application of herbicides. An odor from the operation was detected while conducting a walk-around of the facility and the waste lagoons. In a previous inspection conducted on March 26, 2014, of the C&C Hog Farm (Permit 3540-WR-5), it was noted the facility was not in operation and the settling basin and holding pond had been closed by removing waste, backfilling, and vegetating, and a certification of closure had been submitted to the Department. Application records obtained during a separate site visit shows the facility did not land apply waste from April 2 through April 17, 2014. Further investigations of land application practices will be conducted.													
REFERRED: *** TO WHOM: N/A				DATE REFERE	RED:								
DECORAGE DECUESTED	RESPONSE	TRACKI	NG										
NO	SPONSE PROVIDED			PROVIDED DA	ATE:								
BY WHOM?(ID and Name):		ASSIGN	ED TO? (ID a	nd Name):									
RESPONSE COMMENT:													
INSPECTOR: Click text to left to add signatu	ERE**	DATE:											
SUPERVISOR:		DATE: 6/5/2014											

5/6/14	5/6/14	4/25/14	4/22/14	4/22/14	4/22/14	4/18/2014	4/18/2014	4/1/2014	4/1/2014	4/1/2014	4/1/2014	4/1/2014	3/31/2014	3/24/2014	3/22/2014	3/14/2014	3/11/2014	1/25/2014	1/20/2014	1/19/2014	1/16/2014	1/16/2014	12/31/2013	12/30/2013	DATE 12/27/2013
4	10 !	17	12	10	17	17	10	17	4	⊢	17	15	5 1	1 !	1 t	t 1	13	ω	15	ω	17	15	15	5	FIELD T
84 sse 16	84 sse 16	72 nnw 4	73 nnw 8	73 nnw 8	73 nnw 8	72 e3	71 e2	72 s 10	72 s 10	72 s 10	72 s 10	72 s 10	70 s se 13	56 F AT 4 .	59 ssw9	70 SWW 10	73 SE 10 to 15	55 NNW 2	66 NNW 6	8 WSS 65	51 NW 16	51 NW 16	52 S AT 4	40 SW AT 7	FIELD TEMP WIND/DIR 15 45 E AT 4
4	17	12	7	6	7	Сī	20	10	هـــو	ω	υī	σ	U1 →	. ~7	υ t	1 10	4`;	υ	6	4	2	(J	ტ	2	HOUR'S
12,000	51,000	36,000	48,000	18,000	21,000	30,000	60,000	3,000	3,000	18,000	30,000	45,000	42,000	51.000	45,000	57,500	33,000	38,500	36,000	18,000	6,000	18,000	24,000	6,000	GAL 3,000
MIXED	MIXED	MIXED	MIXED	MIXED	MIXED	MIXED	MIXED	MIXED	MIXED	MIXED	MIXED	MIXED	MIXED	MIXED	MIXED	CROP									
HONEYWAGON	HONEYWAGON	HONEYWAGON	HONEYWAGON	HONEYWAGON	HONEYWAGON	HONEYWAGON	HONEYWAGON	HONEYWAGON	HONEYWAGON	HONEYWAGON	HONEYWAGON	HONEYWAGON	HONEYWAGON	HONEYWAGON	HONEYWAGON	METHOD HONEYWAGON									
4	14	12	9.9	6	7	5	15	10	د سو	6	10	15	14	17		3 15	: 11	~ 6	13	6	2	7	9	2	TOTAL ACRI
DRY	DRY	DRY	DRY	DRY	-DRY	DRY	DRY	DRY	DRY	DRY	DRY	Fair	DRY	DRY	DRY	TOTAL ACRES CONDITION OF FIELD 1 DRY									
G00D	GOOD	GOOD	G00D	600D	G00D	GOOD	GOOD	G00D	G00D	GOOD	GOOD	G00D	G00D	G00D	G000	GOOD	GOOD	GOOD	G00D	GOOD	GOOD	GOOD	GOOD	G00D	EQUIPMENT CON POND LINI GOOD GOOD
G00D	G00D	600D	G00D	G00D	GOOD	GOOD	GOOD	GOOD	GOOD	G00D	G00D	G00D	G00D	G00D	900		G00D	GOOD	GOOD	G00D	GOOD	GOOD	G00D	GOOD	POND LIN