≎EPA

Form Approved OMB No. 2040-0003 Approval Expires 7-31-85

	UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Washington, D.C. 20460														rippioval Explics / 31 05														
	NPDES Compliance Inspection Report																												
	Section A: National Data System Coding																												
	Transa	action	Code						NPDI	ES							yr	/mo/d	ay			Ins	pec. T	ype	Ins	specto	r	Fac T	Гуре
1 N 2 5 3 A R 0 0 2 1 7 9 2 11 12 0 6 0 7 1 0 17 18 V 19 S 20 1]															
	Remarks																												
L		F I N 0 8 - 0 0 0 3 4]								
Inspection Work Days Facility Evaluation Rati										Rating													Reserved						
	67		ļ	69				70	N	<u> </u>			71	N	72	N	73			74	75	<u></u>						80	
	Section B: Facility Data																												
	Name and Location of Facility Inspected (For industrial users discharging to POTW, also Entry Time /Date																Permit Effective Date												
City	include POTW name and NPDES permit number) City of Berryville 11:30 a.m./7-10-76															11-1-2002													
	Manhole overflow behind 703 S. Main St Berryville, AR Exit Time/Date															Per	mit E	xpirati	on Da	ate									
	12:45 p.m./7-10-76																10-3	31-200	07										
		of On-S)/Title	e(s)/F	Phone a	and Fax	x Nui	mber(s))										Otl	Other Facility Data						
Kirb City P.O	Name, Address of Responsible Official/Title/Phone and Fax Number Kirby Murry/Public Works Director/870-423-4074/870-423-4501 City of Berryville P.O. Box 227 Berryville, AR 72616 Contacted Yes X No																												
	Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)																												
N	Permit				I	N	Flow 1	Measu	ıreme	ent	nt N					Operations & Maintenance						N CSO/SSO							
N	Records/Reports				N	N Self-Monitoring					Program N				dge Handling/Disposal				N	Pollution Prevention									
N	Facility Site Review				N	N Compliance Sche					edules N				retrea	etreatment				N	Sampling								
N	N Effluent/Receiving Waters N La							Laboratory							Ste	orm V	ater					S	Othe	er: SS	o				
							Sec	tion D	: Sumi	mary	of Fir	dings	s/Con	nment	ts (At	tach a	dditi	onal s	heets	if nec	essar	y)							
ne Ac occ sto eff we	ar 70 cord curre pped luen re oi)3 S. I ing to ed on l on J t ente ut of t	Main Kirb July uly 10 ring o he of	St. I y Mu 10, 20 0, 200 i dry fice.	n reg rry's 906. 96. A creek He st	ards repo On J t the t bed tated	to to ort so uly tim . I : tha	he co ubmit 10, 2 e of i spoke t he h	mpla tted to 006, invest with ad st	int, o the 500 tigat Jan	eards an SS e Arka gallo ion, t nes M ed the	SO re ansa ns ov here lend e ove	epor us De verfl wer lyk o erflo	t was eparti lowed e son n Jul w ear	sub ment d in t ne so ly 10 rlier	mitte t of E he co olids , 200 in th	d to Invir ollec that 6. H e mo	the l ronm tion had He sto ornin	Depa enta syste not l ated g an	ertme d Qu em di been that d wo	ent a ality ie to clea Dew ould	s req , the a cla ned vayne be cl	uired sani ogged up an Alle	d by t tary s d line round n an ng up	the posewer sewer c. The d the d Kin o the	ermi r ove ne ov pipe rby N area	t. erflov erflo e as w Murr a late	w ow vell d ay	
Name(s) and Signature(s) of Inspector(s) Alison West												Agency/Office/Telephone/Fax Arkansas Dept. of Environmental Quality/Springdale/ 479- 927-3257 ext 13/479-927-3261										Date August 1, 2006							
											927	-3257	ext 1	13/479	-927-	3201													
ddw	<u> </u>										927	-3257	ext 1	13/479	927-	3261													



August 14, 2006

Kirby Murry, Public Works Director City of Berryville P.O. Box 227 Berryville, AR 72616

Dear Mr. Murry:

On July 10, 2006, I performed an investigation of a sanitary sewer overflow in response to a complaint. The complaint alleged that a manhole was overflowing in the collection system behind 703 S. Main St. in Berryville, AR. The investigation revealed that you are not in violation of the Arkansas Water and Air Pollution Control Act and the regulations promulgated there under.

However there are some solids which needs to be cleaned up and properly disposed of around the manhole.

If you should have any questions, feel free to contact me at 479-927-3257 ext 13.

Sincerely,

Alison West District Field Inspector Water Division

cc: NPDES Branch