


03336



# El Dorado Water Utilities

500 NORTH WASHINGTON • P. O. BOX 1587 • EL DORADO, AR 71731 (870) 862-6451

February 9, 2007

Mr. John Lamb, District Field Inspector  
ADEQ Water Division  
P. O. Box 8913  
Little Rock, AR 72219-8913

NPDES Permit No. AR0033723

Dear Mr. Lamb:

In response to your letter dated January 29, 2006 and received in our office on February 8, 2007, please be advised of the corrective action taken on the items as follows:

1. The last inspection of Miller Transporters conducted May 23, 2006 did include verification of the self-monitoring conducted by the IU and will be on all subsequent inspection reports. (See attached inspection sheet.)
2. Meters have now been installed on all categorical process waste streams and data is currently being collected.
3. A phone log has been implemented since your inspection. The only notification of violation, which was actually was not a violation since it was never discharged, was documented in said phone log. (See attached phone log.)

If you have any questions concerning this response, please feel free to contact me at (870) 862-6451.

Sincerely,

T. Harold Baker  
Treatment Superintendent

Enclosures

El Dorado Water Utilities  
Industrial Inspection Sheet



Date: 05/23/06

Time: 10:30 am

Industry: Miller Transporters

Address: 2811 Northwest Avenue, El Dorado, AR 71730

Mailing Address: P. O. Box 1392, El Dorado, AR 71730

Contact Person: Tommy Jones 862-5541

Alternate Contact: Tommy Greer 862-5541

Industry Description: Bulk transport company.

Description Of Processes: Wash water from trailers is pumped into a three pit system. The first pit contains the wash water. From the first pit the water goes through a oil separator. The oil and grease goes into the second pit and the cleaned water goes into the third pit for ph adjustment and discharge to the city system.

Categorical Determination: N/A


Monitoring Frequency: monthly

Parameters Monitored: cadmium, chromium, copper, nickel, zinc, VOA, and annually BNA and Phenols.

Compliance: Yes, but they are being required to hold each sample until results are obtained and deemed suitable for discharge to the system.

Future Plans: No expansion plans.

Past Years Pretreatment Performance: Chromium, nickel have been recurring problems during the year and has caused Miller to be in significant noncompliance for 2006.



Self Monitoring Data: Verified that Miller is using correct analytical method for self monitoring and are using Method 4500-h from Standard Methods 2005 edition. Also reviewed self monitoring records.

Allen Gilliam was also present at this inspection.

*John M. Keppeler*

# *El Dorado Water Utilities*

POST # 033336  
NOV 05 2007

500 NORTH WASHINGTON • P. O. BOX 1587 • EL DORADO, AR 71731 (870) 862-6451

MARKED

November 5, 2007

Mr. Greg Hurley  
Arkansas Department of Environmental Quality  
5301 Northshore Drive  
North Little Rock, AR 72118-5317

RE: Permit NO. : AR0033723      AFIN: 70-00341

Dear Mr. Hurley:

In response to your letter dated October 25, 2007, please find attached the response I sent to Mr. John Lamb on February 9, 2007. If you have any questions concerning this response, please feel free to contact me at (870) 862-6451.

Sincerely,



T. Harold Baker  
Treatment Superintendent

Enclosures

# *El Dorado Water Utilities*

500 NORTH WASHINGTON • P. O. BOX 1587 • EL DORADO, AR 71731 (870) 862-6451

February 9, 2007

Mr. John Lamb, District Field Inspector  
ADEQ Water Division  
P. O. Box 8913  
Little Rock, AR 72219-8913

NPDES Permit No. AR0033723

Dear Mr. Lamb:

In response to your letter dated January 29, 2006 and received in our office on February 8, 2007, please be advised of the corrective action taken on the items as follows:

1. The last inspection of Miller Transporters conducted May 23, 2006 did include verification of the self-monitoring conducted by the IU and will be on all subsequent inspection reports. (See attached inspection sheet.)
2. Meters have now been installed on all categorical process waste streams and data is currently being collected.
3. A phone log has been implemented since your inspection. The only notification of violation, which was actually was not a violation since it was never discharged, was documented in said phone log. (See attached phone log.)

If you have any questions concerning this response, please feel free to contact me at (870) 862-6451.

Sincerely,



T. Harold Baker  
Treatment Superintendent

Enclosures

El Dorado Water Utilities  
Industrial Inspection Sheet

Date: 05/23/06

Time: 10:30 am

Industry: Miller Transporters

Address: 2811 Northwest Avenue, El Dorado, AR 71730

Mailing Address: P. O. Box 1392, El Dorado, AR 71730

Contact Person: Tommy Jones 862-5541

Alternate Contact: Tommy Greer 862-5541

Industry Description: Bulk transport company.

Description Of Processes: Wash water from trailers is pumped into a three pit system. The first pit contains the wash water. From the first pit the water goes through a oil separator. The oil and grease goes into the second pit and the cleaned water goes into the third pit for ph adjustment and discharge to the city system.

Categorical Determination: N/A

Monitoring Frequency: monthly

Parameters Monitored: cadmium, chromium, copper, nickel, zinc, VOA, and annually BNA and Phenols.

Compliance: Yes, but they are being required to hold each sample until results are obtained and deemed suitable for discharge to the system.

Future Plans: No expansion plans.

Past Years Pretreatment Performance: Chromium, nickel have been recurring problems during the year and has caused Miller to be in significant noncompliance for 2006.

Self Monitoring Data: Verified that Miller is using correct analytical method for self monitoring and are using Method 4500-h from Standard Methods 2005 edition.  
Also reviewed self monitoring records.

Allen Gilliam was also present at this inspection.

*John M. Peppers*

## PHONE CALL LOG

INDUSTRY: Miller Transporters

CONTACT: Tommy Jones

DATE: 02/05/07

REASON FOR CALL: Notified Tommy that the sample from 01/30/07 was ok to discharge.



## PHONE CALL LOG

INDUSTRY: Miller Transporters

CONTACT: Tommy Jones

DATE: 01/19/07

REASON FOR CALL: Notified Tommy that the sample from 01/08/07 was ok to discharge.

## PHONE CALL LOG

INDUSTRY: Miller Transporters

CONTACT: Tommy Jones

DATE: 12/18/06

REASON FOR CALL: Notified Tommy that the sample from 12/13/06 contained 7.3 mg/l of zinc and was not to be discharged to the collection system.