



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
Washington, D.C. 20460

# NPDES Compliance Inspection Report

Form Approved  
OMB No. 2040-0003

## Section A: National Data System Coding

Transaction Code	NPDES	Yr/Mo/Day	Inspec. Type	Inspector	Fac. Type	
1 <input type="text" value="N"/> 2 <input type="text" value="5"/> 3 <input type="text" value="A"/> <input type="text" value="R"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="2"/> <input type="text" value="2"/> <input type="text" value="3"/> <input type="text" value="6"/> <input type="text" value="5"/> 11 12 <input type="text" value="0"/> <input type="text" value="7"/> <input type="text" value="0"/> <input type="text" value="9"/> <input type="text" value="2"/> <input type="text" value="4"/> 17 18 <input type="text" value="R"/> 19 <input type="text" value="S"/> 20 <input type="text" value="1"/>	Remarks					
<input type="text" value="5"/> <input type="text" value="2"/> <input type="text" value="-"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="7"/> <input type="text" value="3"/>						
Inspection Work Days	Facility Evaluation Rating	BI	QA	Reserved		
67 <input type="text"/> <input type="text"/> <input type="text"/> 69	70 <input type="text" value="N"/>	71 <input type="text" value="N"/>	72 <input type="text" value="N"/>	73 <input type="text"/>	74 <input type="text"/>	
75 <input type="text"/>						
80 <input type="text"/>						

## Section B: Facility Data

Name and Location of Facility Inspected ( <i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i> ) <b>City of Camden WWTP</b> <b>Corner of Jasper and Gibson</b> <b>Camden, AR</b>	Entry Time/Date <b>10:10/09/24/07</b>	Permit Effective Date <b>01 July 2002</b>
	Exit Time/Date <b>11:12/09/24/07</b>	Permit Expiration Date <b>30 June 2007</b>
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) <b>Keith Ballard, Waste Water Plant Manager</b>	Other Facility Data	
Name, Address of Responsible Official/Title/Phone and Fax Number <b>David Richardson, Assistant Utilities Manager</b> <b>P.O. Box J</b> <b>Camden, AR 71711</b>	Contacted Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	


## Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

<input type="text" value="N"/>	Permit	<input type="text" value="N"/>	Flow Measurement	<input type="text" value="N"/>	Operations & Maintenance	<input type="text" value="N"/>	Sampling
<input type="text" value="N"/>	Records/Reports	<input type="text" value="N"/>	Self-Monitoring Program	<input type="text" value="N"/>	Sludge Handling/Disposal	<input type="text" value="N"/>	Pollution Prevention
<input type="text" value="N"/>	Facility Site Review	<input type="text" value="N"/>	Compliance Schedules	<input type="text" value="N"/>	Pretreatment	<input type="text" value="N"/>	Multimedia
<input type="text" value="S"/>	Effluent/Receiving Waters	<input type="text" value="N"/>	Laboratory	<input type="text" value="N"/>	Storm Water	<input type="text" value="N"/>	Other:

## Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

This inspection was performed at the request of the Permits Section. The Permit Section needed the verification of the exact coordinates of the outfall to the Ouachita River, end of pipe. The end of pipe discharge in the Ouachita River was taken using a Garmin III GPS on this date. The coordinates of said discharge were N 33.56379 W -92.78693

Name(s) and Signature(s) of Inspector(s)  John W. Lamb	Agency/Office/Telephone/Fax <b>AR Dept. of Environmental Quality/ El Dorado</b> <b>870-862-0680, Fax 870-862-3509</b>	Date <b>24 September 2007</b>
Signature of Reviewer	Agency/Office/Phone and Fax Numbers	Date

- SL to Frank

036164

OCT 16 2007

# Stuttgart Municipal Water Works

612 S College - PO Box 130 - Stuttgart Arkansas 72160

MARKED

October 16, 2007

Tommy Lawson  
Manager

Water Division Enforcement Section  
Arkansas Department of Environmental Quality  
5301 Northshore Drive  
North Little Rock, AR 72118-8913

RE: Inspection Report by Steve Henderson  
NPDES Permit #AR003480


Dear Sir:

This letter is in response to the inspection performed on September 20, 2007 at the Stuttgart Wastewater Treatment Facility. The permit limits that were exceeded are D.O. and TRC. We are presently looking at installing air stripping in the last chamber of the CL2 contact basin. Hopefully, this will take care of both the D.O. and the TRC problems. We will be working with Mr. Charles Summerford on the project to make these repairs. There will also be a blower installed that will produce approximately 300 CFM of air. This should add enough O2 and remove any CL2 remaining in the wastewater flow that is leaving the plant.

We hope to have these repairs made as quickly as possible to prevent future non-compliance of the plant.

If you have any questions please do not hesitate to call me at 870-673-3246.

Sincerely,



Tommy Lawson  
Manager