٢	SEPA UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Washington, D.C. 20460 NPDES Compliance Inspection Report										Form Approved OMB No. 2040-0003 Approval Expires 7-31-85																			
Section A: National Data System Coding																														
1	N 2 5 3 A R 0 0 3 3 1 6 11 12 0 7 1 2 0 3 17 18												spec. Type Inspector Fac Type I 19 S 20 2						Туре											
l I l	0	2	-	С											Rema	urks														
	In: 67	spect 0	ion W 0	/ork	Days 69			Fa	acility 70	Evalua N	ation I	Rating	5	71	BI N	72	QA N	73			74	75		-Rese	rved				80	
	Section B: Facility Data																													
incl	Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number) Entry Time /Date Permit Effective Date Aramark (City of Pine Bluff WWTP, AR0033316) ~2:30 p.m. 12/03/07 12/03/07																													
5508 Jefferson Parkway Exit Time/Date Permit Expiration Date Pine Bluff, Arkansas 71602 ~3:00 p.m. 12/03/07 12/03/07										Date																				
	Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Other Facility Data Mark Peden, General Manager (870) 247-3758																													
Ma Ara 550	Name, Address of Responsible Official/Title/Phone and Fax Number Contacted Mark Peden, General Manager (870) 247-3758 Aramark Yes 5508 Jefferson Parkway Yes Pine Bluff, Arkansas 71602 No																													
	Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)																													
/	/ Permit / Flow Measuremen							ent			/	O	oerati	erations & Maintenance					/	CSO/SSO										
/ Records/Reports					/			-Moni		-	-		/		0	dge Handling/Disposal					/	Pollution Prevention								
/	/ Facility Site Review / Effluent/Receiving Waters					/			plianc		edule	S		Y			etreatment // rm Water //					/	/ Sampling / Other:							
,							of Fi	f Findings/Comments (Attach additional sheets if necessary)																						
Bi re	A site visit was conducted at Aramark during the recent Pretreatment Compliance Inspection at the City of Pine Bluff Wastewater Utility. This facility specializes in the rental of reusable textiles. The cleaning of industrial textiles requires water washing utilizing surfactants, silicates and alkali detergents to remove organic and inorganic soils. Oxalic acid is used to whiten garments.																													
	Name(s) and Signature(s) of Inspector(s) Steven L. Henderson								Agency/Office/Telephone/Fax ADEQ/ Stuttgart/ 870-673-8846/ 870-673-7236									Date December 3, 2007												
ý	, The j	<u>, </u>	back	hav																										
Signature of Reviewer Agency/Office/Phone and Fax Numbers Date																														

EPA Form 3560-3 (Rev. 9-94) Previous editions are obsolete.

POTW Pretreatment Program

Industrial Site Visit

Name of Industry: Aramark									
Industry Contacts: Mark Peden, General Manager									
Type of Industry: <u>Industrial laundry servic</u>	е.								
Date of Visit: December 3, 2007									
1. Significant industrial user:	<u>X</u> Yes	No	Not Determined						
2. Pretreatment equipment or procedures?	<u>X</u> Yes	No	N/A						
3. Pretreatment equipment maintained and operational?	<u>X</u> Yes	No	N/A						
4. Hazardous waste generated or stored?	Yes	<u>X</u> No	N/A						
5. Proper solid waste disposal?	<u>X</u> Yes	No	N/A						
6. Solvent management/TTO control?	<u>X</u> Yes	No	N/A						
7. Suitable sampling location?	<u>X</u> Yes	No	N/A						
8. Appropriate self-monitoring procedures / equipment?	<u>X</u> Yes	No	N/A						
9. Adequate spill prevention?	<u>X</u> Yes	No	N/A						
10. Industry familiar with limits and requirements?	<u>X</u> Yes	No	N/A						
Additional Comments: None									
Visit Conducted By: <u>Steven L. Henderson</u>	Date:Dec	cember 3, 2007							