



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
Washington, D.C. 20460

## NPDES Compliance Inspection Report

Form Approved  
OMB No. 2040-0003

### Section A: National Data System Coding

Transaction Code	NPDES	Yr/Mo/Day	Inspec. Type	Inspector	Fac. Type				
1 <input type="text" value="N"/> 2 <input type="text" value="5"/> 3 <input type="text" value="A"/> <input type="text" value="R"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="2"/> <input type="text" value="1"/> <input type="text" value="9"/> <input type="text" value="7"/> <input type="text" value="1"/> 11 <input type="text" value="0"/> 12 <input type="text" value="7"/> <input type="text" value="1"/> <input type="text" value="2"/> <input type="text" value="2"/> <input type="text" value="1"/> 17 <input type="text" value="R"/> 19 <input type="text" value="S"/> 20 <input type="text" value="1"/>	Remarks								
Inspection Work Days		Facility Evaluation Rating		BI		QA		-----Reserved-----	
67 <input type="text"/> <input type="text"/> <input type="text"/> 69		70 <input type="text" value="N"/>		71 <input type="text" value="N"/>		72 <input type="text" value="N"/>		73 <input type="text"/> <input type="text"/> <input type="text"/> 74 75 <input type="text"/> <input type="text"/> <input type="text"/> 80	

### Section B: Facility Data

Name and Location of Facility Inspected ( <i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i> ) <b>City of Marion WWTP</b> <b>West of Highway 118</b> <b>S. of UP Railroad</b> <b>Marion, AR</b>	Entry Time/Date <b>1240 12/21/2007</b>	Permit Effective Date <b>March 1, 2007</b>
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) <b>None</b>	Exit Time/Date <b>1250 12/21/2007</b>	
Name, Address of Responsible Official/Title/Phone and Fax Number <b>Frank Fogleman/Mayor/870-739-3073</b> <b>City of Marion</b> <b>P.O. Box 717</b> <b>Marion, AR 72364</b>	Permit Expiration Date <b>February 29, 2012</b>	
Other Facility Data		Contacted Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>

### Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

U	Permit	N	Flow Measurement	U	Operations & Maintenance	N	Sampling
N	Records/Reports	N	Self-Monitoring Program	N	Sludge Handling/Disposal	U	Pollution Prevention
N	Facility Site Review	N	Compliance Schedules	N	Pretreatment	N	Multimedia
U	Effluent/Receiving Waters	N	Laboratory	N	Storm Water	U	Other: SSO

### Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

This reconnaissance inspection was conducted to determine if the unpermitted discharge noted during a CEI inspection on December 19, 2007, had been corrected.

At the time of this inspection the facility was still discharging from the old outfall structure of lagoon #1 into the abandoned chlorine contact chamber thence through the abandoned outfall into the receiving stream.

The NPDES Enforcement Section of this department was notified immediately via telephone of the observations.

No letter will be sent.

Name(s) and Signature(s) of Inspector(s)	Agency/Office/Telephone/Fax	Date
Brent L. Walker	AR Dept. of Environmental Quality-Jonesboro (870) 935-7221 ext. 12/(870) 935-4715 (Fax)	March 24, 2008
Signature of Reviewer	Agency/Office/Phone and Fax Numbers	Date

**Water Division NPDES Photographic Evidence Sheet**

<b>Location:</b>	City of Marion WWTP		
------------------	---------------------	--	--

<b>Photographer:</b>	Brent Walker	<b>Witness:</b>	None
----------------------	--------------	-----------------	------

<b>Photo #</b>	1	<b>Of</b>	4	<b>Date:</b>	12/21/2007	<b>Time:</b>	1242
----------------	---	-----------	---	--------------	------------	--------------	------

<b>Description:</b>	Discharge from Lagoon #1 into the old outfall structure.		
---------------------	--	--	--



<b>Photographer:</b>	Brent Walker	<b>Witness:</b>	None
----------------------	--------------	-----------------	------

<b>Photo #</b>	2	<b>Of</b>	4	<b>Date:</b>	12/21/2007	<b>Time:</b>	1243
----------------	---	-----------	---	--------------	------------	--------------	------

<b>Description:</b>	Discharge into the abandoned chlorine contact chamber.		
---------------------	--	--	--



**Water Division NPDES Photographic Evidence Sheet**

**Location:** City of Marion WWTP

**Photographer:** Brent Walker      **Witness:** None

**Photo #** 3    **Of** 4      **Date:** 12/21/2007    **Time:** 1245

**Description:** Unpermitted discharge from the abandoned outfall.



**Photographer:** Brent Walker      **Witness:** None

**Photo #** 4    **Of** 4      **Date:** 12/21/2007    **Time:** 1245

**Description:** Solids on bank of receiving stream.

