



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Washington, D.C. 20460

Form Approved
OMB No. 2040-0003
Approval Expires 7-31-85

NPDES Compliance Inspection Report

Section A: National Data System Coding

Transaction Code			NPDES										Yr/Mo/Day					Inspec. Type		Inspector		Fac. Type						
1	N	2	5	3	A	R	0	0	2	1	6	6	1	11	12	0	8	0	5	1	4	17	18	V	19	S	20	1
Remarks																												
A F I N 4 3 - 0 0 0 5 9 L O N O K E C O U N T Y																												
Inspection Work Days						Facility Evaluation Rating						BI		QA		Reserved												
67						70						71		72		73 74 75 80												

Section B: Facility Data

Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number) Cabot Water & Wastewater Commission – Pump station just east of North 2nd street – from North Little Rock, go north on Highway 67/167 toward Cabot. Take the Highway 89 exit and go east toward downtown. Turn left at 2nd street and go north approximately 4 blocks. Pump station is at back of vacant lot across from W. Cherry Street.		Entry Time/Date 11:15 AM/ 05/14/08		Permit Effective Date 11/01/07	
		Exit Time/Date 12:03 PM/ 05/14/08		Permit Expiration Date 10/31/12	
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) none				Other Facility Data	
Name, Address of Responsible Official/Title/Phone and Fax Number Tim Joyner P.E. – General Manager / 501-605-1740 208 North 1st St. Cabot, AR 72023				Contacted Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	

Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

N	Permit	N	Flow Measurement	N	Operations & Maintenance	N	Sampling
N	Records/Reports	N	Self-Monitoring Program	N	Sludge Handling/Disposal	N	Pollution Prevention
N	Facility Site Review	N	Compliance Schedules	N	Pretreatment	N	Multimedia
U	Effluent/Receiving Waters	N	Laboratory	N	Storm Water	U	Other: SSO

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

Investigated SSO referral from emergency response group. Spot where gravity line to pumping station and force main from pumping station cross small storm drain had failed due to storm flows. When I arrived, the Cabot work crews had already repaired the gravity line and were working on replacing force main. Pump station wet well was holding wastewater, so discharge to stream had stopped. Walked portion of creek. No visible solids, although water was gray and smelled of sewage. Drove to where stream crossed North Polk Street, water still smelled of sewage but was not septic and no visible solids were noted. Followed stream to railroad tracks. No dead fish, no paper, water gray.

Name(s) and Signature(s) of Inspector(s) Dennis Benson		Agency/Office/Telephone/Fax ADEQ/ North Little Rock/ 501-683-0827/ 501 682-0910 (Fax)		Date 05/14/08	
Signature of Reviewer		Agency/Office/Phone and Fax Numbers		Date	

Location:	Cabot Water and Sewer						
Photographer:	Dennis Benson			Witness:	None		
Photo #	1	Of	2	Date:	05/14/08	Time:	11:17 am
Description:	Repaired gravity line which goes to pump station to the left						



Photographer:	Dennis Benson			Witness:	None		
Photo #	2	Of	2	Date:	05/14/08	Time:	11:17 am
Description:	Force main from pumping station being repaired						

