



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
Washington, D.C. 20460

# NPDES Compliance Inspection Report

Form Approved  
OMB No. 2040-0003

## Section A: National Data System Coding

Transaction Code			NPDES										Yr/Mo/Day					Inspec. Type		Inspector		Fac. Type							
1	N	2	5	3	A	R	0	0	3	4	3	8	0	11	12	0	8	0	5	1	2	17	18	R	19	S	20	1	
Remarks																													
Inspection Work Days						Facility Evaluation Rating						BI		QA		Reserved													
67	0	0	1	69	70	3	71	N	72	N	73		74	75															80

## Section B: Facility Data

Name and Location of Facility Inspected ( <i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i> ) <b>City of Stuttgart WWTP</b> <b>10<sup>th</sup> Street Extension West</b> <b>Section 29, Township 3 South, Range 2 West</b> <b>Arkansas County, Arkansas</b>		Entry Time/Date <b>11:30 a.m. 5/12/08</b>	Permit Effective Date <b>February 1, 2004</b>
		Exit Time/Date <b>12:30 p.m. 5/12/08</b>	Permit Expiration Date <b>January 31, 2009</b>
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) <b>Danny Wilson, Head Wastewater Operator (870) 673-1043 or (870) 674-4819</b>		Other Facility Data	
Name, Address of Responsible Official/Title/Phone and Fax Number <b>Tommy Lawson, Manager (870) 673-3246</b> <b>City of Stuttgart Water Utilities</b> <b>P.O. Box 130</b> <b>Stuttgart, Arkansas 72160</b>		Contacted Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	


## Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

N	Permit	N	Flow Measurement	N	Operations & Maintenance	N	Sampling
N	Records/Reports	N	Self-Monitoring Program	N	Sludge Handling/Disposal	N	Pollution Prevention
S	Facility Site Review	N	Compliance Schedules	N	Pretreatment	N	Multimedia
S	Effluent/Receiving Waters	N	Laboratory	N	Storm Water		Other:

## Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

***As requested, a reconnaissance inspection was conducted to determine if the May 10, 2008 Tornado caused any power outage or structural damage to the City's Wastewater Treatment Plant. The inspection revealed no power outage or structural damage to the facility. The facility appeared to be operating normally. However, the city did have two pump stations with minor damage and loss of power. The city had generating units assisting the pump stations by Monday morning, May 12, 2008.***

Name(s) and Signature(s) of Inspector(s)  Steven L. Henderson	Agency/Office/Telephone/Fax ADEQ/ Stuttgart/ (870) 673-8846/ (870) 673-7236	Date May 19, 2008
Signature of Reviewer	Agency/Office/Phone and Fax Numbers	Date

ADEQ Water NPDES Inspection	AFIN:	Permit #:
-----------------------------	-------	-----------