ADEQ Water NPDES Inspection	AFIN: 18-0010	Permit #: AR0021971

⊕	E P A																		(oprove 2040-0		
	UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Washington, D.C. 20460																							
	NPDES Compliance Inspection Report																							
	Section A: National Data System Coding																							
														pec. T	pec. Type Inspector Fac. Type									
1	N 2 5 3 A R 0 0 2 1 9 7 1 11 12 0 8 0 1 0 3 17 18												V	V 19 S 20 1										
I				Ī	Ī		İ	ĺ	Remar	ks						Ī				I	ĺ			
L	Inspection Work Days Facility Evaluation Rating BI QA													Reserv	Reserved									
	67 69		7	0 N]			71	N	72	N	73			74	75		80						
	Section B: Facility Data													_										
Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number) City of Marion WWTP Entry Time/Date 1235 1/3/2008												Permit Effective Date March 1, 2007												
West of Highway 118 S. of UP Railroad Marion, AR Exit Time/Date 1245 1/3/2008												Permit Expiration Date February 29, 2012												
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) None Other											Oth	Other Facility Data												
Name, Address of Responsible Official/Title/Phone and Fax Number Frank Fogleman/Mayor/870-739-3073 City of Marion P.O. Box 717 Marion, AR 72364 Contacted Yes No																								
			(5	S = Satis					E <mark>valuat</mark> l, U = U					Evalı	uated)									
U	Permit	N	Flov	v Measu	reme	nt			U	Ope	eratio	ns &	Main	tenan	ce		N	Sampling						
N	Records/Reports	N	Self-	Monito	ring F	Progra	am		N	Slu	Sludge Handling/Disposal U						U	Pollution Prevention						
N	Facility Site Review	N	Con	pliance	Sche	dules			N	Pretreatment N						N	Multimedia							
U	Effluent/Receiving Waters	N		oratory					N		orm Water U						Other: SSO							
Section D: Summary of Findings/Comments (Attach additional sheets if necessary) This inspection was conducted to verify that the unpermitted discharge observed on 12/19/2007 had been stopped. At the time of the inspection there was still an unpermitted discharge from the old outfall structure into the receiving stream. No letter will be sent.																								
Nar	ne(s) and Signature(s) of Inspector(s	s)							e/Telep			.al:4-	To	-ba				Date	e					
Brei	nt L. Walker Breet & Wal	n					•		Enviroi 1 ext. 1		-							Jun	e 30,	2008				
Signature of Reviewer Agency/Office/Phone and Fax										Fax Numbers Date														

	Water Division NPDES Photographic Evidence Sheet											
Location:	Location: City of Marion WWTP											
Photographer: Brent Walker					Witness:	None						
Photo #	1	Of	4		Date:	1/3/2008	Time:	1237				


Description: Discharge from cell 1 into old outlet structure.



Photographer: Brent Walker						Witness:	None	None				
Photo #	2	Of	4				Date:	1/3/2008	Time:	1238		

Description: Discharge from cell one into abandoned chlorine contact chamber.







Photograph	ner:	Brent V	Walker	Witness:	None		
Photo #	4	Of	4	Date:	1/3/2008	Time:	1242

Description: Paper, plastics and other solids on bank of receiving stream.

