



Form Approved  
OMB No. 2040-0003

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
Washington, D.C. 20460

## NPDES Compliance Inspection Report

### Section A: National Data System Coding

Transaction Code			NPDES										Yr/Mo/Day					Inspec. Type		Inspector		Fac. Type							
1	N	2	5	3	A	R	0	0	2	1	9	7	1	11	12	0	8	1	0	2	1	17	18	R	19	S	20	1	
Remarks																													
Inspection Work Days						Facility Evaluation Rating						BI		QA		-----Reserved-----													
67						70	N	71	N	72	N	73			74	75													80

### Section B: Facility Data

Name and Location of Facility Inspected ( <i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i> ) <b>City of Sunset</b> <b>Satellite of Marion AR0021971</b>  <b>Crittenden Co.</b>	Entry Time/Date <b>1110 10/21/2008</b>	Permit Effective Date <b>3/1/2007</b>
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) <b>None</b>	Other Facility Data	
Name, Address of Responsible Official/Title/Phone and Fax Number <b>Kirby Massey/Mayor/870-739-3233 Cell-870-225-3452</b> <b>City of Sunset</b> <b>300 John H. Johnson Blvd.</b> <b>Sunset, AR 72364</b>	Contacted Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	

### Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

<b>U</b>	<b>Permit</b>	<b>N</b>	<b>Flow Measurement</b>	<b>U</b>	<b>Operations &amp; Maintenance</b>	<b>N</b>	<b>Sampling</b>
<b>U</b>	<b>Records/Reports</b>	<b>N</b>	<b>Self-Monitoring Program</b>	<b>N</b>	<b>Sludge Handling/Disposal</b>	<b>U</b>	<b>Pollution Prevention</b>
<b>U</b>	<b>Facility Site Review</b>	<b>N</b>	<b>Compliance Schedules</b>	<b>N</b>	<b>Pretreatment</b>	<b>N</b>	<b>Multimedia</b>
<b>U</b>	<b>Effluent/Receiving Waters</b>	<b>N</b>	<b>Laboratory</b>	<b>N</b>	<b>Storm Water</b>	<b>U</b>	<b>Other: SSO</b>

### Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

This recon inspection was conducted in response to an additional complaint alleging repeated overflows of the sewer system. The City of Sunset operates and maintains two pump stations. The City of Sunset pumps their sewage to the City of Marion (AR0021971) for treatment.

An recon inspection of the collection system behind the Harvard One Apartments was performed. At the time of the inspection, the manhole was no longer overflowing and the level in the collection system had dropped. There was evidence of a recent overflow - within the last few hours as there was still a small amount of liquid sewage on the ground in the vicinity of the manhole.

The matter has been referred to the enforcement branch of this department for their review and consideration in the ongoing enforcement action against the City of Sunset.

Name(s) and Signature(s) of Inspector(s) <b>Brent L. Walker</b> <i>Brent L. Walker</i>	Agency/Office/Telephone/Fax <b>AR Dept. of Environmental Quality-Jonesboro</b> <b>(870) 935-7221 ext. 12/(870) 935-4715 (Fax)</b>	Date <b>November 17, 2008</b>
Signature of Reviewer	Agency/Office/Phone and Fax Numbers	Date

**Water Division NPDES Photographic Evidence Sheet**

<b>Location:</b>	City of Sunset		
------------------	----------------	--	--

<b>Photographer:</b>	Brent Walker	<b>Witness:</b>	None
----------------------	--------------	-----------------	------

<b>Photo #</b>	1	<b>Of</b>	4	<b>Date:</b>	10/21/2008	<b>Time:</b>	1115
----------------	---	-----------	---	--------------	------------	--------------	------

<b>Description:</b>	Evidence of recent overflow and discharge to ditch.
---------------------	---



<b>Photographer:</b>	Brent Walker	<b>Witness:</b>	None
----------------------	--------------	-----------------	------

<b>Photo #</b>	2	<b>Of</b>	4	<b>Date:</b>	10/21/2008	<b>Time:</b>	1115
----------------	---	-----------	---	--------------	------------	--------------	------

<b>Description:</b>	Evidence of recent overflow and discharge to ditch.
---------------------	---



**Water Division NPDES Photographic Evidence Sheet**

<b>Location:</b>	City of Sunset						
<b>Photographer:</b>	Brent Walker			<b>Witness:</b>	None		
<b>Photo #</b>	3	<b>Of</b>	4	<b>Date:</b>	10/21/2008	<b>Time:</b>	1115
<b>Description:</b>	Evidence of recent overflow.						



<b>Photographer:</b>	Brent Walker			<b>Witness:</b>	None		
<b>Photo #</b>	4	<b>Of</b>	4	<b>Date:</b>	10/21/2008	<b>Time:</b>	1115
<b>Description:</b>	Area of recent overflow.						

