

# ADEQ

ARKANSAS  
Department of Environmental Quality

May 11, 2009

Craig Noble, General Manager  
Russellville City Corporation  
P.O. Box 3186  
Russellville, AR 72811

RE: Manhole overflow, Intersection of W. Cedar and Commerce St.

AFIN: 58-00105      NPDES Permit No.: AR0021768

Dear Mr. Noble:

On May 7, 2009, I performed a sanitary sewer overflow inspection of the collection system at a manhole located at the intersection of North Cedar St. and Commerce St. in response to a complaint. This inspection revealed the area has been treated with lime and the overflow has been orally reported to the Department. You are not in violation of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder.

Please be reminded that the overflow will need to be recorded on your monthly sanitary sewer overflow report and submitted with your May 2009 Discharge Monitoring Report.

If I can be of any assistance, please contact me at 479-968-7339.

Sincerely,



Amy Beck  
District 5 Field Inspector  
Water Division

cc:      Water Division Enforcement Branch  
          Water Division Permits Branch



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
Washington, D.C. 20460

## NPDES Compliance Inspection Report

Form Approved  
OMB No. 2040-0003

### Section A: National Data System Coding

Transaction Code			NPDES										Yr/Mo/Day					Inspec. Type		Inspector		Fac. Type							
1	N	2	5	3	A	R	0	0	2	1	7	6	8	11	12	0	9	0	5	0	7	17	18	R	19	S	20	1	
Remarks																													
Inspection Work Days						Facility Evaluation Rating						BI		QA		Reserved													
67	0	0	1	69	70	N	71	N	72	N	73		74	75															80

### Section B: Facility Data

Name and Location of Facility Inspected ( <i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i> ) <b>RUSSELLVILLE WWTP (CITY CORPORATION)</b> 404 Jimmy Lile Road Russellville, AR 72802		Entry Time/Date 1600 / 5-07-2009		Permit Effective Date 4/1/2005			
		Exit Time/Date 1615 / 5-07-2009		Permit Expiration Date 3/31/2010			
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) NA				Other Facility Data Complaint and photos attached			
Name, Address of Responsible Official/Title/Phone and Fax Number Craig No ble, (479) 968-2080 ext. 113 RUSSELLVILLE CITY CORPORATION P.O. Box 3186 Russellville, AR 72811							
Contacted Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>							

### Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

N	Permit	N	Flow Measurement	N	Operations & Maintenance	N	Sampling
N	Records/Reports	N	Self-Monitoring Program	N	Sludge Handling/Disposal	N	Pollution Prevention
N	Facility Site Review	N	Compliance Schedules	N	Pretreatment	N	Multimedia
S	Effluent/Receiving Waters	N	Laboratory	N	Storm Water	N	Other:

### Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

**This inspection was conducted in response to a complaint of a manhole overflow at the intersection of W. Cedar and Commerce St. in Russellville. Complaint was reported to ADEQ on May 7, 2009. I inspected the site on the same afternoon and observed evidence of the overflow around the manhole and on the south side of Commerce St. The overflow had stopped.**

**I contacted the wastewater operations manager, Larry Collins on 5-8-2009 and he stated that the city was aware of the problem. He stated that the contaminated area had been treated with granulated lime and the overflow had been reported to the Department. Excess water was the result of heavy rainfall that had occurred throughout the previous week.**

Name(s) and Signature(s) of Inspector(s) <b>Amy Beck</b>		Agency/Office/Telephone/Fax <b>Arkansas Department of Environmental Quality / Russellville / 479-968-7339 / 479-968-7321</b>		Date <b>May 11, 2009</b>	
Signature of Reviewer		Agency/Office/Phone and Fax Numbers		Date	

**Water Division NPDES Photographic Evidence Sheet**

**Location:** Manhole overflow at intersection of W. Cedar and Commerce St. in Russellville, AR

**Photographer:** Amy Beck      **Witness:** None

**Photo #** 1    **Of** 2      **Date:** 5-07-2009    **Time:** 1612

**Description:** Area around manhole had been limed. Stream is in the background.



**Photographer:** Amy Beck      **Witness:** None

**Photo #** 2    **Of** 2      **Date:** 5-07-2009    **Time:** 1614

**Description:** Overflow runoff to south side of Commerce St.

